

Underground Contamination Investigations, Groundwater Consultants, Environmental Engineering

REPORT OF GROUNDWATER SAMPLING

(sampled December 2, 1992)

ADOBE PLAZA 3098 Castro Valley Blvd Castro Valley, CA

December 4, 1992

TABLE OF CONTENTS

I.	INTRODUCTION	1
II.	FIELD WORK	4
	Monitoring Well Sampling	4
	Wastewater Generation	5
ıı.	RESULTS OF WATER LEVEL MEASUREMENTS	6
	Shallow Groundwater Flow Direction	6
	Shallow Water Table Hydraulic Gradient	6
	Historical Water Level Measurements	6
IV.	SHALLOW GROUNDWATER SAMPLING RESULTS	10
	Laboratory Analysis	10
	Results of Laboratory Analysis	10

ATTACHMENT A -- Well Sampling Logs

ATTACHMENT B -- Analytical Results: Groundwater

I. INTRODUCTION

The site location is 3098 Castro Valley Blvd, Castro Valley, California, and has been maintained by the current owners for a number of years as a car wash and gasoline station. The location of the site is shown in Figure 1.

On July 26, 1988, two underground gasoline storage tanks were removed by Hageman-Schank, Inc. A map of the site is shown in Figure 2. This map shows the present layout of the facility (Adobe Plaza Shopping Center, constructed in 1989), along with the location of the previous underground tank excavation and removal. Analysis of a pit water sample collected at the time of the tank removals indicated the presence of Gasoline and Benzene at concentrations of 2.0 mg/L (ppm) and 32 μ g/L (ppb), respectively.

The three on-site shallow groundwater monitoring wells MW-1, MW-2 and MW-3 were subsequently installed on August 11, 1989, by Hageman-Schank, Inc.

On December 2, 1992, on-site monitoring well MW-2 was sampled for the laboratory analysis for dissolved petroleum constituents. In addition to the monitoring well sampling, other tasks included water level measurements for each monitoring well. This round of groundwater sampling has been conducted as part of the continued groundwater monitoring program at the site, as required by the Alameda County Department of Environmental Health and the California Regional Water Quality Control Board (RWQCB), San Francisco Bay Region.





FIGURE 1. Site Location Map.



Site Map.

II. FIELD WORK

Monitoring Well Sampling

On December 2, 1992, groundwater samples were collected from on-site monitoring well MW-2. The locations of the three onsite monitoring wells are shown in Figure 2 (site map). Prior to groundwater sampling, the well was purged by bailing approximately 10 casing volumes of water. Field conductivity, temperature, and pH meters were present on-site during the monitoring well sampling. As the purging process proceeded, the three parameters were monitored. continued until readings appeared to have reasonably stabilized. After the water level in the well had attained 80% or more of the original static water level, a groundwater sample was collected using a clean teflon bailer. sample was placed inside appropriate 40 mL VOA vials free of any headspace. The samples were immediately placed on ice, then transported under chain-of-custody to the laboratory at the end of the work day.

At the time the monitoring well was sampled, the following information was recorded in the field: 1) depth-to-water prior to purging, using an electrical well sounding tape, 2) identification of any floating product, sheen, or odor prior to purging, using a clear teflon bailer, 3) sample pH, 4) sample temperature, and 5) specific conductance of the sample.

Copies of the well sampling logs are included as Attachment A.

Wastewater Generation

All water removed from the wells during development and purging was drummed and stored on-site until the results of laboratory analyses were obtained. Based upon these results, the water is considered to contain no detectable concentrations of any petroleum hydrocarbons. It appears that this water could be used for on-site irrigation, or else it should be disposed of at one of the on-site sanitary sewer connections (in accordance with local sewering agency permit requirements). The disposal of wastewater is the responsibility of the property owner (waste generator), and is beyond the scope of work as described in this report.

III. RESULTS OF WATER LEVEL MEASUREMENTS

Shallow Groundwater Flow Direction.

Shallow water table elevations were measured on December 2, 1992. These measurements are shown in Table 1. Figure 3 presents a contour map for the shallow groundwater table beneath the site. As shown in this figure, the data from these monitoring wells indicate that the shallow groundwater flow beneath the site at the time of the groundwater sampling was in the southeasterly direction.

Shallow Water Table Hydraulic Gradient

Figure 3 presents the contour map for the shallow groundwater table beneath the site. As shown in this figure, the shallow groundwater table appears to have a calculated hydraulic gradient of dH/dL = 2!/155! = 0.013.

<u>Historical Water Level Measurements</u>

In addition to the most recent measurement of the shallow water table elevations prior to the groundwater sampling on December 2, 1992, a tabulation of all historical water level measurements for the site has been completed. Table 2 presents the results of all water level measurements collected between August 23, 1989, and the present time.

TABLE 1.

Shallow Water Table Elevations
December 2, 1992

Well	Top of Casing Elevation (feet)	Depth to Water (feet)	Water Table Elevation (feet)
MW-1	99.73	8.76	90.97
MW-2	100.00	6.99	93.01
MW-3	99.76	7.24	92.52




TABLE 2.
Historical Water Table Elevations (feet)

	Date of Measurement												
Well	8-23-89	6-8-90	8-29-90	11-28-90	3-8-91	10-10-91	3-9-92	9-8-92	12-2-92				
MW-1	90.27	91.23	90.33	90.24	90.17	88.57	91.13	89.69	90.97				
√0° MW-2 MW-3	92.45 92.38	93.07 93.35	92.78 92.17	92.79 92.17	93.12 93.98	92.80 92.16	93.04 94.26	92.87 92.10	93.01 92.52				
Carpo													
Flow Direction	SE	SE	SE	SE	SE	SE	SE	SE	SE				

IV. SHALLOW GROUNDWATER SAMPLING RESULTS

Laboratory Analysis

All analyses were conducted by a California State DOHS certified laboratory in accordance with EPA recommended procedures (Priority Environmental Laboratory, Milpitas, CA). All Groundwater samples were analyzed for Total Petroleum Hydrocarbons as Gasoline (EPA method 8015), and Benzene, Toluene, Ethylbenzene, and Total Xylenes (EPA method 602).

Results of Laboratory Analysis.

Table 3 presents the results of the laboratory analysis for TPH and BTEX of the groundwater samples collected from monitoring well MW-2. In addition, the previous analytical results for all three on-site monitoring wells are also shown.

For this round of groundwater sampling, <u>no detectable</u> <u>concentrations</u> of either Gasoline, Benzene, Toluene, Ethylbenzene, or Total Xylenes were detected in the shallow groundwater samples collected from well MW-2.

A copy of the laboratory certificate for the water sample analysis is included as Attachment B.

TABLE 3.
Shallow Groundwater Sampling Results

Well	Date	TPH as Gasoline (ug/L)	Benzene (ug/L)	Toluene (ug/L)	Ethyl- benzene (ug/L)	Xylenes (ug/L)
1	08-22-89	ND	0.5	1.2	ND	3.1
	05-24-90	ND	ND	ND	ND	ND
	08-29-90	ND	ND	ND	ND	ND
	11 <i>-</i> 28-90	ND	ND	ND	ND	ND
	03-08-91	ND	ND	ND	ND	ND
	10-10-91	DN	ND	ND	ND	ND
	03-09-92	ND	ND	ND	ND	ND
	09-08-92	ND	ND	ND	ND	ND
2	08-22-89	110	5.3	ND	ND	ND
 	09-06-89	ND	ND	ND	ND	ND ND
	05-24-90	ND	ND	ND	ND	ND ND
1	08-29-90	110	ND	0.8	1.1	0.6
	11-28-90	ND	ND	ND	ND	ND
	03-08-91	ND	ND	ND	ND	ND
	10-10-91	160	13	3.2	2.0	18
	03-09-92	ND	ND	ND	ND	ND
	09-08-92	ND	ND	ND	ND	ND
	12-02-92	ND	ND	ND	ND	ND
3	3 08-22-89		ND	ND	ND	ND
	06-08-90	ND ND	ND	ND ND	ND	ND ND
	08-29-90	ND	ND	ND	ND	ND
	11-28-90	ND	ND 1	ND	ND	ND
	03-08-91	ND	ND	ND	ND	ND ND
	10-10-91	ND	ND	ND	ND	ND ND
	03-18-92	ND	ND	ND	ND	ND
	09-08-92		ND	ND	ND	ND
Detection	on Limit	50	0.5	0.5	0.5	0.5

REPORT OF GROUNDWATER SAMPLING ADOBE PLAZA 3098 Castro Valley Blvd, Castro Valley, CA

December 2, 1992

No. C-34262

No. C-34262

No. C-34262

EXP, 9-30-95

Gary Aguiar

RCE 34262

Bruce Hageman

ATTACHMENT A

WELL SAMPLING LOGS

WELL SAMPLING LOG

Project/No. ADOBE PLAZA Page of
Site Location CASTRO VALLEY Date 12-2-92
Well No. MW 2
Weather CLOUDY 550F Completed 1305
EVACUATION DATA
Description of Measuring Point (MP) WELL BOX AT GRADE
Total Sounded Depth of Well Below MP 19.20
- Depth to Water Below MP 6.99 of Casing 2"
= Water Column in Well 12.21
Gallons in Casing $\frac{2.0}{0.00}$ + Annular Space $\frac{2.0}{0.00}$ = Total Gallons $\frac{2.0}{0.00}$
Gallons Pumped Prior to Sampling 20
Evacuation Method TEFLON BAILER
SAMPLING DATA / FIELD PARAMETERS
Inspection for Free Product: None Detected (thickness to 0.1 inch, if any)
Time 1230 1241 1248 1255
Gals Removed 0 10 15 20
Temperature 20.0 19.5 18.9 19.1
conductivity <u>750</u> <u>700</u> <u>650</u> <u>650</u>
by 8,0 7,9 7.8 7.7
Color / Odor GRY/SEP BUK SEP BUK SEP
Turbidity MED HIGH HIGH HIGH
Comments:

ADOBE FLAZA 12-2-92

MN 1 8,76 MN 2 6,99 MN 3 7.24 DB

19.20

ATTACHMENT B

ANALYTICAL RESULTS: GROUNDWATER



PRIORITY ENVIRONMENTAL LABS

Precision Environmental Analytical Laboratory

December 04, 1992

PEL # 9212009

HAGEMAN - AGUIAR, INC.

Attn: Jeffrey Roth

Re: One water sample for Gasoline/BTEX analysis.

Project name: Adobe Plaza

Project location: Castro Valley Blvd., -Castro Valley, CA.

Date sampled: Dec 02, 1992 Date extracted: Dec 03, 1992

Date submitted: Dec 03, 1992 Date analyzed: Dec 03, 1992

RESULTS:

SAMPLE I.D.	Gasoline	Benzen	e Toluene	Ethyl	Total
	(ug/L)	(ug/L)	(ug/L)	Benzene (ug/L)	(ug/L)
MW 2	N.D.	N.D.	N.D.	N.D.	N.D.
Blank	N.D.	N.D.	N.D.	N.D.	N.D.
Spiked Recovery	90.4%	87.8%	82.1%	89.0%	90.3%
Detection limit	50	0.5	0.5	0.5	0.5
Method of Analysis	5030 / · 8015	602	602	602	602

David Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035

Tel: 408-946-9636

Fax. ADR.QAR.QRET

PEL#

9212009

INV#

23247

CHAIN OF CUSTODY RECORD

PROJECT NAME AN	NO ADDRESS:	0-0			SAMPLER: (Signati		211						/	7	//	7	77
CASTA	eo Val	NEY Z	Ber Ce	S.	HAGEMAN - AGUIAR, INC. 3732 Mt. Dieblo Blvd., Suite 372 Lefeyette, CA 94549 (415)284-1661 (415)284-1664 (FAX)				ANALYSIS REQUESTED								
CROSS REFERENCE NUMBER	DATE	TIME	S 0 1 L	W A T E R	STATION LOCATION					ß,					RE	MAR	KS
Anw 2	12-2-92	1305	<u> </u>	X	MONIT	ORING	WELL		X	入					NORA	72	77
		<u> </u>		 		·											
								_								·	
			-	 			· · · · · · · · · · · · · · · · · · ·										
							<u> </u>	 									
						 -											
						-											
						· 											
																· · · · · · · · · · · · · · · · · · ·	
								_							·		···
RELINQUISHED BY: (Signature)					DATE /2-3-9. TIME /600	RECEIVED BY: (Si	gnature)	1	1					1	ATE .		
RELINQUISHED BY: (Signature)						DATE TIME	RECEIVED BY: (Signature) DATE TIME										
RELINQUISHED BY:	(Signeture)					DATE	AECEIVED BY: (Si	gnature)	,						1	ATE	
RELINQUISHED BY: (Signature)						TIME	RECEIVED FOR LA	BORATOR	/ BY: (S	igratura	<u>, </u>					IME ATE	403/m
						TIME								6:30			
					·		Ü									'	