

5

FILE OR] ENVELOPE
 PER NO.] No. of

OWNER Buerer, Inc.
 Address 1061 Eastshore Hwy
Albany 94710 Phone _____

Contractor Ken Willis
 Address 321-1st Ave South
Palo Alto 94353 Phone 228-10.00

OTHER (Specify)
 Address _____
 Phone _____

CONTACT FOR INVESTIGATION

PLAN REVIEW

\$ 450.00 Rec'd. 1/19/88 MAC

No. 4 Plans Rec'd. MAC 1-19-88

Plans Approved _____

Layout Made _____

Rejected _____

Applicant Notified _____

Plans Returned _____

Permit Issued _____

CONSTRUCTION PROGRESS ACCEPTANCE

FOOD Pre-Plaster/drywall _____

Pre-Final _____

Final _____

By Date

POOL Pre-Concrete/Gunite _____

Pre-Plaster _____

Final _____

EXCAVATION Septic Tank _____

Absorption Field _____

Absorption Bed _____

House Sewer _____

FINAL Septic Tank _____

Absorption Field _____

Absorption Bed _____

OTHER _____

By Date

Pre-Covering _____

Final _____

U.G. TANKS

LOP 1323

XR		REMARKS		LOCATION
Date	By	Date	By	
				Vicinity Map
2/10	pm	2/10	pm	
		2/16		
		2/18		
		7/7		

2/10 - call to Willis - Not time
 cannot put up tank
 on site unless final
 results < 100ppm TPH

2/16 Inspec scheduled at 11
 on 2/18

2/18 On site for tank removal -
 No haz waste hauler - can not
 remove tank unless
 cert. lab analysis on final rinse
 < 100 ppm. Ken Willis will contract
 with haz waste hauler to remove tank
 this afternoon. Told him to contact
 our office as to who hauler will be.

7/7 Left msg @ Buerer for W Johnson
 we need the final report (soils,
 manifest, etc.) before we can
 make billing adv.

(cont. on back)

Project # U505549
 Fee Paid \$450.00
 Date 1-19-88

REMARKS			REMARKS			REMARKS		
Date	By		Date	By		Date	By	
7/25/89	GW	Receive sampling results after requesting these materials from Clay Johnson - contaminant assessment will be required because of detectable ACs found in water			work is required at site. work plan due 12/21.			
			2/22/91	gmu	Additional deposit received. Review Aegis work plan, outline response. Prepare letter 2/26 requiring amended work plan. Phone call w/ Larry Brown Braybrooks of AEGIS, to clarify requirements for amended work plan.			
10/17	GW	Talk w/ Bruce Hagenan of Hagenan + Schenk; will be meeting today w/ Buehner to explain work plan requirements and will submit plan as soon as possible	3/6		Review amended work plan: OK.			
			3/25		Review three quarterly monitoring reports, submitted together (latest sampling 11/90). All four wells show similar contamination of TPA-G and diesel, all < 1 ppm. Very shallow gradient and GW flow direction seems to vary all over the map.			
11/28		Talk to Bruce Hagenan, leave message w/ Clay Johnson - work plan is adequate, and work should proceed.	5/16/91					
3/27/90		Review work plan from AEGIS Environmental - a revision of Hagenan - Schenk workplan. Let's work will proceed immediately, w/ report available in about 8 weeks.						
11/19		Review Aegis report + prepare letter indicating that additional						