

R01100

CL



**CERTIFIED
ENVIRONMENTAL
CONSULTING**

93 AUG -4 PM 1:05

August 2, 1993

REF: 93-301-1033

Mr. Barney Chan
Health Care Services
Alameda County
80 Swan Way, Room 200
Oakland, CA 94621
(510) 271-4530

**SUBJECT: TYPOGRAPHIC ERROR IN THE CEC REPORT ON 852 85TH AVENUE,
OAKLAND DATED JULY 23, 1993**

Dear Mr. Chan:

I noticed a typographic error in the report covering the well installation and initial groundwater sampling at 852 85th Avenue in Oakland and want to correct it. Table 2 of the report contains the results of the groundwater analysis and shows the values as ppm. These values are actually in ppb as indicated on the Laboratory Report sheets in Appendix C of the report. Enclosed is a corrected copy of the page containing Table 2.

I apologize for not catching the error before the report was sent. If you have any questions on this or any other aspect of this project, please call me at (707) 745-0171.

Sincerely,

James H. Robbins
James H. Robbins
Environmental Specialist

enclosure

cc: Mr. Ned Raudsep
Geo. M. Robinson & Co.
915 Commercial Street
San Jose, CA 95112
(408) 453-3473
(408) 437-1964 FAX

TABLE 1**SOIL ANALYSIS**

SAMPLE	TPH(G) (ppm)	BENZENE (ppm)	TOLUENE (ppm)	ETHYL BENZENE (ppm)	XYLENE (ppm)
MW1, 10'	ND	ND	ND	ND	ND
MW1, 20'	ND	ND	ND	ND	ND
MW2, 5'	1.0	0.071	ND	ND	ND
MW2, 20'	ND	ND	ND	ND	ND

TABLE 2**GROUNDWATER ANALYSIS**

SAMPLE	TPH(G) (ppb)	BENZENE (ppb)	TOLUENE (ppb)	ETHYL BENZENE (ppb)	XYLENE (ppb)	BARIUM (ppb)
MW-1	ND	ND	0.60	ND	ND	320
MW-2	150	ND	1.6	1.6	1.5	81
State Standard	None	1.0	None	680	1750	1000