



December 1, 1992

9201-2-1115

Ms. Juliet Shin  
Hazardous Materials Specialist  
Alameda County Health Care Services Agency  
Dept. of Environmental Health  
Hazardous Materials Division  
80 Swan Way, Room 200  
Oakland, CA 94621

**Subject: Revised - Workplan for Monitoring Well Installation  
Alameda Collision Repair, 1911 Park Street  
Alameda, California 94501  
(Project No. 929393)**

Aqua Terra Technologies  
Consulting Engineers  
& Scientists

Dear Ms. Shin:


In response to correspondence issued on November 20, 1992 by the Alameda County Health Care Services Agency the following is provided:

- o A revised monitoring well location is provided that places the monitoring well to the northeasterly direction.
- o This is to confirm that soil samples will be collected at five-foot intervals and at any change in lithology, and that at least one sample will be collected from the boring.

Please contact us if you have any questions or comments.

Sincerely,

**AQUA TERRA TECHNOLOGIES, INC.**

  
Terrance E. Carter  
Senior Environmental Engineer  
Project Manager


TEC:pd  
Attachments

cc: Mr. Jim Thompson, Alameda Collision Repair

929393/DK1/REV-WRK.PLN


1911 PARK ST.

1919 PARK ST.



Proposed Well Location

ASPHALT  
PARKING AREA



PARK STREET



SCALE 1"=10'



FORMER TANK LOCATION

**ATT**

Aqua Terra Technologies  
Consulting Engineers  
& Scientists

**ALAMEDA COLLISION REPAIR**

JOB NUMBER  
929393

DATE  
11/92

PLATE

3