

DAILY REPORT

Gettler - Ryan Inc.

TAGS

FORMS

COMPANY Tosco # 11/20 JOB NO. 140229.02

LOCATION 6400 Dublin Blvd, Dublin, CT DATE 5/14/99

ARRIVAL TIME 11:45

DEPARTURE TIME: 4:30

JOB INSTRUCTIONS: Arrive @ site @ 11:45 after drillers call

Set up on HP-1 near phone w/ Gregg drill

Do a 25' CPT run for free, then move ~1' &

WORK PERFORMED (CONT. ON REVERSE SIDE): put down HP-1 to 15' &

open 3' of screen to 12' by 5 by 1:15. Move auger

tracks to HP-2 & hand auger it down. HP-1 is 14' South

& 35' west of NW corner of building & 15' south of MW-7

scar. HP-2 is 10' North & 7' east of NW corner

of building. Move HP-2 ~2' west due to object @ 3.5'

No H₂O in HP-1 @ 2:00, so pull out & place temp

casing. Push to 25'. Move again on HP-2 to 14' north

MATERIALS: & 4' east of NW corner of building & hit asphalt - push thru

Collect HP-1 @ 3:15 @ ~6' by 5. Go to 25' on HP-2

& put down casing @ 3:20. Bentonite HP-1 & cap w/ cutback. HP-2

SUBCONTRACTORS: still dry @ 3:50. Collect HP-2 @ 4:15 -> H₂O

coming up fast. Cleanup & leave by 4:30.

EQUIPMENT:

AIR COMPRESSOR _____ CONCRETE SAWING _____ HELIUM TESTER _____

DUMP TRUCK _____ STEAM CLEANER _____ HYDROCARBON SURVEYOR _____

SPECIALTY TRUCK _____ WATER/TRANSFER PUMP _____ HORIBA _____

BACKHOE/LOADER _____ PETRO-TITE LINE TESTER _____ VR-3 _____

KOMATSU _____ PETRO-TITE TANK TESTER _____ OVA _____

PAVING EQUIPMENT _____ VAPOR TESTER _____ ELECTRONIC INTERFACE PROBE _____


FOREMAN Clyde Galantine



GETTLER-RYAN INC.

Site : Tasco St.11120
Location : CPT-01

Geologist : C. Galantine
Date : 05:14:99 12:41



Max. Depth: 25.10 (ft)

Depth Inc.: 0.164 (ft)

SBT: Soil Behavior Type (Robertson and Campanella 1988)

DRAFT