
ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director





ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

June 18, 2004

Mr. Doug Herman Port of Oakland 530 Water St. P.O. Box 2064 Oakland, CA 94604-2064

Dear Mr. Herman:

Subject:

Fuel Leak Site Case Closure, Port of Oakland, Embarcadero Cove, 1275 Embarcadero, Oakland.

CA 94606; Case No. RO0002445

This letter confirms the completion of a site investigation and remedial action for the former gasoline underground storage tank formerly located at the above-described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tank(s) are greatly appreciated.

Based on information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, this agency finds that the site investigation and corrective action carried out at your underground storage tank(s) site is in compliance with the requirements of subdivisions (a) and (b) of Section 25299.37 of the Health and Safety Code and with corrective action regulations adopted pursuant to Section 25299.77 of the Health and Safety Code and that no further action related to the petroleum release(s) at the site is required.

This notice is issued pursuant to subdivision (h) of Section 25299.37 of the Health and Safety Code.

Please contact our office if you have any questions regarding this matter.

Sincerely,

Mee Ling Tung

Director

Alameda County Environmental Health

Mee Ling Jung

ALAMEDA COUNTY HEALTH CARE SERVICES

AGENCY





ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION

1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

June 18, 2004

Mr. Doug Herman Port of Oakland 530 Water St. P.O. Box 2064 Oakland, CA 94604-2064

Dear Mr. Herman:

1211 Be

Subject:

Fuel Leak Site Case Closure, Port of Oakland, Embarcadero Cove, 1275 Embarcadero,

Oakland, CA 94606; Case No. RO0002445

This letter transmits the enclosed underground storage tank (UST) case closure letter in accordance with Chapter 6.75 (Article 4, Section 25299.37[h]). The State Water Resources Control Board adopted this letter on February 20, 1997. As of March 1, 1997, the Alameda County Environmental Hcalth (ACEH) is required to use this case closure letter for all UST leak sites. We are also transmitting to you the enclosed case closure summary. These documents confirm the completion of the investigation and cleanup of the reported release at the subject site. The subject fuel leak case is closed.

SITE INVESTIGATION AND CLEANUP SUMMARY

Please be advised that the following conditions exist at the site:

- 2300 ppm TPHg, 850 ppm TPHd, 300 ppm TPHmo, 1.8 ppm benzene, 3.7 ppm toluene, 48 ppm ethyl benzene, 7.2 ppm xylenes, 5.1 ppm MTBE, 2.2 ppm 2-methyl naphthalene and 2.2 ppm naphthalene remain in the soil at this site.
- 59 ppb TPHd, 0.58 ppb benzene and 0.32 ppb pyrene remain in groundwater at this site.

If you have any questions, please call Barney Chan at (510) 567-6765. Thank you.

Sincerely,

Donna L. Drogos, P.E.

LOP Program Manager

Enclosures:

- 1. Case Closure Letter
- 2. Case Closure Summary

cc: Ms. Betty Graham (w/enc)
Regional Water Quality Control Board
San Francisco Bay Region
1515 Clay Street, Suite 1400
Oakland, CA 94612

Mr. Toru Okamoto (w/enc)
State Water Resources Control Board
Underground Storage Tank Cleanup Fund
P.O. Box 944212
Sacramento, CA 94244-2120

Mr. Leroy Griffin, City of Oakland FD,(w/enc) 1605 MLK Jr. Way, Oakland, CA 94612

B. Chan (w/orig enc), D. Drogos (w/enc), R. Garcia-La Grille (w/enc)

CASE CLOSURE SUMMARY LEAKING UNDERGROUND FUEL STORAGE TANK - LOCAL OVERSIGHT PROGRAM

I. AGENCY INFORMATION

Agency Name: Alameda County Environmental Health	Address: 1131 Harbor Bay Parkway
City/State/Zip: Alameda, CA 94502-6577	Phone: (510) 567-6765
Responsible Staff Person: Barney Chan	Title: Hazardous Materials Specialist

Date: May 3, 2004

II. CASE INFORMATION

Site Facility Name: Port of Oakland, I			
RB Case No.: NA URF Filing Date:	Local Case No.: NA SWEEPS No.:		Sase No.: RO0002445
Responsible Parties	Addresses		Phone Numbers
Mr. Doug Herman Port of Oakland	530 Water St., P.O. Box 2064, Oakland 94604- 510-627-1184 2064		510-627-1184

Tank I.D. No	Size in Gallons	Contents	Closed In Place/Removed?	Date
1	Unknown	gasoline	Removed	Approx 1970
	Piping		Removed	Арргох 1970

III. RELEASE AND SITE CHARACTERIZATION INFORMATION

Site characterization complete? Yes	Date Approved By Oversight Agency:	
Monitoring wells installed? Yes	Number: 5	Proper screened interval? Yes, 4-15'
Highest GW Depth Below Ground Surface: 4.69'	Lowest Depth: 8.22'	Flow Direction: northeast

Summary of Production Wells in Vicinity:	
No water supply wells were identified within 1/4-	mile of the subject site.
Are drinking water wells affected? No	Aquifer Name: Oakland Sub Area, East Bay Plain
Is surface water affected? No	Nearest SW Name: Oakland-Alameda estuary 120' to the south
Off-Site Beneficial Use Impacts (Addresses/Loc	ations): None identified
Reports on file? Yes	Where are reports filed? Alameda County Environmental Health and City of Oakland Fire Services Agency, OES

	TREATMENT ANI	D DISPOSAL OF AFFECTED MATERIAL	
Material	Amount (Include Units)	Action (Treatment or Disposal w/Destination)	Date
Tank	Not reported	Not reported	~ 1970
Piping	Not reported	Not reported	~1970
Soil	60 CY	Disposed to Forward Landfill, Manteca	7/16/2002

MAXIMUM DOCUMENTED CONTAMINANT CONCENTRATIONS BEFORE AND AFTER CLEANUP (Please see Attachments for additional information on contaminant locations and concentrations)

	Soil ((ppm)	Water (ppb)	
Contaminant	Before ^l	After ²	Before ³	After ⁴
TPH (Gas)	2300	2300	80,000	<50
TPH (Diesel)	850	850	5800	59
ТРН (МО)	300	300	7200	<250
Benzene	1.8	1.8	8600	0.58
Tolucne	3.7	3.7	8200	<0.5
Ethyl Benzenc	48	48	3900	<0.5
Xylenes	7.2	7.2	14600	<0.5
Heavy Metals: Cd, Cr, Pb, Ni, Zn	NA, 56, 2.6, 64, 29	NA, 56, 2.6, 64, 29	NA	<5, <20, <5.3, <50, 50
MTBE (if not analyzed, explain below)	*5.1	*5.1	<5	<5
Other (8240/8270)	2.2 +	2.2 +	610#	0.32 pyrene

- 1 Results from sample M-1-5, * MTBE reported in M-1-5 run by EPA Method 8020
- NA= not analyzed
- 2 No soil samples collected after excavation of tank pit (& M-1-5 area) to a depth of 11'
- 3 Grab groundwater sample results from borings SB-1 and SB-A through SB-F.
- 4 Results from MW-4a (5/14/03)
- + volatile constituents of gasoline (naphthalene, n-butyl benzene, 1sopropyl benzene, n-propyl benzene, 1,2,4- tri-methyl benzene and 1,3,5-tri-methyl benzene) were detected at concentrations from 0.22-2.2 ppm.
 - # 2-methyl naphthalene and naphthalene detected in grab groundwater sample at 260 and 610 ppb, respectively

Site History and Description of Corrective Actions:

The site shown on Attachment 1 is located along the north side of the Oakland-Alameda estuary. Currently, the site was occupied with a vacant restaurant and its parking lot. This address is part of a larger parcel of which only this address is currently being considered for development. A multi-story commercial building is proposed within the footprint of the former restaurant.

Historical site use:

1965-1969 occupied by Acme Pallet Co.

1970- a cooling tower and an UST (presumed gasoline tank) removed from site

1973- Barclay Jack's restaurant and later operated as a Hungry Hunter restaurant

The original Gray and Reynold's project considered development of the area from 1275-1363 Embarcadero. Later, developer decided to develop only 1275 Embarcadero for commercial use.

In 1970, an underground storage tank, assumed gasoline, and an associated pump were removed from the site, however, no records exist to confirm this, nor the exact location of the former tank and pump. Therefore, an initial subsurface investigation was performed to confirm the absence of the underground tank and to investigate other areas based upon past site usage.

5/01- Four borings (SB-1, SB-1A, SB-2 and SB-3) were completed to groundwater and four shallow borings where refusal was encountered (SB-1B, SB-1C, SB-2C and SB-2D) were advanced. In addition, six shallow random borings (RN-A1, RN-A2, RN-A3, RN-A4, RN-B1 and RN-B2) were advanced to assess the site. See Attachment 2 and 3. Soil and groundwater were analyzed for VOCs, SVOCs, TPHg, TPHd, PCBs and hexavalent chrome (in sample near former cooling tower). The random samples ranged from 0.5-1.5' in depth were analyzed for BTEX and MTBE. All of these samples were < detection limits for these analytes. In the borings advanced to groundwater, only the soil sample SB-1A, 5-5.5, exhibited significant contamination with 500 ppm TPHg and 22ppm cumulative TEX. The groundwater samples from SB-1 and SB-1A exhibited elevated TPHg and BTEX concentrations up to 80,000 ppb TPHg and 8,600, 8,200, 3,900, 14,600 ppb BTEX, respectively. These results are consistent with the former gasoline tank being located near these two borings. Groundwater was encountered at depths ranging from 4-7' bgs. Typical soils encountered beneath the asphalt cap were gravel and sand to the depth of groundwater, then gravelly, sandy clay to the depth of boring (10' bgs).

8/30/01- Six additional soil borings (SB-A through SB-F) were advanced to groundwater with exception of SB-C, which encountered obstructions in the borehole. Soil samples were collected at 3.5' bgs and exhibited up to 2.5 ppm for TPHg, 0.021, 0.01, <0.005, 0.026 ppm BTEX, respectively, <0.05 ppm MTBE, 16 ppm TPHmo and ND for SVOCs. Among the grab groundwater samples, only that from SB-E exhibited detectable TPHg where up to 39,000 ppb TPHg, and 3,200, 750, 1,200, 3,600 ppb BTEX, respectively, was reported. Up to 5,800 and 7,200 ppb of TPHd and TPHmo respectively, were exhibited in the groundwater samples. See Attachment 3.

Sanborn maps and aerial photos were used to attempt to determine the location of the former UST, however, results were inconclusive. From the Sanborn maps, no other areas of hazardous materials usage were identified. A prior request for services by the Port of Oakland was made to remove a gasoline pump and tank in a location consistent with where the UST is assumed to have been. Magnetometer and GPR surveys were performed to identify possible USTs or remnants. Four subsurface anomalies were identified. Anomaly I was excavated to approximately 6' bgs. Rebar, wires and concrete foundation was encountered and it appears this was the location of the former UST. Soil sample M-1-5 was taken from this pit at a depth of 5' bgs. This sample exhibited 2,300 ppm TPHg and 1.89, 3.7, 48, 7.2, 5.1 ppm, BTEX and MTBE, respectively. The MTBE result was run using EPA Method 8020. Given the absence of detection of MTBE in all other soil and groundwater samples, it is the consultant's opinion that this result is anomalous.

10/9/01- Four monitoring wells, MW-1 through MW-4, were installed next to and at locations assumed up and down-gradient of the former tank and northwest of the former UST where elevated groundwater samples were observed. Soil samples were taken from depths of 5' and 8' bgs. Up to 34 ppm TPHg, 0.7, 0.068, 0.7, 0.97 ppm BTEX, respectively, <0.05 ppm MTBE, 300 ppm TPHmo, 74 ppm TPHd and ND for semi-volatiles was exhibited in soil samples. MW-1, located within the former tank pit, and MW-4, located north of MW-1, exhibited the highest contamination where up to 44,000 ppb TPHg, 1,900, 300, 1, 500, 3,300 ppb BTEX was reported. Contamination, while expected near the former UST (MW-1), is less explainable in the area of MW-4. Groundwater gradient has been to the northeast, the opposite direction of what would be expected ie southwest towards the estuary. See Attachment 4.

4/26/02- MW-5 was installed northeast (down-gradient) of the former tank pit. Soil samples were collected from 7 and 10' bgs from the boring for MW-5. These samples reported ND for TPHg and BTEX, 14 ppm TPHd and 26 ppm TPHmo. The depth to water in MW-5, 4.69', produced a gradient consistent with that previously determined, northeast.

5/15/02- Approximately 60 cubic yards of soil from a 10' by 10' by 11' bgs area was excavated in an area centered around MW-1. The excavation area also included the location of former boring M-1. MW-1 was properly destroyed at this time. One hundred twenty pounds of Oxygen Release Compound (ORC) was distributed across the floor of the excavation prior to backfilling. No soil sampling was done as the excavation extended beyond the depth to groundwater.

10/10/02- To allow for the future development of the site, monitoring wells MW-2, MW-3 and MW-4 were properly destroyed. MW-4a, the replacement well for MW-4, was installed just north of the original well. Soil samples were collected from 6.5 and 10' bgs from the boring for MW-4a. Up to 5 ppm TPHd, 11 ppm TPHmo, 0.034 benzene was exhibited in these samples. TPHg and MTBE were ND.

11/22/02- As part of the preferential pathway investigation, four temporary monitoring wells were advanced within the utility backfills. Temporary wells TW-1 and TW-2 were located at the up-gradient property boundary within the backfill of the storm drain and sanitary sewer backfills, respectively and temporary wells TW-3 and TW-4 were located down-gradient of MW-5 within the same respective utility backfills. No TPHg, BTEX or MTBE was detected in any of the groundwater samples from the temporary wells. TPHd and TPHmo ranging from ND to 470 ppb were found in these water samples. Because the concentrations of TPHd and TPHmo in the up and down-gradient water samples were similar, either the site is not adding to the influent TPH concentration and/or the utilities are not acting as preferential pathways. See Attachment 4.

The remaining wells, MW-4a and MW-5 have been sampled for four events from 6/02 to 5/03 for TPHg, BTEX, MTBE, TPHd, TPHmo and PAHs with results being ND to just slightly above detection limits. See Attachment 6.

A Screening-Level Risk Assessment was performed evaluating all soil and groundwater data to date (1/02). The site specific assessment assumed the proposed development would be located within the footprint of the former restaurant building, therefore, the only complete soil and groundwater contamination exposure scenario would be to future commercial and construction workers. Ecological exposure to aquatic life and terrestrial flora and fauna was also evaluated.

The exposure pathways of direct contact and potential indoor air impact from soil and groundwater exposure through volatilization to indoor air for commercial workers are considered incomplete. Soil concentrations are below RBSLs for construction workers. Groundwater concentrations in all wells at the site are below aquatic RBSLs established by the Water Board. Residual soil and groundwater contamination within area of the former UST has been treated with ORC and impacted soil removed.

IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? Yes No

Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? Yes No

Does corrective action protect public health for current land use? Alameda County Environmental Health staff does not make specific determinations concerning public health risk. However, based upon the information available in our files to date, it does not appear that the release would present a risk to human health based upon current land use and conditions.

Site Management Requirements: Case closure for the fuel leak site is granted for commercial land use. If a change in land use to residential or other conservative scenario occurs at this property, Alameda County Environmental Health must be notified and the case needs to be re-evaluated.

Should corrective action be reviewed if land use changes? Yes

Monitoring Wells Decommissioned: yes

Number Decommissioned: 4

Number Retained: 2

List Enforcement Actions Taken: none

List Enforcement Actions Rescinded: none

V. ADDITIONAL COMMENTS, DATA, ETC.

Considerations and/or Variances:

- No records exist for the tank removal presumed to have occurred in 1970, however, a GPR and magnetometer survey did not
 identify any USTs. Excavation revealed an area likely to have been the former tank pit where TPHg impacted soil and
 groundwater was observed.
- Confirmation soil sampling was not done after excavation near MW-1, however, the pit was excavated to 11' bgs, below depth to groundwater and 120 pounds of ORC added to the bottom of the pit.
- Residual petroleum hydrocarbon contamination in soil and groundwater remains in place at this site, however, ORC has been added to the capillary zone to enhance bio-degradation. The residual contamination resides beneath the parking lot of the proposed development.
- The groundwater gradient is contrary to what is assumed, however, monitoring wells indicate the petroleum plume is limited to the site boundary and at 220 ppb TPHg near the proposed commercial building.
- Analysis for EDB, EDC, TAME, ETBE, DIPE and TBA were not done on water and soil samples in the vicinity of the former
 gasoline UST, however, no MTBE has been reported in groundwater and the only soil that reported MTBE was run using EPA
 Method 8020 and not confirmed by GC/MS.
- No source or explanation for the petroleum contamination found in groundwater north of the former UST is given.

Conclusion:

Alameda County Environmental Health staff believes that the levels of residual contamination do not pose a significant threat to water resources, public health and safety, and the environment under the proposed future commercial land use. The source area (10'x10'x 11'deep) was over-excavated and 120 pounds of ORC added on the excavation floor. Residual pollution is expected to biodegrade over time. This area is proposed as a paved parking lot in the future. A risk assessment prepared by Iris-Cambria for the site indicates that the site does not appear to pose a significant threat to the public and the environment under the current use. It is anticipated that bioremediation and attenuation process over time will be effective in reducing residual pollution remaining at this site. ACEH staff recommends closure for this site.

VI. LOCAL AGENCY REPRESENTATIVE DATA

Prepared by: Barney Chan	Title: Hazardous Materials Specialist
Signature: Barney Cha_	Date: 5/3/04
Approved by: Donna L. Drogos, P.E.	Title: Supervising Hazardous Materials Specialist
Signature:	Date: 05/03/04

This closure approval is based upon the available information and with the provision that the information provided to this agency was accurate and representative of site conditions.

VII. REGIONAL BOARD NOTIFICATION

Regional Board Staff Name: Betty Graham	Title: Associate Water Resources Control Engineer
RB Response: Concur, based solely upon information contained in this case closure summary.	Date Submitted to RB:
Signature:	Date:

Attachments:

- 1. Vicinity Map
- 2. Soil Boring Location Map
- 3. Soil Boring Location Map
- 4. Monitoring and Temporary Well Location Map
- 5. Soil Analytical Data-Light Range and MTBE, Heavy Range and SVOCs, 4 pages
- 6. Groundwater Analytical Data, Borings, Temporary and Permanent Wells, 7 pages
- 7. Boring Logs, Soil Borings, Temporary and Permanent Wells, 16 pages

This document and the related CASE CLOSURE LETTER, shall be retained by the lead agency as part of the official site file.

Conclusion:

Alameda County Environmental Health staff believes that the levels of residual contamination do not pose a significant threat to water resources, public health and safety, and the environment under the proposed future commercial land use. The source area (10'x10'x 11'deep) was over-excavated and 120 pounds of ORC added on the excavation floor. Residual pollution is expected to biodegrade over time. This area is proposed as a paved parking lot in the future. A risk assessment prepared by fris-Cambria for the site indicates that the site does not appear to pose a significant threat to the public and the environment under the current use. It is anticipated that bioremediation and attenuation process over time will be effective in reducing residual pollution remaining at this site. ACBH staff recommends closure for this site.

VI. LOCAL AGENCY REPRESENTATIVE DATA

Prepared by: Barney Chan	Title: Hazardous Materials Specialist
Signature: Barney Cha_	Date: 5/3/04
Approved by: Donna L. Drogos, P.E.	Title: Supervising Hazardous Materials Specialist
Signaturo:	Date: 05/03/04

This closure approval is based upon the available information and with the provision that the information provided to this agency was accurate and representative of site conditions.

VII. REGIONAL BOARD NOTIFICATION


Regional Board Staff Name: Betty Graham	Title: Associate Water Resources Control Engineer
RB Response: Concur, based solely upon information contained in this case closure summary.	Date Submitted to RB;
Signature: Add In	Date: 5/11/04

Attachments:

- 1. Vicinity Map
- 2. Soil Buring Location Map
- 3. Soil Boring Location Map
- 4. Monitoring and Temporary Well Location Map
- 5. Soil Analytical Data-Light Range and MTBE, Heavy Range and SVOCs , 4 pages
- 6. Groundwater Analytical Data, Borings, Temporary and Permanent Wells, 7 pages
- 7. Boring Logs, Soil Borings, Temporary and Permanent Wells, 16 pages

This document and the related CASE CLOSURE LETTER, shall be retained by the lead agency as part of the official site file.

Post-It® Fax Note 7671	Date \$1164 pages
To Barney Chan	From Belty Graham
Co./Dept.	Co.
Phone #	Phone ii
Fax# :337-9335	Fax# \





Port of Oakland


1275 Embarcadero Embarcadero Cove Project Oakland, California




·Vicinity Map









Port of Oakland

1275 Embarcadero Embarcadero Cove Project



Site Plan

Table 1: Soil Analytical Data - Light-Range Petroleum Hydrocarbons and MTBE - 1275 Embarcadero, Oakland, CA

Sample	Date	Sample	TPHg	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE
D	Sampled	Depth (ft)	 		in	ıg/kg —		
Baseline Samples								
RN-A1;1.5-2	05/01/01	1.5		< 0.005	< 0.005	< 0.005	< 0.005	< 1.0
RN-A2;1-1.5	05/01/01	1.0	••	<.0.005	< 0.005	< 0.005	< 0.005	< 1.0
RN-A3;0.5-1	05/01/01	0.5		< 0.005	< 0.005	< 0.005	< 0.005	` < 1.0
RN-A4;1.0-1.5	05/01/01	1.0		< 0.005	< 0.005	< 0.005	< 0.005	< 1.0
RN-B1;1-1.5	05/01/01	1.0		< 0.005	< 0.005	< 0.005	< 0.005	< 1.0
RN-B2;1-1.5	05/01/01	1.0	••	< 0.005	< 0.005	< 0.005	< 0.005	< 1.0
SB-1;0.75-1.25	05/01/01	0.75	< 1.1	< 0.0056	< 0.0056	< 0.0056	< 0.0056	
SB-1;3-3.5	05/01/01	3.0	< 1.0	0.013	< 0.0052	< 0.0052	< 0.0052	,
SB-1A;0-0.5	05/02/01	0.0	< 1.1	< 0.0054	< 0.0054	< 0.0054	< 0.0054	••
SB-1A;5-5.5	05/02/01	5.0	500	< 0.130	1.1	5.0	16.1	••
SB-1B;1-1.5	05/02/01	1.0	< 1.0	< 0.005	< 0.005	< 0.005	0.0074	••
SB-2;1-1.5	05/01/01	1.0	< .98	< 0.0049	< 0.0049	< 0.0049	< 0.0049	**
SB-2:4-4.5	05/01/01	4.0	< 1.1	< 0.0054	< 0.0054	< 0.0054	< 0.0054	
SB-2C;0-0.5	05/02/01	0.0	< 0.96	< 0.0048	< 0.0048	< 0.0048	< 0.0048	••
SB-2C;3-3.5	05/02/01	3.0	< 1.0	< 0.0052	< 0.0052	< 0.0052	< 0.0052	••
Cambria Samples								
\$B-A-3.5	08/30/01	3.5	< 1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.05
SB-B-3.5	. 08/30/01	3.5	< 1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.05
SB-D-3.5	08/30/01	3.5	< 1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.05
SB-E-3.5	08/30/01	3.5	1.4	0.014	0.0080	< 0.005	0.026	< 0.05
SB-F-3.5	08/30/01	. 3.5	2.5	0.021	0.010	< 0.005	0.005	< 0.05
M-1-5	09/17/01	5.0 .	2,300	1.8	3.7	48	7.2	5.1
MW-1-8.3	10/09/01	8.3	30	0.48	0.067	0.70	0.52	<0.05
MW-2-5.0	10/09/01	5.0	7.5	0.027	0.051	0.041	0.087	<0.05
MW-3-5.0	10/09/01	- 5.0	1.6	< 0.005	< 0.005	< 0.005	< 0:005	<0.05
MW-4-5.3	-10/09/01	5.3	34	0.70	0.068	- 0.41	0.97	<0.05

Table 2: Soil Analytical Data - Heavy-Range Petroleum Hydrocarbons and SVOCs - 1275 Embarcadero, Oakland, CA

ample	Date	Sample	TPHd	TPHmo	bis(2-ethylhexyl) phthalate	Fluoranthene	2 - methyl naphthalene	Naphthalene	Pyrene
D D	Sampled	Depth (ft)	(mg/kg			
Baseline Samples 1								< 0.0046	-
N-A1;1.5-2	05/01/01	1.5	-		-			< 0.005	••
N-A2;1-1.5	05/01/01	1.0	-		•	-	**	< 0.005	-
RN-A3;0.5-1	05/01/01	0.5		-			<u></u>	< 0.0046	
RN-A4:1.0-1.5	05/01/01	1.0	••			· .		< 0.0049	
RN-B1:1-1.5	05/01/01	1.0	-					< 0.0047	**
RN-B2:1-1.5	05/01/01	1.0		+-	-0.22	< 0.33	< 0.33	< 0.33 ·	< 0.33
SB-1;0.75-1.25	05/01/01	0.75	62²	••	< 0.33	< 0.33	< 0.33	< 0.33	< 0.33
SB-1:3-3.5	05/01/01	3.0	13 ²	••	0.61	< 6.60	< 6.60	< 6.60	< 6.60
SB-1A;0-0.5	05/02/01	0.0	240 ²		< 6.60	< 0.33	2.2	2.2	< 0.33
SB-1A:5-5.5	05/02/01	5.0	40 ²		< 0.33	< 0.33		••	
SB-1B:1-1.5	05/02/01	1.0	60 ²			< 0.33	< 0.33	< 0.33	< 0.33
SB-2;1-1.5	05/01/01	1.0	43 ²		< 0.33		< 0.33	< 0.33	< 0.33
SB-2;4-4.5	05/01/01	4.0	43 ²		< 0.33	< 0.33		••	••
SB-2C;0-0.5	05/02/01	0.0	25 ²	••	••		-	••	-
SB-2C;3-3.5	05/02/01	3.0	37 ²			••			•
Cambria Samples						< 0.25		< 0.25	< 0.25
SB-A-3.5	08/30/01	3.5	1.4	5.2		< 0.062		< 0.062	< 0.062
SB-B-3.5	08/30/01	3.5	< 1.0	< 5.0		< 0.062		< 0.062	< 0.062
SB-D-3.5	08/30/01	3.5	< 1.0	< 5.0		< 0.062	•••	< 0.062	< 0.062
SB-E-3.5	08/30/01	3.5	2.4	6.1		< 0.25	**	< 0.25	< 0.25
SB-F-3.5	08/30/01	3.5	4.6	16	••		••		
M-1-5	09/17/01	5.0	850	97	- 0.22	< 0.33	< 0.33	< 0.33 / 0.58 ⁵	< 0.33
MW-1-8.3	10/09/01	8.3	5.7	< 5.0	< 0.33	< 1.0	< 1.0	< 1.0 / < 0.005 ³	< 1.0
MW-2-5.0	10/09/01	5.0	74	- 300	< 1.0	< 0.33	< 0.33	9	< 0.33
MW-3-5.0	10/09/01	5.0	17	- 160	< 0.33	< 0.33 < 0.33	< 0.33	0.62 / 0.623	< 0.33
MW-4-5.3	10/09/01	5.3	8.3	10	< 0.33	< 0.33			ì
0.46	a è				m tatti il				12.
Surface Soil (<3 m)	Commercial Worke	r (non-drinking wat	er source) 4		100	6,000	280	5.7	11,000
Human Health R	tisk-Based	*	11,000	11,000	180 530 ***	60	0.25	4.9	55
Soil Leaching-B	ased for Protection 6	of Aquatic Life	500	1,000	J3V	40		40	. ~
Urban Area Eco Construction Work	toxicity-Based	a man product	, i kayan ay na j	, messa en	1,200	12,000	18,000	450	16,000

Table 1: Soil Analytical Data - Light-Range Petroleum Hydrocarbons and MTBE - 1275 Embarcadero, Oakland, CA

Sample	Date	Sample	TPHg	Benzene	Toluene	Ethylbenzene	Xylenes	МТВЕ
1D	Sampled	Depth (ft)			m	g/kg		
MW-5-7.0	04/26/02	7.0	<1	< 0.005	< 0.005	< 0.005	< 0.005	<0.05
MW-5-10.0	04/26/02	10.0	<1	< 0.005	< 0.005	< 0 005	< 0 005	<0.05
MW-5-10.5D*	04/26/02	10.5	<1	< 0.005	< 0.005	< 0.005	< 0.005	<0.05
Current Cambria Inv	estigation							
MW-4a-6.5	11/22/02	6.5	<1	< 0.005	< 0.005	< 0 005	< 0.005	<0.05
MW-4a-10.0	11/22/02	10.0	<1	0.034	< 0.005	< 0.005	< 0.005	<0.05
Soil Screening Values Surface Soil (<3 m) C Human Health Ris	Commercial Worker	non-drinking water s	ource] ¹	0.39	89	220	210	
-	ed for Protection of A	quatic Life	400	2.1	8.4	220 24	210 sat	69
Urban Area Ecoto:	xicity-Based	idance mic		25	150			
Construction Worker	3							

Abbreviations and Methods:

ft = feet

mg/kg = milligrams per kilogram

- = not available, not analyzed, or does not apply

MTBE = methyl tert-butyl ether by EPA Method 8020

Benzene, toluene, ethylbenzene, and xylenes by EPA Method 8020 or 8021B

Thursday, and the state of the

TPHg = total petroleum hydrocarbons as gasoline by EPA Methods modified 8015, 5030, and 8020 or 602

sat = saturation limit

Notes:

- *Duplicate Sample.
- ¹ Soil screening values from RWQCB's (2000) Table B-2.
- ² Soil screening values from RWQCB's (2000) Table K-3.

Bolded values indicate exceedance of soil screening values.

Table 2: Soil Analytical Data - Heavy-Range Petroleum Hydrocarbons and SVOCs - 1275 Embarcadero, Oakland, CA

Sample ID	Date Sampled	Sample Depth (ft)	ТРНа	TPHmo	bis(2-ethylhexyl) phthalate	Fluoranthene	2 - methyl naphthalene	Naphthalene	Pyrene
						mg/kg			
MW-5-7.0	04/26/02	7.0	8.6	15					
MW-5-10.0	04/26/02	10.0	14	22				••	
MW-5-10.5D*	04/26/02	10.5	12	26	••				- -
Current Cambria In	vestigation								
MW-4a-6.5	11/22/02	6.5	5.0	11					
MW-4a-10.0	11/22/02	10 0	2.9	< 5 0					
Soil Screening Value									
	Commercial Worker	[non-drinking water	source] ⁴						
Human Health Ris			11,000	11,000	180	6,000	280	5 7	11,000
	sed for Protection of A	Aquatic Life	500	1,000	530	60	0 25	4.9	55
Urban Area Ecoto						40		40	
Construction Worker								40	••
Human Health Ris	sk-Based		16,000	16,000	1,200	12,000	18,000	450	16,000

Abbreviations and Methods:

ft = feet

mg/kg = milligrams per kilogram

- = not available, not analyzed, or does not apply

TPHd = total petroleum hydrocarbons as diesel by EPA method 8015

TPHd analyses with silica gel clean-up prior to extraction unless otherwise noted

TPHmo = total petroleum hydrocarbons as motor oil by EPA method 8015

SVOC = semi-volatile organic compounds by EPA Method 8270 (modified 8100) and 3550 or 625 and 3510 unless otherwise noted

Notes:

Only those compounds above laboratory reporting limits are shown

Bolded values indicate exceedance of soil screening values.

^{*}Duplicate sample.

¹ Baseline samples analyzed for SVOCs by EPA Method 8260 or 8270

² No silica gel cleanup performed, prepared by shaker table.

³ Analyzed by EPA Method 8270 and additionally by EPA Method 8260

⁴ Soil screening values from RWQCB's (2000) Table B-2.

⁵ Soil screening values from RWQCB's (2000) Table K-3.

Table 3: Groundwater Analytical and Elevation Data - Light-Range Petroleum Hydrocarbons and MTBE - 1275 Embarcadero, Oakland, CA

Sample ID TOC	Date Sampled	Groundwater Elevation	Depth to Water	TPHg	Benzene	Toluene	Ethylbenzene µg/L ————	Xylenes	МТВЕ
(ft)		(ft ^t)	(ft)						
Baseline Grab S	•							 ,	
SB-1	05/01/01		-	80,000	8,600	8,200	3,900	14,600	
SB-1A	05/02/01			25,000	260	170	760	2,290	••
SB-2	05/01/01			< 50	< 0.5	< 0.5	< 0.5	< 0.5	
Cambria Grab S	Samples								
SB-A	08/30/01		**	< 50	-06	-0.5			
SB-B	08/30/01			< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 5.0
SB-D	08/30/01		****	< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 5.0
SB-E	08/30/01				< 0.5	< 0.5	< 0.5	< 0.5	< 5.0
SB-F	08/30/01			39,000	3,200	750	1,200	3,600	< 200
	00.50.01			< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 5.0
TW-1	11/22/02		**	< 50	< 0.5	< 0.5	.0.5	_	
ΓW - 2	11/22/02			< 50	< 0.5		< 0.5	< 0.5	< 5.0
ΓW-3	11/22/02			< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 5.0
ľW-4	11/22/02		**	< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 50
Cambria Monite	oring Well Samples	3		- 100	V 0.5	< 0.5	< 0.5	< 0.5	< 5.0
MW-1	10/12/01	4.88	7.15						
12.03	10/19/01	4.81	7.22	11,000	900	300	••		**
	12/05/01 2	5.33	6.70	13,000		300	470	1,000	
	12/05/01 3	4.74	7.29	3,100	1,300 270	180	1,200	860	< 20
	12/19/01 4	4.95	7.08	3,100		12	150	74	< 50
	05/03/02	6.12	5.91		1.400			~ -	
		V.12	J.71	20,000	1,400	160	580	630	<500
/W-2	10/12/01	5.71	5.75						
11.46	10/19/01	5.52	5.94	< 50	< 0.5	< 0.5			
	12/05/01 2	6.11	5.35	< 50	< 0.5	< 0.5	< 0.5	< 0.5	
	12/05/01 3	5.66	5.80	< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 5.0
	12/19/01 4	5.65	5.81			-	< 0.5	< 0.5	< 5 0
	05/03/02	6.46	5.00	< 50	< 0.5				
	6/10/2002 ⁷	6.57	4.89	< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 5 0
		****	7.07	~ 20	< 0.5	< 0.5	< 0.5	< 0.5	< 5.0

Table 4: Groundwater Analytical and Elevation Data - Heavy-Range Petroleum Hydrocarbons, SVOCs and PAHs 1275 Embarcadero, Oakland, CA

Sample ID TOC	Date Sampled	Groundwater Elevation (ft ¹)	Depth to Water (ft)	Thun	Zara a	400mph.	Diotz-enym	Hueronia Hg/L Hg/L	oun Hebu	Z. mensy.	Apply of the state	Juan Harbout	300 Juny	
Baseline Grab	Samples													
SB-I	05/01/01			2,900		< 94	< 94	< 94		260	610	< 94	< 94	
SB-IA	05/02/01			800		<9.6	<9.6	<9.6		130	170	<96	<9.6	
SB-2	05/01/01			180		< 9.7	< 9.7	< 9.7	~	< 9.7	< 97	< 97	< 9.7	
Cambria Grab	Samples													
SB-A	08/30/01			1,500	7,200	< 10		< 10			< 10	< 10	< 10	
SB-B	08/30/01			63	550	< 10		< 10			< 10	< 10	< 10	
SB-D	08/30/01			1,100	3,400	< 10		11			< 10	< 10	1 I	
SB-E	08/30/01	•••		5,800	350	< 50		< 50			370	< 50	< 50	
SB-F	08/30/01			480	1,400	< 10		< 10			< 10	< 10	< 10	
TW-I	11/22/02			78	470									
TW-2	11/22/02			< 50	< 250	**		••						
TW-3	11/22/02			120	350									
TW-4	11/22/02			< 50	< 250				3-					
Cambria Moni	toring Well Samp	oles												
MW-1	10/12/01	4.88	7.15											
12.03	10/19/01	4.81	7.22	3,300	< 250	< 10	< 10	< 10		54	66	< 10	< 10	
	12/05/01 2	5.33	6.70	3,800	< 250	72		< 10	150	220	360	< 10	< 10	
	12/05/01 3 4	4.74	7.29	680	< 250	9.6	u_	< 1.0	18	14	22	1.3	< 1.0	
	12/19/01 5	4.95	7.08											
	5/3/2002 8	6.12	5.91	5,300	450									

Table 3: Groundwater Analytical and Elevation Data - Light-Range Petroleum Hydrocarbons and MTBE - 1275 Embarcadero, Oakland, CA

Sample ID TOC	Date Sampled	Groundwater Elevation	Depth to Water -	TPHg	Benzene	Toluene	Ethylbenzene	Xylenes	МТВЕ
(ft)	Sampled	(ft !)	(ft)		· · · · · · · · · · · · · · · · · · ·		μg/L		
MW-3	10/12/01	5.89	6.60				····		· · · · · · · · · · · · · · · · · · ·
12.49	10/19/01 5	5.84	6.65	290				,	
	12/05/01 25	6 69	5.8	310	2.0	6.6	0 54	1.2	
	12/05/01 3.5	5.54	6.95	320	0.72	2.2	< 0.5	< 0.5	< 5.0
	12/19/01 4	6.10	6.39		0.84	2.6	< 0.5	0.76	< 50
	05/03/02	7.29					••		
	6/10/2002 7	7.44	5.20	280	0.74	0.87	< 0.5	0.76	< 5.0
	0/10/2002	7.44	5.05	220	< 0.5	1	< 0.5	< 0.5	< 5.0
MW-4	10/12/01	4.98	8.15						
13.13	10/19/01	4.91	8.22	44,000	1,900	270	1 500	**	
	12/05/01 2	5.61	7.52	13,000	120	28	1,500	3,300	
	12/05/01 3	5.08	8.05	20,000	420	26 78	170	380	< 10
	12/19/01 4	5.09	8.04	20,000		-	390	870	< 20
	05/03/02	6.93	6.20		1 500				••
	6/10/2002 7	7.15	5.98	19,000	1,500	240	730	1,400	<1,000
	5.0.2002	7.13	3,96	28,000	1,700	230	930	2,100	<500
MW-4a	12/03/02	Not yet surveyed	5.90	< 50	5.7 8	< 108	< 0.5 ⁸	0.58 8	< 0.5 8
MW-5	05/03/02	5.50							
10.19	6/10/2002 7	5.50	4.69	< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5
10.19		5.58	4.61	< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 5.0
	12/03/02	5.22	4.97	< 50	< 0.5 8	< 108	< 0.5 8	< 0.5 8	< 0.5 8
Trip Blank									
TB	12/05/01		=-	< 50	< 0.5	< 0.5	 - 0.5		
					~ 0.3	~ U.3	< 0.5	< 0.5	< 5.0
Groundwater Sc	reening Values ⁶		**				- -		
Indoor Air Impa	cts				84	76,000	170,000 soi	150,000	290000
Aquatic Life Pro	tection			3,700 *	700 b	5,000 ^b	430 °	13 ^d	8,000°

Table 4: Groundwater Analytical and Elevation Data - Heavy-Range Petroleum Hydrocarbons, SVOCs and PAHs 1275 Embarcadero, Oakland, CA

				/	/	/ /	John John John John John John John John	Marine Park	, in ,	* &	, &/	/ ~ /	
Sample ID TOC	Date Sampled	Groundwater Elevation (ft 1)	Depth to	· Zan	2 / 22	A CONTRACTOR	Dist. Co.	— μg/L	outhout 1	Top Hool Top	1.C. Hude.	Parent de la contraction de la	William Survey Services
MW-2	10/12/01	5.71	(ft) 5.75										
11.46	10/19/01	5.52				**							
	12/5/01 2	6.11	5.94	210	460	< 10	< 10	< 10		< 10	< 10		
	12/05/01 3.4		5.35	150	560	< 0.5		< 0.25		< 1.0	< 0.25	< 10	< 10
	12/19/01 5	5.66	5.80	75	270	< 0.5		< 0.25	< 1.0	< 1.0		0140	< 0.25
	5/3/2002 8	5.65	5.81					••		· ·	< 0.25	< 0.25	< 0.25
	6/10/2002 °	6.46	5 00	440	440								
	0:10:2002	6.57	4.89	220	370	<10*		<10*				, **	
MW-3	10/12/04							-10			<10*	<50*	<10*
12.49	10/12/01	5.89	6.60										
12.49	10/19/01 6	5.84	6.65	1,600	1,300	< 25	< 25						
	12/05/01 2-6	6.69	5.80	480	480	< 0.5		< 25		670	420	< 25	< 25
	12/05/01 3.6	5.54	6.95	530	550	< 0.5		< 0.25	< 1.0	< 1.0	< 0.25	< 0.25	< 0.25
	12/19/01 5	6.10	6.39					< 0.25	< 1.0	< 1.0	< 0.25	< 0.25	0.31
	5/3/2002 8	7.29	5.2	770	430			**					
	6/10/2002 9	7.44	5.05	390									
			0.00	230	470	<10*		<{0*			<10*	<50*	<10*
AW-4	10/12/01	4.98	8.15										10
13.13	10/19/01	4.91	8.22										
	12/05/01 2	5.61		33,000	900	< 50	< 50	< 50		< 50	< 50	< 50	- 50
	12/05/01 3	5.08	7.52	6,400	430	24		< 10	99	190	60		< 50
	12/19/01 5	5.09	8.05	5,400	450	21		< 10	100	180	96	18	< 10
	5/3/2002 8		8.04					v .				12	< 10
	6/10/2002 °	6.93	6.20	3,600	300			~ •					
	0/10/2002	7.15	5.98	4,500	<250	<50*		<50*	**		**		
IW-4a	12/2/2000							-50			250*	<250*	0.12*
44	12/3/2002	Not yet surveyed	5.9 0	<50	<250	<0.5*		<0.062*	at 0#				
W-5	5 /2 /2 a 0					-	-	~0.002**	<1.0*	<1.0*	<0.2*	<0.05*	<50*
	5/3/2002 8	5.50	4.69	74	<250								
10.19	6/10/2002 °	5.58	4.61	110	330	<10*				•	-		
	12/03/02	5.22	4.97	<50	<250	<0.5*	••	<10*			0*</td <td><50*</td> <td><10*</td>	<50*	<10*
			•		~220	<0.5* 2 of 3		0 24*	<1.0*	<1.0*	<0.2*	<0.05*	1.0*

Table 4: Groundwater Analytical and Elevation Data - Heavy-Range Petroleum Hydrocarbons, SVOCs and PAHs 1275 Embarçadero, Oakland, CA

Sample ID TOC	Date Sampled	Groundwater Elevation (ft ')	Depth to Water (ft)		om S	Dist. Config.	- μg/L	Then Then The Then The Then The Then Then	ound the state of	January Harmond	Journey Journey
Groundwater So Indoor Air Impo Aquatic Life Pro			6	40 ² 640	 310 ⁸	32 b	 11 °	26,000 sol 26,000 sol 2.1 d 2.1 d	9,200 2,350 °	 4.6 ^r	135 sol 300 °

Abbreviations and Methods:

ft = feet

μg/L = micrograms per liter

-- = not available, not analyzed, or does not apply

msl = mean sea level

TOC Elev (ft) = top of casing elevation in feet (Port of Oakland datum)

TPHd analyses with silica gel clean-up prior to extraction unless otherwise noted

TPHmo = total petroleum hydrocarbons as motor oil by EPA method 8015

SVOC = semi-volatile organic compound analyses performed by

EPA Method 8270 (modified 8100) and 3550 unless otherwise noted

PAH = polynuclear aromatic hydrocarbon analyses performed by

EPA Method 8270D

TPHd = total petroleum hydrocarbons as diesel by EPA method 8015, and 3550 or 3510

Only those compounds above laboratory reporting limits are shown

Depth to water in monitoring wells is ft below TOC.

sol = solubility threshold

Notes:

Bolded values indicate exceedance of groundwater screening values

- ^a RWQCB Saltwater and Freshest Water Criteria
- ^b USEPA Freshwater Chronic Ecotoxicity Criteria
- ^c USEPA Saltwater Chronic Ecotoxicity Criteria
- ^d USDOE Freshwater Chronic Preliminary Remedial Goal
- ^c USEPA Saltwater Acute Lowest Observable Effect Level
- ^f USEPA Saltwater Crierion for Continuous Concentration
- g Ontario Ministry of Environment and Energy Drinking Water Screening Level

¹ Elevation in feet, Port of Oakland datum

² Wells gauged between 6:00 am and 6:30 am on 12/5 near lower high tide.

³ Wells gauged between 11.40 am and 12:00 pm on 12/5 near higher high tide.

⁴ SVOC extraction performed past standard 7day hold time per SW-846 Table 2-36 Revision 3, 1

⁵ Wells gauged between 9:00 pm and 9:15 pm on 12/19 at lower low tide.

⁶ Sample was collected pre-purge

⁷ Goundwater screening values from RWQCB's (2000) Table F-2, F-4a, b, and c.

⁸ Sample was analyzed without silica gel clean-up.

⁹ Depth to water measurement collected on July 2, 2002.

^{*} PAH analysis

Table 1: Groundwater Analytical Data - Light-Range Petroleum Hydrocarbons and MTBE - 1275 Embarcadero, Oakland, CA

Sample ID	Date	TPHg	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE →
	Sampled				ıg/L		
				< 0.5	< 0.5	< 0.5	< 5.0
TW-I	11/22/02	< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 5.0
TW-2	11/22/02	< 50	< 0.5		< 0.5	< 0.5	< 5.0
TW-3	11/22/02	< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 5.0
TW-4	11/22/02	< 50	< 0.5	< 0.5	~0.5	*	
MW-2	06/10/02	< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 5.0
MW-3	06/10/02	220	< 0.5	1	< 0.5	< 0.5	< 5.0
MW-4	06/10/02	28,000	1,700	230	930	2,100	<500 •
14141-4	,				< 0.5	0.58	< 0.5
MW-4a	12/03/02	< 50	5.7	< 1.0	< 0.5	< 0.5	< 50
IAT AA —ta	02/20/03	< 50	1.6	<0.5	<0.5	<0.5	<5.0
	05/14/03	<50	0.58	<0.5	Z-0.2		
`	00.200				< 0.5	< 0.5	< 5.0
1007.5	06/10/02	< 50	< 0.5	< 0.5		< 0.5	< 0.5
MW-5	12/03/02	< 50	< 0.5	< 1.0	< 0.5	< 0.5	< 5.0
	02/20/03	< 50	< 0.5	< 0.5	< 0.5	< 0.5	< 5.0
	05/14/03	< 50	< 0.5	< 0.5	< 0.5	~ 0.5	

Abbreviations and Methods:

NOTE: 12/03/02 benzene, toluene, ethylbenzene, xylenes, and methyl tertiary butyl ether by EPA Method 8260

All other benzene, toluene, ethylbenzene, xylenes, and methyl tertiary butyl ether by EPA Method 8020

TPHg = total petroleum hydrocarbons as gasoline by EPA Methods modified 8015, 5030, and 8020 or 602

 $\mu g/L = micrograms per liter$

Table 2: Groundwater Analytical Data - Heavy-Range Petroleum Hydrocarbons and PAHs 1275 Embarcadero, Oakland, CA

	Date /	True	TPHIMO	4cenaphinalene	Pinoranthene	1. methy.	2 methys	Nephilipiline	Phenantirene	- A. P. Prene	/
Sample ID	Sampled	4				μg/L					
TW-1 TW-2 TW-3	11/22/02 11/22/02 11/22/02	78 < 50 120	470 < 250 350	 	 	 	 	 	 	-	
TW-4	11/22/02	< 50	< 250 370	 <10*	<10*			<10*	<50*	<10*	•
MW-2	06/10/02 06/10/02	220 390	470	<10*	<10*			<10*	<50*	<10*	
MW-3 MW-4	06/10/02	4,500	<250	<50*	<50*			250*	<250*	0.12* <50*	
MW-4a	12/03/02 02/20/03	<50 <50 59	<250 <250 < 250	<0.5* <10* < 10 *	<0.062* <10* <10*	<1.0* <10* <10*	<1.0* <10* <1 0 *	<0.2* <10* <10*	<0.05* <10* < 10 *	<10* 0.23*	•
MW-5	05/14/03 06/10/02 12/03/02 02/20/03 05/14/03	110 <50 <50 < 50	330 <250 <250 <250	<10* <0.5* <10* <10*	<10* 0.24* <10* <10*	<1.0* <10* <10*	<1.0* <10* <10*	<10* <0.2* <10* <10*	<50* <0.05* <10* <10*	<10* 1.0* <10* 0.32*	

Notes:

* PAH analysis

Abbreviations and Methods:

ft = feet

 μ g/L = micrograms per liter

- = not available, not analyzed, or does not apply

TPHd = total petroleum hydrocarbons as diesel by EPA method 8015, and 3550 or 3510

TPHmo = total petroleum hydrocarbons as motor oil by EPA method 8015


PAH = polynuclear aromatic hydrocarbon analyses performed by EPA Method 8270D

* Signal Signal

\mathbf{B}	ASE	LI		7		DRILL LC	G NO.: SB-	Page 1 of 1
	5900 Hollis Stre Emeryville, Calif (510) 420-86 (510) 420-1	iornia 94 86 voice	608	Loca Drille Metr Logg Datu	er nodi ger	: Embarcadero Cove ; Precision Sampling : Direct push : WKS : N/A	Boring no Project no. Date Casing size Bore size	: S8-1 : 98379-30 : 5/1/01 : 1-inch : 4-inch
Depth In feet	Hydropunch:	Samples	nscs	GRAPHIC	PID (ppm)	Water Levels ▼ Water level observed dunn ▼ Water level measured		NOT
		Sa	Sn	<u> </u>	(pp)	DESCRIPT	ION	
171111111111111111111111111111111111111			GW		0.2	Asphalt cover 4 inches Yellowish brown GRAVEL wi 3/4-inch diameter subangular grained sand, moist (Baserod	r clasts, fine	
3			SP		154	Very dark gray to gray SAND grained, moist (Fill) Decrease in gravel, some cla		Slight petroleum o
5	5				210	Greenish gray gravelly CLAY diameter angular clasts, high	, 1/3- to 2-inch , wet (Bay Mud) F\11	Strong petroleum diesel-gas
7-	y. 100 100 100 100 100 100 100 100 100 10		CH ,		416	Light greenish gray silty CLA large lenses sand lenses 8.5 inches thick, shell fragments	and 9 feet few	Very strong petrol
	10		СН			Total depth 10.0 feet	ATTACHMEN	Product seen on f when pulled Grouted hole to st neat cement

1101	<u> </u>			DRILL LOG NO.: SB-1A							
F005 11 /// -	:						(Page 1 of 1)				
Emeryville, Califo (510) 420-86	5900 Hollis Street, Sulte D Emeryville, California 94608 (510) 420-8686 voice (510) 420-1707 fax			ation er hod ger um	: Embarcadero Cove Boring no. : Precision Sampling Project no. : Direct push Date : WKS Casing size : N/A Bore size		: SB-1A : 98379-30 : 5/2/01 : 1-inch : 4-inch				
Hydropunch:	Samples	SOSA	GRAPHIC	PID (ppm)	Water Levels ✓ Water level observed during ✓ Water level measured DESCRIPTIO		NOTES				
П					Asphalt cover		T				
		SC		0	Mottled brown-gray clayey SAN moist (Fill)		Peat layer at contact 4.0 feet				
<u> </u>	— 	СН		30	Greenish gray mottled with blac high plasticity, very moist (Bay	ck silty CLAY, Mud)					
		sw		652	Light gray silty SAND, fine grain fragments, wet (Native) Increase in clay content	ned, shell					
				•	Total depth 10.0 feet		NTU 239 of water sample Grouted hole to surface with				

The state of the s



5			<u> </u>	4	DRILL LOG NO.: SB-3 (Page 1 of 1)						
Emer (5	5900 Hollis Street, Suite D Emeryville, California 94608 (510) 420-8686 voice (510) 420-1707 fax				on od er	: Embarcadero Cove : Precision Sampling : Direct push : WKS : N/A	Boring no. Project no. Date Casing size Bore size	: SB-3 : 98379-30 : 6/1/01 : 1-inch : 4-inch			
Hyd epth feet	ropunch:	Samples	SOSN	GRAPHIC	PID (ppm)	Water Levels ▼ Water level observed during drilling ▼ Water level measured DESCRIPTION		NOTES			
0			CL SW/ML		0	Brown silty CLAY with sand, mediabundant rootlets, dry (Fill) Brown silty SAND-sandy SILT, ve concrene grained, dry (Fill)	ery fine grained	,			
2 2 2 4 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5		GC/CL			Yellowish brown GRAVEL with si to 2-inch diameter angular to sub (Fill) Brown mottled with greenish gra GRAVEL-gravelly CLAY, 1/3- to diameter subangular to angular plasticity, brick pieces, very mo	y clayey 1 1/2-inch clasts, moderate				
6 7 8 9 9 11 11 11 11 11 11 11 11 11 11 11 11	मितासामा सामा स्थापना		CL/C	# T		Greenish gray to black silty CL. 1/3- to 3/4-inch diameter subar moderate to high plasticity, brid	ck pieces (Fill)	NTU 240 of water sample			



Cambria Environmental Technology, Inc. 1144 - 651h St. Oakland, CA 94608

Telephone: (510) 420-0700 Fax: (510) 420-9170

BORING/WELL LOG

CLIENT NAME Port of Oakland BORING/WELL NAME SB-A **JOB/SITE NAME** Embarcadero Cove DRILLING STARTED 29-Aug-01 LOCATION 1275 Embarcadero, Oakland, CA DRILLING COMPLETED 30-Aug-01 PROJECT NUMBER 458-1705 WELL DEVELOPMENT DATE (YIELD) NA DRILLER Vironex **GROUND SURFACE ELEVATION** Not Surveyed DRILLING METHOD Hydraulic push TOP OF CASING ELEVATION NA BORING DIAMETER __ SCREENED INTERVAL LOGGED BY K. Cejka DEPTH TO WATER (First Encountered) 8.0 ft (30-Aug-01) REVIEWED BY R. Schultz, RG# 7012 DEPTH TO WATER (Static)

REMARKS Hand augered to 3 ft bgs; located 66 ft WNW of eastern planter, 40 ft SSW of northern planter (mdd) BLOW COUNTS U.S.C.S. DEPTH (ft bgs) SAMPLE CONTACT DEPTH (# bg 9 LITHOLOGIC DESCRIPTION **WELL DIAGRAM ASPHALT** FILL: Sandy fill; greyish brown; dry; 20% silt, 80% fine 0.5 grained sand; very high estimated permeability 2.0 CONCRETE 2.5 ASPHALT 2.7 CONCRETE
FILL: Silty gravelly fill; light brown; 10% clay, 30% silt, 3.0 3 SB-A- 3.5 60% fine to coarse grained gravel; high estimated 4.0 Silty CLAY (CL): Brown; dry; 60% clay, 25% silt, 15% CL sand; medium plasticity; very low estimated permeability Sandy CLAY (CH): Grey; damp; 65% clay, 30% sand, 5.0 Portland Type 5% fine grained gravel; high plasticity; very low estimated I/II Cement SB-A- 7.5 @ 8 ft: Brown; wet; 70% clay, 5% silt, 25% sand ∇ 9.0 Silty CLAY (CL): Grey; wet; 65% clay, 35% silt; CL medium plasticity; very low estimated permeability; shell SB-A- 9.5 fragments 10.0 Bottom of Boring @ 10 ft



П NAME

Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

Port of Oakland

HTE NAME	Embar	cadero	Cove			DRILLING COMPLETED 30-Aug	-01		
TION	1275 E	mbarca	dero,	Oakland	<u>i, CA</u>	WELL DEVELOPMENT DATE (YIEL			
ECT NUMBER		705				WITH THE ACT TO EVATION	Not Su	rveyed	
	Virone	x				NIA THE TAXABLE NA			
ING METHOD	Hydra	ulic pusl	า			TOP OF CASING EZZIVE			
NG DIAMETER	2*						ered) 7.0 i	t (30-Aug-01) <u>¥</u>
SED BY	K Cei	ka				DEPTH TO WATER (Flist Encount	NA.		<u>¥</u>
EMED BA	R. Sci	nultz, RC	3# 701	2	- CANADAR OF	DEPTH TO WATER (Static)	m planter		
	Hand	augered	to 3.5	tt bgs;	located 102 ft WNW of	f eatern planter, 40 ft SSW of northe	in plante.		
ARKS	7107-						(sgc)		
BLOW	SAMPLE 1D EXTENT	DEPTH (ft bgs)	U.S.C.S.	GRAPHIC LOG	LITHC	DLOGIC DESCRIPTION	CONTACT DEPTH (# bgs)	WELL I	DIAGRAM
					ASPHALT		0.5		
					CONCRETE ASPHALI	y; dry; 20% silt, 80% fine grained nated permeability; cobble	2.0 2.5 2.7 3.0		
S	в-в- 3.5	- 5-			CONCRETE FILL: Silty gravelly sand, 60% fine to co medium estimated	fill; brown; 15% clay, 20% silt, 5% parse grained gravel; low plasticity, permeability	5.5		Portland Type
s	sB-B- 6.5		SM		grained sand; high	Grey; damp; 40% silt, 60% fine estimated permeability Grey; wet; 60% clay, 40% silt; low estimated permeability	⊽ 7.0		I/II Cement
	SB-B- 10.5	-10-	СН			·	11.0		Bottom of Boring @ 11 ft
									PAGE 1 OF 1

BORING/WELL NAME

DRILLING STARTED

SB-B

29-Aug-01

BORING/WELL LOG



Combria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608

BORING/WELL	LOG

PAGE 1 OF 1

2	•	Telep Fox:	hor (51	ne: 0) -	A 9460 (510) 420-91	420-0 170	700		BORING/WELL NAME	\$B-C				
	IAME				Oaklar				DRILLING STARTED					
SITE	NAME				cadero			nd, CA	DRILLING COMPLETED	29-Aug-01				
\TIC				_		auero.	Cama		WELL DEVELOPMENT D		Not Cur	veyed		
	CT NUMBER 458-1705 Vironex								GROUND SURFACE ELE	VATION _				
LER	NG METHOD Hand auger								TOP OF CASING ELEVATION					
ING GED	G METH DIAMET DBY ED BY _	ER	4" K.	Cej	ka				DEPTH TO WATER (State	Encountered) c)	NA NA		<u>\</u> \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
ARH			Ha	and	augere	d lo 4	it bas;	143 ft WNW of eastern	planter, 36 ft SSW of north	ern plantei				
	BLOW	SAMPLE ID		EXTENT	DEPTH (ft bgs)	U.S.C.S.	GRAPHIC LOG	LITH	OLOGIC DESCRIPTION		CONTACT DEPTH (# bgs)	WEL	L DIAGRAM	
	100 18		ASPHALT FILL: Sandy fill; grey sand; very high estim CONCRETE ASPHALI CONCRETE CONCRETE			ey; dry; 10% silt, 90% fine g imated permeability rey; 10% clay, 90% fine to c y high estimated permeabili	oarse	2.0 2.5 2.7 3.0 4.0		Bottom of Boring @ 4 ft				



Cambria Environmental Technology...c. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fox: (510) 420-9170



JENT	NAME		Port	of Oakl	and			BORING/WELL NAME	SB-D			<u> </u>			
	E NAME		Emb	arcade				DRILLING STARTED _	29-Aug-01						
CATIO			1275	Emba	rcadero	, Oakla	nd, CA	DRILLING COMPLETED _	30-Aug-01						
	T NUME	ER	458-	1705				WELL DEVELOPMENT DA							
RILLEF			Viro	nex				GROUND SURFACE ELEV							
	G METH	OD	Hydi	aulic pu				TOP OF CASING ELEVAT							
	DIAMET		2"					SCREENED INTERVAL _	NA	——————————————————————————————————————					
YGGEL	n RY		K. C	ejka		_		DEPTH TO WATER (First							
:VIEW	ED BY	-	R. S	R. Schultz, RG# 7012 DEPTH TO WATER (Static)					;)		١				
EMARI			Han	d auger	ed to 3	ft bgs;	located 20 ft WNW of ea	stern planter, 30 ft SSW of	northern plan	ler		 			
				1	1						T				
<u></u>	(0	Ō			ن ا	Ω				2 5					
ğ	ĕĔ	빌	I Z	F 8	ő	풀의	LITHO	LOGIC DESCRIPTION		F I	WEL	L DIAGRAM			
PID (ppm)	BLOW	SAMPLE ID	EXTEN	DEPTH (ft bgs)	U.S.C.S.	GRAPHIC LOG	•	•		δĒ.					
<u>-</u>	۳ö	Ϋ́	"	'i		ا "ا				CONTACT DEPTH (ft bgs)					
			1	-	 		ASPHALT			0.5					
		1	- 4	1		XXXX	FILL: Gravelly sand	fill; brown; moist; 70% san	d, 30%	1		1			
		l			-	₩	gravel; high estimate	d permeability							
			- 4			XXX					X/XX/A				
				'L -	<u> </u>	 	ACHODETE			2.0		1			
			- 11				CONCRETE	11. Leave ich black: maict: 5%	/ clay	2.5					
				<u>'</u> L.	_	₩₩	FILL: Silty gravelly I	ll; brownish black; moist; 5% coarse grained gravel; high	o ciay,						
		ļ		T	1	₩	estimated permeabili	ty				į.			
4		SB-D-	3.5			₩									
			_ [T	1	\bowtie]			
						XXX				5.0					
]		<u> </u>	╂		Silty CLAY (CL): Da	rk brown; damp; 65% clay,	35%	1	KWX				
]		1	i	<i>W///</i> //	silt; low plasticity; ve	ry tow permeability				✓ Portland Type I/II Cement			
		1		<u> </u>	CL							,,,, OD,,,,o.,,			
]	L]					Ώ		K/XK/A	1			
3		SB-D-	6.5					0.007 - 11		7.0					
		1		T			Clayey SILT (CL): G	rey; wet; 40% clay, 60% silt w estimated permeability	Ţ.						
		1					medium piasticity, io	w estimated permeasing							
			1	-	1			,							
		[- 1												
			- 1	- ·	СН										
		1	- {												
		1		-10-	1										
		Ì	1_] ``)										
2	}	SB-D			1					11.0	[XXIIXX	Bottom of			
		10.5	, L	T	Τ -							Boring @ 11 ft			
:	1	[1			1 1									
				1											
:				İ	1					1	1	l			
			-	1		1 1						1			
;		1	- [l	l					1	ļ ļ	l l			
		1			ł							1			
		1		į .							1				
								•							
		1	ļ												
	Ì											l			
	l														
	Ī		1									l			
	ţ	ļ	- [1										
	ł				1							į			
								•		1					
]	1			<u> </u>	لــــــــــــــــــــــــــــــــــــــ						PAGE 1 OF 1			



Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

BO	RI	N	G.	/W	FL	1.	L	O	G
----	----	---	----	----	----	----	---	---	---

CLIENT NAME _	Port of Oakland	BORING/WELL NAME SB-E							
JOB/SITE NAME	Embarcadero Cove	DRILLING STARTED 29-Aug-01							
LOCATION	1275 Embarcadero, Oakland, CA	DRILLING COMPLETED 30-Aug-01							
PROJECT NUMBER	458-1705	WELL DEVELOPMENT DATE (YIELD) NA							
DRILLER	Vironex	GROUND SURFACE ELEVATION Not Surveyed							
DRILLING METHOD	Hydraulic push	TOP OF CASING ELEVATION NA							
BORING DIAMETER _	2"	SCREENED INTERVAL NA							
LOGGED BY	K. Cejka	DEPTH TO WATER (First Encountered) 6.0 ft (30-Aug-01)	<u> </u>						
REVIEWED BY	R. Schultz, RG# 7012	DEPTH TO WATER (Static) NA NA	<u> </u>						
REMARKS	Hand augered to 3.5 ft bgs; 63 ft WNW of	eastern planter, 12 ft SSW of northern planter							

PID (ppm)	BLOW	SAMPLE ID	EXTENT	DEPTH (ft bgs)	U.S.C.S.	GRAPHIC	LITHOLOGIC DESCRIPTION		CONTACT DEPTH (ft bgs)	WE	LL DIAGRAM
WELL LOG (PID) HIPORTOF-NEMBARC-NGINTIEMBCOVE.GPJ DEFAULT.GDT 1/1002 8 25 44 PID	18	SB-E- 6 SB-E- 7.5		5	SM	GR GR	ASPHALT EILL: Sandy fill; brown; damp; 10% silt, 90% fine grained sand; very high estimated permeability CONCRETE: dyed EILL: Sandy gravelly fill; brown; damp; 20% sand 80% fine to coarse gravel; very high estimated permeability Silty SAND (SM): Brown; wet; 30% silt, 50% sand, 20% fine gravel; medium to high estimated permeability; shell fragments Silty CLAY (CL): Brown; wet; 60% clay, 40% silt; medium plasticity; low estimated permeability	₩	2.0 2.5 5.0		■ Portland Type I/II Cement Bottom of Boring @ 8 ft
WELL LOG (P):											PAGE 1 OF 1



Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

BORING/WELL LOG

CLIENT	ГИАМЕ		Por	t of Oa	kland			BORING/WELL NAME	SB-F				
JOB/SI	TE NAM				lero Co			DRILLING STARTED	29-Aug-01				
LOCAT	10N		127	5 Emb	arcade	ro, Oak	land, CA	DRILLING COMPLETED	30-Aug-01		···		
PROJE	CT NUM			-1705				WELL DEVELOPMENT DATE (YIELD) NA					
DRILLE	R		Viro	nex				GROUND SURFACE ELE	VATION _	Not	Surveyed		
DRILLII	NG MET	HOD	Hyd	raulic j	push			TOP OF CASING ELEVATION NA					
BORING	G DIAME	TER	2"					SCREENED INTERVAL	NANA				
LOGGE	DBY		K. C	ejka				DEPTH TO WATER (First	Encountered)6	.5 ft (30-A		
REVIEV	VED BY		<u>R. S</u>	chultz	, RG# 7	012	,	DEPTH TO WATER (Stati	ic)	1	IA	Ţ	
REMAR	KS _		Han	d auge	ered to	3.5 ft b	gs; located 90 ft WNW of	eastern planter, 12 ft SSW	of northern pla	anter			
	т	···	1	T			T			1 - 3	. 1		
Ê	_ <u>છ</u>	₽		Ta	S	GRAPHIC LOG				CONTACT EPTH (# bgs)	•		
PID (ppm)	BLOW	SAMPLE ID	EXTENT	DEPTH (# bas)	U.S.C.S.	148	LITHO	LOGIC DESCRIPTION		ĮŽ.	WE	ELL DIAGRAM	
윤	# Š	₩	\	∥ដ≝	3	FR J				lõE	1		
		· · ·	1_		<u>. İ</u>	Ľ							
	•	1	∦	1	L		<u>ASPHALT</u>			0.5		a	
			11			\bowtie		/; damp; 80% sand, 20%gra	vel;]		3	
		İ	I		1	\bowtie	very high estimated p	permeability		1		\$	
	1	1	П			$\otimes\!\!\!\otimes\!\!\!\otimes$				2.0		1	
		1	H				CONCRETE: dyed			2.5		1	
l i	1			1			FILL: Clayey gravelly	y fill; brown; wet; 30% clay,	10%	2.5		1	
		i	И	<u> </u>	1	$\otimes\!\!\!\otimes$	sand, 60% gravel; hig	gh estimated permeability					
9		SB-F- 3.5	, 44		<u> </u>	M	Silty GRAVEL (GM):	Brown; damp; 10% clay, 30		3.5		3	
	ļ			<u> </u>	4	600	60% gravel, very low	estimated permeability	,			Portland Type	
		ļ		Ī	GM	186						I/II Cement	
		ĺ		<u> </u>	-								
6		 SB-F- 5.5			ļ		OLAY (OLD) - Dis-struct			5.5			
ľ		SB-F- 3.0		ļ	СН		plasticity: very low es	amp; 90% clay, 10% silt; hi timated permeability	Ĭ ~	6.0			
]]		Silty SAND (SM): Gr	ev: wet: 40% silt, 60% sand	; high ∑				
				L.	SM		plasticity; high estima	ted permeability					
	!		Ш		""				j				
5		SB-F- 7.5								8.0			
!		ĺ	11					<u> </u>				Bottom of Boring @ 8 ft	
					i						ļ	DOINING OF BILL	
			11		1				ļ				
1													
									İ]		
					l i								
	Į.												
			I						1				
1		İ				.			ì				
- 1					i	- 1							
	1							•					
	[- 1							
										i			
		ļ]		,				j	
1	j	1		ĺ		1						1	
	į			1					ļ			I	
1			- 1			-			1				
F		1	-	- 1	- 1	- 1							
1	1	1	- [ľ	ł				-			-	
J		j	J								- 1		

BORING/WELL LOG



Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

JOB/ LOC/ PRO. DRIL DRIL BORI LOGG REVI	NT NAME SITE NAME ATION JECT NUM LER LING METH ING DIAME GED BY EWED BY ARKS	E E E E E E E E E E E E E E E E E E E	275 Emba 58-1705 &W Drillin tollow-ster Cejka 3. Schultz,	ero Cov ircader ig n auge RG# 7	e o, Oakla r 012		DRILLING STARTED 09-Oct-01 DRILLING COMPLETED 09-Oct-01 WELL DEVELOPMENT DATE (YIELD) 12-Oct-01 GROUND SURFACE ELEVATION Not Surveyed TOP OF CASING ELEVATION 8.83 ft above msl SCREENED INTERVAL 4 to 15 ft bgs DEPTH TO WATER (First Encountered) 8.6 ft (09-Oct-01)					
PIO (ppm)	BLOW	SAMPLE ID	EXTENT DEPTH (# bgs)	U.S.C.S.	GRAPHIC LOG	ытно	LOGIC DESCRIPTION	aktivengili di disemberah di di Pril	CONTACT DEPTH (ft bgs)	WE	LL DIAGRAM	
316	2 2 2	MW-1- 5.0 MW-1- 8.3	- 5 - X	МН		fine to coarse grained permeability Clayey SILT(MH): Bit; low to medium pl shell fragments	fill; light brown; dry; 20% s i sand, 30% gravel; high es ack to grey; damp; 20% cla asticity; low estimated pern	-y, 80% neability; ▼	5.0		Portland Type I/II Cement Bentonite Sea Monterey Sand #2/12 2"-diameter, 0.010" Slotted Schedule 40 PVC	
C LOG (P10) RIPORT OF TEMBARC-TIGIN TECOVERWIGH DEFAULT	1 2 3		15-			@ 13.5 ft: Light yello 5% fine grained sand	wish brown; wet; 10% clay, ; medium plasticity		15.0		Bottom of Boring @ 15 ft	



Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

BORING/WELL	LOG
-------------	-----

MW-2

BORING/WELL NAME

bl 5 665	=	Port of Oakland						NO STARTED	08-Oct-01			······
IT NAME		Embarcadero Cove						DRILLING STARTED 08-Oct-01 DRILLING COMPLETED 09-Oct-01				
	yl L.	127	5 E	mbarca	dero.	Oaklang	I <u>, CA</u>	DEVELOPMENT DA	ATE (YIELD)	12-00	1-01	
TION ECT NU	45B	.17	05				_ , CERT OLDEACE ELE	ΛΑΤΙΟΝ	NOT SHIVE YES			
	1/81	M D	rillina		_			10N 8.26 ft	above n	nsl		
_ING METHODHo			low.	stem a	uger			_ TO, OF THE MATERIAL	4 to 15	ft bas		
								COTILETED /First	Encountered) 10	.0 ft (09-Oct-(<u>)1) </u>
NG DIA	V Coika							n)	5.75 ft (12-Oct-01)			
SED BY		50.4 7012						DEPTH TO WATER (Stati	i of norther nis	nter		
EWED B			-d-	waero	d 10 4	ft bas; lo	cated 28 ft WNW of	eastern planter, 68 feet SSW	Of Horate: pic	111101		
ARKS		—-т	7			T				CONTACT SEPTH (# bgs)	1	DIAGRAM
BLOW	SOUNTS	SAMPLE ID	EXTENT	OEPTH (ft bgs)	U.S.C.S.	GRAPHIC LOG	LITH	HOLOGIC DESCRIPTION		——-	W W	······································
						<u> </u>	ASPHALT			0.5		
	- 1			ļ		××××		ndy fill; grey to brown; dry; 20)% silt, vot: high			Portland Type
- 1	-	1		_			40% cand 48% M	leginti to coarse arams - s	vei, ingii	1.5		I/II Cement
- 1		ļ			. <u>. </u>	XXX	estimated permea	DIRTY				
ł					İ					2.4		Bentonite Seal
1	İ			-			Gravelly sa	ndy fill; brown; dry; 20% silt,	50%	1		
1	1						sand, 30% gravel	; high estimated permeability				■ Monterey
1			111		1	****						Sand #2/12
ļ			Ш							4.5		
- }	1		1	- i	1	- XXX				- \ -		1
- 1			1		<u> </u>	<u>-}^^```</u>	Clayey SILT(MH)	: Grey to brown; moist; 20% nedium plasticity; low estimat	ed	1		
	,			- 5 -	┨		80% sut; fow to n permeability	Region biggins 174		Ţ		
- 1	1	MW-2- 5.0		 	1	-11111	perman ,			-	1. 目 1	
- 1	3	U	\square	<u> </u>		-11111				Í		
- 1	4		\bigcirc		}	-				1		
}	1			i_]							
	İ				1	- (111)				1		
			1		1							
	1		ı	 	1					l l		
ļ				1						į.		
1	l			-	-	-1111				l l		2"-diameter, 0.010" Slotted
	- 1			1	M	н				立		Schedule 40
1			L	10	4	- 1111	ക 10 0 ft: Wet;	shell fragments		- 1	目	PVC
.6	1	MW 2					G 70.0 1.1 112.5			Į.		`
1	3	10.0	Б	₹	1	-	Ì				I 目 :	-
	5		7	1	1							
-		1	F	=	1	1111	ł			- 1		3
]	1	-	+							:}
1		1					1					
1		1			4	[[]]]	1					.4
1		1]		1		1					.1
		i	V	7	1		1	•	= =	14	1.4	.]
1		1	- 1	XΓ	7_		OW CAMPICAL	/i): Grey to brown; wet; 15%	clay, 35%	110	5.0	
1		1	1	\mathbb{N}	1 8	SM .	silt, 45% fine to	d): Grey to brown, wet, 10 % of coarse grained sand, 5% gr	ravel; low to	_/ヿ゚		Bottom of Boring @ 15 ft
		1	f		5-	·	moderate estin	o coarse grained sand, 5% 9 nated permeability; rust-color	e <u>u otaninia</u>	7	1	Doming o
1		1				[_					
l			l			1						
1				1]	1				l		
1		1			-	ŀ						
1		1			-	1	Į.					
1		1]						PAGE 1 OI
ľ		1		í i	ł	- 1			-			1



Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fox: (510) 420-9170

JOB/SITE NAME Emb LOCATION 127: PROJECT NUMBER 458: DRILLER V&V DRILLING METHOD HOH BORING DIAMETER 8" LOGGED BY K. C	parcadero Cove 5 Embarcadero, Oa 1705 V Drilling ow-stem auger cejka	kland, CA bgs; located 69 ft WNW of	DRILLING STARTED 08-Oct-01 DRILLING COMPLETED 09-Oct-01 WELL DEVELOPMENT DATE (YIELD) 12-Oct-01 GROUND SURFACE ELEVATION Not Surveyed TOP OF CASING ELEVATION 9.29 ft above msl SCREENED INTERVAL 4 to 13 ft bgs DEPTH TO WATER (First Encountered) 7.9 ft (09-Oct-01) DEPTH TO WATER (Static) 6.60 ft (12-Oct-01)				
PID (ppm) BLOW COUNTS SAMPLE ID	DEPTH (# bgs) U.S.C.S.	LITH	OLOGIC DESCRIPTION	CONTACT DEPTH (# bgs)	WELL DIAGRAM		
2 3 5.0 W.904.70F-1/EMBARC-1/GINTECOVEMW.GPJ DEFAULT GDT 1/10/02 WAS-3-2-2-3-4 WAS-3-3-15-3-4 WAS-3-3-15-3-4 WAS-3-3-15-3-4 WAS-3-3-15-3-4 WAS-3-3-15-3-4 WAS-3-3-15-3-4 WAS-3-3-15-3-4 WAS-3-3-15-3-4 WAS-3-15-3-4 WAS	MH	CONCRETE ASPHALT CONCRETE FILL: Gravelly sand sand, 30% gravel; high estimate Concrete Fill: Gravelly sand sand, 30% gravel; high sand sand, 30% gravel; high sand sand, 30% gravel; high sand sand; for the sand sand; high sand sand sand; high sand sand sand sand sand sand sand sand	own; dry; 20% silt, 70% sand, 10% ed permeability ly fill; brown; dry; 20% silt, 50% igh estimated permeability Dark greenish grey; moist; 25% clay, medium plasticity; very low estimated wish brown; wet; 20% clay, 80% silt; or grey; wet; 20% clay, 70% silt, 10% ow estimated permeability; roots	0.5 2.5 2.8 3.0 3.3 5.0	Portland Type I/II Cement Bentonite Seal Monterey Sand #3 2"-diam., 0.020" Slotted Schedule 40 PVC Bottom of Boring @ 13 ft		

BORING/WELL LOG



Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

BORING/WELL LOG

TNA		Port of C				BORING/WELL NAME MW-4					
ITE N	AME	Embarca				DRILLING STARTED 08-Oct-01					
TION 1275 Embarcadero, Oakland, CA											
ECT NUMBER 458-1705						WELL DEVELOPMENT DATE (YIELD) 12-Oct-01					
ER V&W Drilling											
NG METHOD Hollow-stem auger											
G DIAMETER 8"						SCREENED INTERVAL 4 to 15 ft bgs					
∄D BY		K. Cejka				DEPTH TO WATER (First				9-Oct-01)	$\overline{\nabla}$
NED E	BY	R. Schult	z, RG# 7	012		DEPTH TO WATER (Statio				2-Oct-01)	¥.
łKS		Hand aug	ered to	4 fl bgs;	located 18.7 ft WNW of e	entrance way, 3 ft NNW of i		nter			_==:
T				1					<u></u>		
BLOW	SAMPLE ID	EXTENT	(π bgs)	GRAPHIC LOG	LITHO	LOGIC DESCRIPTION		CONTACT DEPTH (# bgs)		VELL DIAGRAM	
2 3 4 4 6	MW-4- 10.5	5-10-	MH SM		© 4.5 ft: Sandy silty fi 20% sand; medium plasticity; low sand; moderate estima Clayey SILT(MH): Grey sand; moderate estima Clayey SILT(MH): Grey medium plasticity; low e Silty SAND(SM): Grey; sand; moderate estimate.	II; black; moist; 5% clay, 75 isticity y; moist; 20% clay, 80% silestimated permeability; wet; 45% silt, 55% fine grated permeability ted permeability wet; 45% silt, 55% fine grated permeability wet; 45% silt, 55% fine grated permeability ; wet; 20% clay, 75% silt, 2 m plasticity; low estimated	ined ined w	4.5 5.3 6.0 11.8		Portland Tyl/II Cement Bentonite S Monterey Sand #3 2"-diam., 0.020" Slotte Schedule 40 PVC Bottom of Boring @ 15 ft	6eal
									j		



CLIENT NAME

WELL LOG (TPH-G) HIPORTOF-INEMBARC-INGINTICOVEMW GPJ DEFAULT GDT 125/02

Cambria Environmental Technology, Inc. 1144 - 65th St. Oakland, CA 94608 Telephone: (510) 420-0700 Fax: (510) 420-9170

BORING/WELL LOG

Port of Oakland

JOB/SITE NAME Em LOCATION 127 PROJECT NUMBER 458 DRILLER Woo DRILLING METHOD Holl BORING DIAMETER 8" LOGGED BY I. YO REVIEWED BY R. M REMARKS Han-	odward Drilling low-stem auger oung Marinai, RG# 54 d augered to 5	o, Oakland, CA 179 ft bgs; located in sidewalk appi	DRILLING COMPLETED 22-Nov-02 WELL DEVELOPMENT DATE (YIELD) NA GROUND SURFACE ELEVATION Not Surveyed TOP OF CASING ELEVATION NA SCREENED INTERVAL 4 to 12 ft bgs DEPTH TO WATER (First Encountered) 6.9 ft (22-Nov-02) DEPTH TO WATER (Static) NA Deproximately 22 ft north of driveway.				
TPHg (mg/kg) BLOW COUNTS SAMPLE ID	DEPTH (ft bgs) U.S.C.S.	GRAPHIC LOG LOG	DLOGIC DESCRIPTION	CONTACT DEPTH (ft bgs)	WELL DIAGRAM		
3	SM SM	@ 1.0 ft: Sandy Graves 50% medium to coars 50% medium to coars 62.0 ft: Baserock a 62.0 ft: Clayey Silty silt, 35% fine to medius permeability. Silty CLAY (CL): Darke silt; low plasticity; low plasticity; low 6.9 ft: Wet. Silty SAND (SM): Gree 30% silt; 65% fine to mestimated permeability Silty CLAY (CL): Green	enish grey; loose; wet; 5% clay,	Q 0.3	Portland Type I/II Cement Bentonite Sea Monterey Sand #2/12 2"-diameter, 0.010" Slotted Schedule 40 PVC Bottom of Boring @ 12 ft		



Cambria Environmenta thnology, Inc. 1144 - 65th St.
Oakland, CA 94608
Telephone: (510) 420-0700
Fax: (510) 420-9170



BORING/WELL LOG

PAGE 1 OF

CLIENT NAME Port of Oakland BORING/WELL NAME MW-5 JOB/SITE NAME Embarcadero Cove DRILLING STARTED 26-Apr-02 LOCATION 1275 Embarcadero, Oakland, CA DRILLING COMPLETED 26-Apr-02 PROJECT NUMBER 458-1705 WELL DEVELOPMENT DATE (YIELD) NA DRILLER Gregg Drilling **GROUND SURFACE ELEVATION** Not Surveyed DRILLING METHOD Hollow-stem auger TOP OF CASING ELEVATION NA BORING DIAMETER 8" SCREENED INTERVAL 4 to 12 ft bgs 1. Young LOGGED BY DEPTH TO WATER (First Encountered) _____7.5 ft (26-Apr-02) REVIEWED BY R. Marinai, RG# 5479 **DEPTH TO WATER (Static)** <u>__N</u>A REMARKS

Hand augered to 5 ft bgs; located in sidewalk approximately 9 ft south of driveway. GRAPHIC LOG (mdd) BLOW CONTACT EPTH (# bgs EXTENT U.S.C.S. DEPTH (ft bgs) SAMPLE LITHOLOGIC DESCRIPTION 5 WELL DIAGRAM CONCRETE 0.3 FILL: Baserock/gravelly fill; high estimated permeability. @ 0.5 ft: Sandy Gravelly FILL: Brown; dry; 15% silt, Portland Type 65% medium to coarse grained sand, 20% coarse gravel; I/II Cement brick fragments present. 0.0 2.5 Bentonite Seal Silty CLAY (CL): Mottled light and dark brown; stiff; dry: 50% clay, 40% silt, 10% fine grained sand; low plasticity: CL low estimated permeability. 3.5 Silty Sandy FILL: Dark brown; dry; 10% clay, 40% silt, Monterey 50% fine to medium grained sand; moderate estimated Sand #2/12 4.0 permeability. CLAY (CL): Interbedded grey and black; stiff; dry; 80% CL clay, 20% silt; high plasticity; low estimated permeability. 5 5.5 Clayey SILT (ML): Grey; very loose; wet; 30% clay, 70% silt; slight plasticity; moderate estimated permeability. 0.0 MW-5-7.0 ML Δ 2"-diameter. 0.010" Slotted Schedule 40 **PVC** 9.5 Silty CLAY (CL): Greenish grey; loose; wet; 70% clay, 30% silt; low plasticity; low estimated permeability; 0.0 MW-5occasional thin sand lenses and shell fragments present. 10.0 CL 12.0 Bottom of Boring @ 12 ft