

December 17, 1991

91 DEC 18 AM 12:26 Susan

6/12/92

Alameda County  
Environmental Health Dept  
Hazardous materials Division  
80 Swan Way  
Room 200  
Oakland, CA 94621

Lop # 2623

not sure who has  
this one. P.S.I did the removal some  
time ago.

Attn: Mr. Paul Smith

RE: 4341 Howard Street  
Oakland, CA

Gentlemen:

Enclosed please find the lead analysis for the above referenced property. The laboratory failed to send these results when the samples were initially run.

We apologize if this has caused any inconvenience. If you have any questions, please contact my office at (415) 363-2181.

Sincerely,

ZACCOR CORP.

*Gary Zaccor*Gary Zaccor  
Project Manager

GZ/Is

Enclosure

Mr & Mrs Jim Mewer  
P.O. Box 726  
Diablo CA 94528

# CHROMALAB, INC.

5 DAYS TURNAROUND

Analytical Laboratory (E694)

December 16, 1991

ChromaLab File No.: 1191156

ZACCOR COMPANIES, INCORPORATED

Attn: Gary Zaccor

RE: Two samples for Lead analysis

Project Name: MINOR PROPERTY

Project Location: Howard St., Oakland

Date Sampled: Nov. 15, 1991

Date Submitted: Nov. 15, 1991

Date Extracted: Dec. 13, 1991

Date Analyzed: Dec. 13, 1991

RESULTS:

<u>Sample I.D.</u>	<u>Lead (mg/kg)</u>
TP-1	8.80
TP-2	123
BLANK	N.D.
SPIKED RECOVERY	100%
DUPLICATE SPIKED RECOVERY	97%
DETECTION LIMIT	2.5
METHOD OF ANALYSIS	7420

→ need to run WET test

ChromaLab, Inc.

*Refaat A. Mankarious*  
Refaat A. Mankarious  
Inorganics Supervisor

  
Eric Tam  
Laboratory Director

NOV

Needs :

- ① Removal of piping & samples under piping & dispenser
- ② Status of stockpiled soils (will need to re-excavate?) & dispose properly. 30 Cubic yds
- ③ Manifest for tank
- ④ Invoice to submit UCR
- ⑤ Contact now Richi Hiett

Paul's letter 12/24/91 - sent Appendix A  
& phone # for Trikes and debris

Zacor report 11/25/91

TP-1 8200 g 33 B 93T 75 E 330 X