# **RECEIVED**

By dehloptoxic at 10:49 am, Feb 01, 2007





Atlantic Richfield Company (a BP affiliated company)

P.O. Box 1257 San Ramon, California 94583 Phone: (925) 275-3801 Fax: (925) 275-3815

30 January 2007

Re: Fourth Quarter 2006 Status Report

Atlantic Richfield Company Service Station #2107

3310 Park Boulevard Oakland, California ACEH Case #RO0002526

"I declare, that to the best of my knowledge at the present time, that the information and/or recommendations contained in the attached document are true and correct."

Submitted by:

Paul Supple

**Environmental Business Manager** 



30 January 2007

Project No. 06-08-614

Atlantic Richfield Company P.O. Box 1257 San Ramon, California 94583 Submitted via ENFOS

Attn.: Mr. Paul Supple

Re:

Fourth Quarter 2006 Status Report, Atlantic Richfield Company (a BP affiliated company)

Station #2107, 3310 Park Boulevard, Oakland, Alameda County, California

ACEH Case #RO0002526.

Dear Mr. Supple:

Provided herein is the *Fourth Quarter 2006 Status Report* for Atlantic Richfield Company Station #2107 located at 3310 Park Boulevard, Oakland, Alameda County, California. This report presents a summary of recent developments at the site up to Fourth Quarter 2006.

Should you have questions regarding this submission, please do not hesitate to contact us at (530) 566-1400.

Sincerely,

BROADBENT & ASSOCIATES, INC.

Thomas A. Venus, P.E.

Senior Engineer

Robert H. Miller, P.G., C.HG.

Principal Hydrogeologist

Enclosure

cc: Mr. Stephen Plunkett, Alameda County Environmental Health (Submitted via ACEH ftp site)

Electronic copy uploaded to GeoTracker

ARIZONA CALIFORNIA

NEVADA

TEXAS

ROBERT H. MILLER

No. 4893

### STATION #2107 QUARTERLY GROUND-WATER STATUS REPORT

Facility: #2107 Address: 3310 Park Boulevard, Oakland, California

Environmental Business Manager: Mr. Paul Supple

Consulting Company/Contact Person: Broadbent & Associates, Inc.(BAI)/Rob Miller & Tom Venus

(530) 566-1400

Consultant Project No.: 06-08-614

Primary Agency/Regulatory ID No.: Alameda County Environmental Health (ACEH)

ACEH Case # RO0002526

### WORK PERFORMED THIS QUARTER (Fourth Quarter 2006):

1. Prepared and submitted the Third Quarter 2006 Status Report.

2. No environmental work was conducted at the site during the Fourth Quarter 2006.

## WORK PROPOSED FOR NEXT QUARTER (First Quarter 2007):

- 1. Prepared and submitted this Fourth Quarter 2006 Status Report (contained herein).
- 2. Investigate acceptability by Oakland Unified School District to drilling in open space of Oakland High School, north of and in lieu of drilling within Park Boulevard.

#### DISCUSSION:

No environmental work has been performed for this site since early 2005. In a letter dated 16 October 2006, ACEH authorized BP to implement the Work Plan Addendum for Offisite Investigation, submitted by URS on 5 April 2005. Due to encroachment issues with City of Oakland and proximity to 16-inch diameter high-pressure gas main and other underground utilities, BAI and Stratus are investigating the potential acceptability of the Oakland Unified School District to drilling within open space at Oakland High School immediately north of the previously approved Hydropunch boring locations. A Site Map is provided as Drawing 1.

#### ATTACHMENTS:

Drawing 1. Site Map, Station #2107, 3310 Park Boulevard, Oakland, California

