



Atlantic Richfield Company
(a BP affiliated company)

P.O. Box 1257
San Ramon, California 94583
Phone: (925) 275-3801
Fax: (925) 275-3815

6 July 2007

Re: Second Quarter 2007 Status Report
Atlantic Richfield Company Service Station #2107
3310 Park Boulevard
Oakland, California
ACEH Case #RO0002526

RECEIVED

1:30 pm, Jul 27, 2007

Alameda County
Environmental Health



"I declare, that to the best of my knowledge at the present time, that the information and/or recommendations contained in the attached document are true and correct."

Submitted by:

Paul Supple
Environmental Business Manager

6 July 2007

Project No. 06-08-614

Atlantic Richfield Company
P.O. Box 1257
San Ramon, California 94583
Submitted via ENFOS

Attn.: Mr. Paul Supple

Re: Second Quarter 2007 Status Report, Atlantic Richfield Company (a BP affiliated company)
Station #2107, 3310 Park Boulevard, Oakland, Alameda County, California;
ACEH Case #RO0002526

Dear Mr. Supple:

Provided herein is the *Second Quarter 2007 Status Report* for Atlantic Richfield Company Station #2107 located at 3310 Park Boulevard, Oakland, Alameda County, California. This report presents a summary of recent developments at the Site through the Second Quarter 2007.


Should you have questions regarding this submission, please do not hesitate to contact us at (530) 566-1400.

Sincerely,


BROADBENT & ASSOCIATES, INC.



Thomas A. Venus, P.E.
Senior Engineer



Robert H. Miller, P.G., C.HG.
Principal Hydrogeologist



Enclosure

cc: Mr. Stephen Plunkett, Alameda County Environmental Health (Submitted via ACEH ftp site)
Electronic copy uploaded to GeoTracker

STATION #2107 QUARTERLY GROUND-WATER STATUS REPORT

Facility: #2107	Address:	3310 Park Boulevard, Oakland, California
Environmental Business Manager:		Mr. Paul Supple
Consulting Company/Contact Person:		Broadbent & Associates, Inc.(BAI)/Rob Miller & Tom Venus (530) 566-1400
Consultant Project No.:		06-08-614
Primary Agency/Regulatory ID No.:		Alameda County Environmental Health (ACEH) ACEH Case # RO0002526

WORK PERFORMED THIS QUARTER (Second Quarter 2007):

1. Prepared and submitted the First Quarter 2007 Status Report.
2. Performed offsite ground-water investigation, across Park Boulevard from Site, within City of Oakland right-of-way. Work performed by Stratus Environmental Services, Inc. (Stratus) on 25 June 2007.

WORK PROPOSED FOR NEXT QUARTER (Third Quarter 2007):

1. Prepared and submitted this Second Quarter 2007 Status Report (contained herein).
2. Prepare Offsite Soil & Ground-Water Investigation Report following results availability.

DISCUSSION:

On 25 June 2007, Stratus and RSI Drilling executed the offsite soil and ground-water Hydropunch boring investigation, in accordance with the *Work Plan Addendum for Offsite Investigation*, submitted by URS on 5 April 2005 and approved by Alameda County Environmental Health in the letter dated 16 October 2006. Work had been delayed for some time due to encroachment issues with the City of Oakland and proximity to high-consequence underground utilities. In the meantime, it had been evaluated but decided against drilling into the base of a small hillside over and behind a short concrete-block retaining wall on property owned by the Oakland High School/Oakland Unified School District.

In accordance with the proposed plan, Hydropunch borings were advanced in four areas across Park Boulevard from the Site. Two borings were advanced at each location to log lithology and collect soil samples, as well as to collect a total of seven depth-discrete ground-water Hydropunch samples. The approximate locations of the Hydropunch boring locations are shown in Drawing 1. Due to the late date of the boring investigation, results are not available to provide herein. The actual boring locations and results of the investigation will be presented within the third quarter, following analysis of the field and laboratory data and preparation of the subsequent Offsite Soil & Ground-Water Investigation report.

ATTACHMENTS:

Drawing 1 Offsite Hydropunch Boring Locations, Station #2107, 3310 Park Boulevard, Oakland, California

Oakland High School

SB-12/HP-9

SB-13/HP-11

SB-14/HP-11

SB-15/HP-12

Sidewalk

16" Steel Gas

10" Sewer 3.6 bgs

PARK BLVD.

33rd St.

Building

PARKING STALLS

LEGEND

— W —	EBMUD WATER LINE	○	MANHOLE
— E —	PG&E 110 kv 6" POWER	■	INLET (STORM CONDUIT)
— GAS —	PG&E GAS LINE	⊗	DESTROYED MONITORING WELL
— SD —	STORM DRAIN	⊕	HYDRO PUNCH LOCATION
— SWR —	SANITARY SEWER	⊕	SOIL BORING LOCATION
○	PROPOSED HYDRO PUNCH AND SOIL BORING LOCATION	⊕	PROPOSED HYDRO PUNCH AND SOIL BORING LOCATION

BROADBENT & ASSOCIATES, INC.
 ENGINEERING WATER RESOURCES & ENVIRONMENTAL
 1324 Menlo Park Ave., Suite 212, Chicago, California

Station #2107
 3310 Park Boulevard
 Oakland, California

Project No.: 06-08-614 Date: 06/27/07

0 30 60
 SCALE (ft)

Drawing 1