ExxonWobil Environmental Services Company

4096 Piedmont Avenue #194 Oakland, California 94611 510 547 8196 Telephone 510 547 8706 Facsimile Jennifer C. Sedlachek Project Manager

ExonMobil

RECEIVED

9:51 am, Sep 01, 2010

Environmental Health

Alameda County

August 25, 2010

Mr. Jerry T. Wickham Alameda County Health Care Services Agency 1131 Harbor Bay Parkway Alameda, California 94502-6577

Subject:

Fuel Leak Investigation Site No. RO0002635

Former Exxon RAS #74121, 10605 Foothill Boulevard, Oakland, California

Dear Mr. Wickham:

Attached for your review and comment is a copy of the *Report of Groundwater Monitoring, Third Quarter 2010* for the above-referenced site. The report, prepared by ETIC Engineering, Inc. of Pleasant Hill, California, details the results of the August 2010 sampling event.

Upon information and belief, I declare, under penalty of perjury, that the information contained in the attached report is true and correct.

If you have any questions or comments, please contact me at 510.547.8196.

Sincerely,

Jennifer C. Sedlachek Project Manager

& Sedwell

Attachment: ETIC Groundwater Monitoring Report

c: w/ attachment:

Mr. Ken Phares - MacArthur Boulevard Associates, Oakland, California

Mr. Peter McIntyre - AEI Consultants

c: w/o attachment:

Mr. Bryan Campbell - ETIC Engineering, Inc.



Report of Groundwater Monitoring Third Quarter 2010

Former Exxon Retail Site 74121 10605 Foothill Boulevard Oakland, California

Prepared for

ExxonMobil Oil Corporation

Prepared by

ETIC Engineering, Inc. 2285 Morello Avenue Pleasant Hill, California 94523 (925) 602-4710

K. Erik Appel, P.G. #8092 Senior Project Geologist SONAL GROWN APPEL NO. 8002

<u>[liezust 25,2010</u>

Date

SITE CONTACTS

Site Name: Former Exxon Retail Site 74121

Site Address: 10605 Foothill Boulevard

Oakland, California

ExxonMobil Project Manager: Jennifer C. Sedlachek

ExxonMobil Environmental Services Company

4096 Piedmont Avenue #194 Oakland, California 94611

(510) 547-8196

Consultant to ExxonMobil: ETIC Engineering, Inc.

2285 Morello Avenue

Pleasant Hill, California 94523

(925) 602-4710

ETIC Project Manager: K. Erik Appel

Regulatory Oversight: Jerry T. Wickham

Alameda County Health Care Services Agency

Environmental Health Services 1131 Harbor Bay Parkway

Alameda, California 94502-6577

(510) 567-6765

INTRODUCTION

ETIC Engineering, Inc. (ETIC) has prepared this quarterly groundwater monitoring report for ExxonMobil Environmental Services Company on behalf of ExxonMobil Oil Corporation for former Exxon Retail Site 74121. This report presents the results for the most recent groundwater monitoring conducted at the site and summarizes recent site activities. This report covers site activities from 16 March 2010, the date of the previous monitoring event, until 2 August 2010, the date of the most recent quarterly monitoring event. Groundwater monitoring results, well construction details, and a groundwater monitoring plan are provided in the attached figures and tables. Groundwater monitoring protocols, field data, and analytical results are provided in the attached appendixes.

GENERAL SITE INFORMATION

Site name: Former Exxon Retail Site 74121

Site address: 10605 Foothill Boulevard, Oakland, California

Current property owner: MacArthur Boulevard Associates

Current site use: Landscaped area

Current phase of project: Groundwater monitoring

Tanks at site: Underground storage tanks removed in 1981 or 1982

Number of wells: 4 (4 onsite, 0 offsite)

GROUNDWATER MONITORING SUMMARY

Gauging and sampling date: 2 August 2010

Wells gauged and sampled: MW1, MW2, MW3, MW5

Wells gauged only:

Groundwater flow direction:

North

Groundwater gradient:

Well screens submerged:

None

Well screens not submerged: MW1, MW2, MW3, MW5
Liquid-phase hydrocarbons: Not observed or detected

Laboratory: Calscience Environmental Laboratories, Inc., Garden Grove,

California

Analyses performed:

- Total Petroleum Hydrocarbons as gasoline by EPA Method 8015B (M)
- Total Petroleum Hydrocarbons as diesel by EPA Method 8015B (M)
- Benzene, toluene, ethylbenzene, and xylenes by EPA Method 8021B
- Methyl tertiary butyl ether, ethyl tertiary butyl ether, tertiary amyl methyl ether, tertiary butyl alcohol, diisopropyl ether, 1,2-dibromoethane, and 1,2-dichloroethane by EPA Method 8260B

ADDITIONAL ACTIVITIES PERFORMED

The Alameda County Health Care Services Agency (ACHCSA) sent a letter dated 22 May 2009 approving the proposed remediation excavation for the site. Additionally, the ACHCSA requested that groundwater monitoring and sampling be reduced to semiannual.

Between 16 February and 4 March 2010 the remedial excavation of the former underground storage tank bed was performed. A report describing this event was submitted under separate cover.

A letter dated 22 July 2010 was received from the ACHCSA requesting a summary report that would either request case closure or recommend further action by 25 September 2010. The report will be submitted under separate cover.

WORK PROPOSED FOR NEXT QUARTER

Groundwater will be monitored according to the attached groundwater monitoring plan.

Attachments:


Figure 1: Site Map Showing Groundwater Elevations and Analytical Results

Table 1: Well Construction DetailsTable 2: Groundwater Monitoring DataTable 3: Groundwater Monitoring Plan

Appendix A: Field Protocols Appendix B: Field Documents

Appendix C: Laboratory Analytical Reports and Chain-of-Custody Documentation





ETICENGINEERING

FORMER EXXON RS 74121 10605 FOOTHILL BOULEVARD, OAKLAND, CALIFORNIA 2 AUGUST 2010



TABLE 1 WELL CONSTRUCTION DETAILS, FORMER EXXON RS 74121, 10605 FOOTHILL BOULEVARD, OAKLAND, CALIFORNIA

Well Number		Well Installation Date	Elevation TOC (feet)	Casing Material	Total Depth (feet)	Well Depth (feet)	Borehole Diameter (inches)	Casing Diameter (inches)	Screened Interval (feet)	Slot Size (inches)	Filter Pack Interval (feet)	Filter Pack Material
MW1	a	01/23/07	82.47	PVC	26.5	25	8	2	10 - 25	0.010	8 - 25	#2/12 Sand
MW2	a	01/23/07	84.40	PVC	26.5	25	8	2	10 - 25	0.010	8 - 25	#2/12 Sand
MW3	a	01/24/07	83.25	PVC	26.5	25	8	2	10 - 25	0.010	8 - 25	#2/12 Sand
MW5	a	01/23/07	82.65	PVC	26.5	25	8	2	10 - 25	0.010	8 - 25	#2/12 Sand
VW1	a	01/22/07		SS	6	6	6	0.25	5.25 - 5.75	0.0057	5 - 6	#2/12 Sand
VW2	a	01/22/07		SS	6	6	6	0.25	5.25 - 5.75	0.0057	5 - 6	#2/12 Sand
VW3	a	01/22/07		SS	6	6	6	0.25	5.25 - 5.75	0.0057	5 - 6	#2/12 Sand
VW4	a	01/22/07		SS	6	6	6	0.25	5.25 - 5.75	0.0057	5 - 6	#2/12 Sand
VW5	a	01/22/07		SS	6	6	6	0.25	5.25 - 5.75	0.0057	5 - 6	#2/12 Sand
VW6	b	03/23/09	7-	SS	6	6	6	0.25	5.25 - 5.75	0.0057	5 - 6	#2/12 Sand
VW7	С	03/23/09	***	SS	6	6	6	0.25	5.25 - 5.75	0.0057	5 - 6	#2/12 Sand
· VW8	С	03/23/09		SS	6	6	6	0.25	5.25 - 5.75	0.0057	5 - 6	#2/12 Sand
VW9	b	03/23/09	** =	SS	6	6	6	0.25	5.25 - 5.75	0.0057	5 - 6	#2/12 Sand
VW10	b	03/23/09		SS	6	6	6	0.25	5.25 - 5.75	0.0057	5 - 6	#2/12 Sand
VW11	b	03/23/09		SS	6	6	6	0.25	5.25 - 5.75	0.0057	5 - 6	#2/12 Sand
VW12	b	03/23/09		SS	6	6	6	0.25	5.25 - 5.75	0.0057	5 - 6	#2/12 Sand

TABLE 1 WELL CONSTRUCTION DETAILS, FORMER EXXON RS 74121, 10605 FOOTHILL BOULEVARD, OAKLAND, CALIFORNIA

	Well	Elevation		Total	Well	Borehole	Casing	Screened		Filter Pack	
Well	Installation	TOC	Casing	Depth	Depth	Diameter	Diameter	Interval	Slot Size	Interval	Filter Pack
Number	Date	(feet)	Material	(feet)	(feet)	(inches)	(inches)	(feet)	(inches)	(feet)	Material

131	a		

Well surveyed on 12 March 2007 by Morrow Surveying.
Well surveyed on 4 May 2009 by Morrow Surveying.
Well destroyed during remedial excavation.
Polyvinyl chloride.
Stainless steel.
Top of casing.

TABLE 2 GROUNDWATER MONITORING DATA, FORMER EXXON RETAIL SITE 74121, 10605 FOOTHILL BOULEVARD, OAKLAND, CALIFORNIA

		Top of Casing	Depth to	Groundwater	LPH			D.C.			Concen	tration (μg/L)					
Well ID	Date	Elevation (feet)	Water (feet)	Elevation (feet)	Thickness (feet)	Benzene	Toluene	Ethyl- benzene	Xylenes	TPH-g	TPH-d	MTBE	TBA	DIPE	ETBE	1,2-DCA	TAME	EDB
MWI	03/08/07	82.47	15.10	67.37	0.00	<1,00	1.21	<1.00	<3.00	440	119	1.91	<10.0	<0.500	<0.500	< 0.500	0.560	<0.500
MWI	06/08/07	82.47	16.47	66.00	0.00	< 0.50	< 0.50	< 0.50	< 0.50	127	<47.6	0.880	<10.0 ^{a,b}	< 0.500	< 0.500	< 0.500	< 0.500	< 0.500
MWI	09/06/07	82.47	17.47	65.00	0.00	< 0.50	< 0.50	< 0.50	< 0.50	78.0	<47.2	0.590	<10.0 ^{a,b}	< 0.500	< 0.500	< 0.500	< 0.500	< 0.500
MWI	12/03/07	82.47	18.10	64.37	0.00	<0.50	< 0.50	< 0.50	< 0.50	<50	<47	< 0.50	<20	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50
MWI	03/19/08	82.47	16.20	66.27	0.00	< 0.50	< 0.50	< 0.50	< 0.50	51.3	61°	3.08	<10.0	< 0.500	< 0.500	< 0.500	0.930	< 0.500
MWI	06/11/08	82.47	17.24	65.23	0.00	< 0.50	< 0.50	< 0.50	< 0.50	<50	<47	0.99	<20	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50
MWI	09/16/08	82.47	18.37	64.10	0.00	< 0.50	< 0.50	< 0.50	< 0.50	< 50	<47	< 0.50	<20	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50
MW1	12/01/08	82.47	18.85	63.62	0.00	< 0.50	< 0.50	< 0.50	< 0.50	<50	<47	< 0.50	<20	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50
MW1	03/12/09	82.47	16.92	65.55	0.00	< 0.50	< 0.50	< 0.50	<1.0	68	<50	0.80	<10	< 0.50	< 0.50	< 0.50	<0.50	< 0.50
MW1	08/12/09	82.47	18.50	63.97	0.00	< 0.50	< 0.50	< 0.50	<1.0	<50	<50	0.45 ^f	<10	< 0.50	< 0.50	< 0.50	0.13 ^f	< 0.50
MW1	03/16/10	82.47	16.77	65.70	0.00	< 0.50	< 0.50	< 0.50	<1.0	<50	<50	0.72	<10	< 0.50	< 0.50	< 0.50	0.15	< 0.50
MWI	08/02/10	82.47	17.06	65.41	0.00	<0.50	< 0.50	<0.50	<1.0	<50	<50	0.26 ^r	<10	<0.50	<0.50	< 0.50	<0.50	< 0.50
MW2	03/08/07	84.40	16.97	67.43	0.00	1.33	3.52	2.41	<3.00	1,620	550	<0.500	<10.0	<0.500	<0.500	<0.500	<0.500	< 0.500
MW2	06/08/07	84.40	18.34	66.06	0.00	21.8	2.45	0.66	< 0.50	2,120	395	< 0.500	10.0°	< 0.500	< 0.500	< 0.500	< 0.500	< 0.500
MW2	09/06/07	84.40	19.33	65.07	0.00	4.66	0.70	< 0.50	1.25	470	208	< 0.500	<10.0 ^{a,c}	< 0.500	< 0.500	< 0.500	< 0.500	< 0.500
MW2	12/03/07	84.40	19.97	64.43	0.00	22 ^d	< 0.50	< 0.50	< 0.50	560	120 ^e	< 0.50	<20	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50
MW2	03/19/08	84.40	18.07	66.33	0.00	5.33	< 0.50	< 0.50	0.82	630	200e	< 0.500	<10.0	< 0.500	< 0.500	< 0.500	<0.500	< 0.500
MW2	06/11/08	84.40	19.13	65.27	0.00	<0.50	< 0.50	< 0.50	< 0.50	430	110 ^e	<0.50	<20	< 0.50	< 0.50	<0.50	<0.50	<0.50
MW2	09/16/08	84.40	20.25	64.15	0.00	8.1 ^d	< 0.50	< 0.50	<0.50	230	63°	< 0.50			<0.50			
													<20	<0.50		<0.50	<0.50	<0.50
MW2	12/01/08	84.40	20.75	63.65	0.00	<0.50	<0.50	<0.50	<0.50	250	58 ^e	<0.50	<20	<0.50	<0.50	<0.50	< 0.50	< 0.50
MW2	03/12/09	84.40	18.85	65.55	0.00	< 0.50	<0.50	<0.50	0.75	940	<50	< 0.50	<10	< 0.50	< 0.50	< 0.50	<0.50	<0.50
MW2 MW2	08/12/09 03/16/10	84.40 84.40	20.43 18.68	63.97 65.72	0.00 0.00	<0.50 <0.50	<0.50 1.3	0.56 1.3	<1.0 <1.0	500 520	<50 <50	<0.50 <0.50	<10 <10	<0.50 <0.50	<0.50 <0.50	<0.50 <0.50	<0.50 <0.50	<0.50 <0.50
MW2	08/02/10	84.40	18.99	65.41	0.00	<0.50	<0.50	<0.50	<1.0	720 ^h	<50	<0.50	<10	<0.50	<0.50			
						~0.50	~0.50	~0.50	~1.0	120	>30	~0.50	~10	~0.30	~0.50	<0.50	<0.50	<0.50
MW3	03/08/07	83.25	15.49	67.76	0.00	<1.00	<1.00	<1.00	<3.00	<100	52.9	< 0.500	<10.0	< 0.500	< 0.500	< 0.500	< 0.500	< 0.500
MW3	06/08/07	83.25	17.02	66.23	0.00	< 0.50	<0.50	< 0.50	< 0.50	<50.0	<47.6	< 0.500	$<10.0^{a,b}$	<0.500	< 0.500	< 0.500	< 0.500	< 0.500
MW3	09/06/07	83.25	18.07	65.18	0.00	< 0.50	< 0.50	< 0.50	< 0.50	<50.0	<47.2	< 0.500	<10.0 ^{a,b}	< 0.500	< 0.500	< 0.500	< 0.500	< 0.500
MW3	12/03/07	83.25	18.69	64.56	0.00	< 0.50	< 0.50	< 0.50	< 0.50	<50	<47	< 0.50	<20	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50
MW3	03/19/08	83.25	16.79	66.46	0.00	<0.50	< 0.50	< 0.50	< 0.50	<50.0	<47	< 0.500	<10.0	< 0.500	<0.500	< 0.500	< 0.500	< 0.500
MW3	06/11/08	83.25	17.82	65.43	0.00	<0.50	<0.50	<0.50	<0.50	<50	<47	<0.50	<20	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50
MW3 MW3	09/16/08 12/01/08	83.25 83.25	18.99 19.46	64.26 63.79	0.00	<0.50 <0.50	< 0.50	<0.50	<0.50	<50	<47	< 0.50	<20	<0.50	< 0.50	< 0.50	< 0.50	<0.50
MW3	03/12/09	83.25	17.53	65.72	0.00	<0.50	<0.50 <0.50	<0.50 <0.50	<0.50 <1,0	<50 <50	<47 <50	<0.50 <0.50	<20 <10	<0.50 <0.50	<0.50 <0.50	<0.50 <0.50	<0.50 <0.50	< 0.50
MW3	08/12/09	83.25	19.11	64.14	0.00	<0.50	<0.50	<0.50	<1.0	<50	<50	< 0.50	<10	< 0.50	<0.50	< 0.50	<0.50	<0.50 <0.50
MW3	03/16/10	83.25	17.40	65.85	0.00	< 0.50	<0.50	< 0.50	<1.0	<50	<50	<0.50	<10	< 0.50	< 0.50	< 0.50	< 0.50	<0.50
MW3	08/02/10	83.25	17.75	65.50	0.00	<0.50	<0.50	<0.50	<1.0	<50	<50	<0.50	<10	<0.50	<0.50	<0.50	<0.50	<0.50
MW5	03/08/07	82.65	14.31	68.34	0.00	<1.00	<1.00	<1.00	<3.00	187	59.2	<0.500	<10.0	< 0.500	<0.500	<0.500	< 0.500	<0.500
MW5	06/08/07	82.65	16.64	66.01	0.00	4.38	0.72	< 0.50	< 0.50	780	90.3	< 0.500	<10.0 ^{a,b}	< 0.500	<0.500	< 0.500	< 0.500	< 0.500
MW5	09/06/07	82.65	17.62	65.03	0.00	< 0.50	< 0.50	< 0.50	< 0.50	<50.0	121	< 0.500	<10.0 ^{a,b}	< 0.500	< 0.500	< 0.500	< 0.500	< 0.500
MW5	12/03/07	82.65	18.27	64.38	0.00	<0.50	<0.50	< 0.50	<0.50	100	65°	<0.50	<20	<0.50	<0.50	<0.50	<0.50	<0.50

TABLE 2 GROUNDWATER MONITORING DATA, FORMER EXXON RETAIL SITE 74121, 10605 FOOTHILL BOULEVARD, OAKLAND, CALIFORNIA

		Top of Casing	Depth to	Groundwater	LPH						Concent	tration (µg/L)						
Well ID	Date	Elevation (feet)	Water (feet)	Elevation (feet)	Thickness (feet)	Benzene	Toluene	Ethyl- benzene	Xylenes	ТРН-д	TPH-d	МТВЕ	TBA	DIPE	ЕТВЕ	1,2-DCA	TAME	ÉDB
MW5	03/19/08	82.65	16.37	66.28	0.00	0.69	<0.50	<0.50	0.87	237	110°	<0.500	<10.0	<0.500	<0.500	<0.500	<0.500	<0.500
MW5	06/11/08	82.65	17.40	65.25	0.00	< 0.50	< 0.50	< 0.50	0.65	83	77°	< 0.50	<20	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50
MW5	09/16/08	82.65	18.54	64.11	0.00	< 0.50	< 0.50	< 0.50	< 0.50	120	<47	< 0.50	<20	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50
MW5	12/01/08	82.65	19.00	63.65	0.00	< 0.50	< 0.50	< 0.50	< 0.50	140	<47	< 0.50	<20	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50
MW5	03/12/09	82.65	17.09	65.56	0.00	0.21	< 0.50	< 0.50	0.85 ^f	410	<50	< 0.50	<10	< 0.50	< 0.50	< 0.50	< 0.50	0.19 ^f
MW5	08/12/09	82.65	18.71	63.94	0.00	0.55 ^g	< 0.50	< 0.50	<1.0	110	<50	< 0.50	<10	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50
MW5	03/26/10	82.65	16.96	65.69	0.00	<0.50	0.46 ^f	0.42 ^f	<1.0	210	<50	< 0.50	<10	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50
MW5	08/02/10	82.65	17.30	65.35	0.00	<0.50	< 0.50	<0.50	<1.0	290 ^h	<50	< 0.50	<10	< 0.50	<0.50	< 0.50	< 0.50	<0.50

Notes: MTBE analyzed by EPA Method 8260B unless otherwise indicated.

Calibration verification recovery was above the method control limit for this analyte. Analyte not detected, data not impacted.

Laboratory control sample and/or laboratory control sample duplicate recovery was above the acceptance limits. Analyte not detected, data not impacted.

Initial analysis within holding time, Reanalysis for the required dilution or confirmation was past holding time. С

The relative percent difference between the primary and confirmatory analysis exceeded 40%. Per EPA Method 8000B, the higher value was reported. d

Does not match typical pattern. e

Analyte was detected at a concentration below the reporting limit and above the laboratory method detection limit. Reported value is estimated.

Analyte presence was not confirmed by second column or GC/MS analysis. g

The sample chromatographic pattern for TPH does not match the chromatographic pattern of the specified standard. Quantitation of the unknown hydrocarbon(s) in the sample was based upon the specified standard.

1.2-DCA 1.2-Dichloroethane.

DIPE Diisopropyl ether.

EDB 1.2-Dibromoethane.

ETBE Ethyl tertiary butyl ether.

MTBE Methyl tertiary butyl ether.

TAME Tertiary amyl methyl ether.

TBA Tertiary butyl alcohol.

TPH-d Total Petroleum Hydrocarbons as diesel analyzed by EPA Method 8015B.

TPH-g Total Petroleum Hydrocarbons as gasoline analyzed by EPA Method 8015B.

μg/L Micrograms per liter.

TABLE 3 GROUNDWATER MONITORING PLAN, FORMER EXXON RS 74121, 10605 FOOTHILL BOULEVARD, OAKLAND, CALIFORNIA

	Groundwater	Groundwater	Sampling and Analy	sis Frequency
Well	Gauging	TPH-g, TPH-d, and		Other Oxygenates
Number	Frequency	BTEX	MTBE	and Additives
MW1	SA	SA	SA	SA
MW2	SA	SA	SA	SA
MW3	SA	SA	SA	SA
MW5	SA	SA	SA	SA
Notes:		es include diisopropyl ether, ter r, 1,2-dibromoethane, and 1,2-d		tertiary amyl methyl ether,
BTEX	Benzene, toluene, ethyli	benzene, and xylenes.		
MTBE	Methyl tertiary butyl eth	ner.		
SA	Semiannually (during th	ne first and third quarters).		
TPH-g	Total Petroleum Hydrod	carbons as gasoline.		
TPH-d	Total Petroleum Hydrod	earbons as diesel.		

Appendix A

Field Protocols

PROTOCOLS FOR QUARTERLY GROUNDWATER MONITORING

GROUNDWATER GAUGING

Wells are opened prior to gauging to allow the groundwater level in the wells to equilibrate with atmospheric pressure. The depth to groundwater and depth to liquid-phase hydrocarbons, if present, are then measured to the nearest 0.01 feet using an electronic water level meter or optical interface probe. The measurements are made from a permanent reference point at the top of the well casing. If less than 1 foot of water is measured in a well, the water is bailed from the well and, if the well does not recover, the well is considered "functionally dry." Wells with a sheen or measurable liquid-phase hydrocarbons are generally not purged or sampled.

WELL PURGING

After the wells are gauged, each well is purged of approximately 3 well casing volumes of water to provide representative groundwater samples for analysis. Field parameters of pH, temperature, and electrical conductance are measured during purging to ensure that these parameters have stabilized before groundwater in a well is sampled. Groundwater in each well is purged using an inertial pump (WaTerra), an electric submersible pump, or a bailer. After the well is purged, the water level is checked to ensure that the well has recharged to at least 80 percent of its original water level.

GROUNDWATER SAMPLING

After purging, groundwater in each well is sampled using dedicated tubing and an inertial pump (WaTerra) or a factory-cleaned disposable bailer. Samples from extraction wells are typically collected from sample ports associated with the groundwater remediation system. Samples collected for volatile organic analysis are placed in Teflon septum-sealed 40-milliliter glass vials. Samples collected for diesel analysis are placed in 1-liter amber glass bottles. Each sample bottle is labeled with the site name, well number, date, sampler's initials, and preservative. The samples are placed in a cooler with ice for delivery to a state-certified laboratory. The information for each sample is entered on a chain-of-custody form prior to transport to the laboratory.

Appendix B Field Documents



MONITORING WELL DATA FORM

Client: Former	Exxon 74121				Date: 🐠 - ৫고	-10			
Project Number:	UP4121.1.6			Parameter Communication of the	Station Number	: 74121			
Site Location: 10605 Foothil	l Boulevard, C	Dakland, CA			Samplers: ALEX				
MONITORING WELL NUMBER	DEPTH TO WATER (TOC)FT.	DEPTH TO PRODUCT (TOC)FT.	APPARENT PRODUCT THICKNESS (FT.)	AMOUNT OF PRODUCT REMOVED(L)	MONITORING WELL INTEGRITY	DEPTH TO BOTTOM (TOC)	WELL CASING DIAMETER		
MW1	17.00	1,2,4,4				24.00	2/		
MW2	18-99					24:72	2//		
MW3	17:75					23.55	20		
MW5	17-80					25.40	211		

ETIC

GROUNDWATER PURGE AND SAMPLE FORM

Project Name:	Exxon 74121			Well No: Mari	Date:	e8 -e2-1e
Project No:	UP4121.1.6			Personnel: AM		-
GAUGING DAT		WLM) / IP		Measuring Point D	escription: TOC	
WELL PÜRGE VOLUME	Total Depth (feet)	Depth to Water (feet)	Water Column (feet)	Multiplier for Casing Diameter	Casing Volume (gal)	Total Purge Volume (gal)
CALCULATION	24.00	17.06	6.94	1 2 4 6 0.04 0.16 0.64 1.44	<i>111</i>	\$33
PURGING DAT Purge Method:	A WATERRA/BAI	LER / SUB	1.000.00	Purç	ge Rate:	GPM
Time	1021	1024 j	1027			
Volume Purge (gal)	1.5	3	4.5			
Temperature (C)	18-3	18-6	/8-7			
рН	6.67	6.89	7.02			***************************************
Spec.Cond.(umhos		1849	1342			
Turbidity/Color	LOW /BAN	sind Jekn	SIA PRO			***************************************
Odor (Y/N)	N	₹W.	N			
Casing Volumes	1	2	3			
Dewatered (Y/N)	N	~	Å			
Comments/Obse	rvations:					
SAMPLING DA	TA			LULUMANANANANANANANANANANANANANANANANANANAN		
Time Sampled:	na pis	5	Approximate Dept	h to Water During Sa	mpling:	(feet)
Comments:						·····
					29-92 (2009) 3 mg/V 2009-2015	researe a Steen Liberary on a notice of
Sample Number	Number of Containers	Container Type	Preservative	Volume Filled (mL or L)	Turbiditý/, Color	Analysis Method
Muj	. 89	Voa	HCL	40 ml		TPH-g, BTEX, MTBE
Mui	2	AMBERS	NONE	1L		TPH-D
Total Purge Vo	et.	(gallons)		Disposal:	SYSTEM	
Weather Condi	tions.		· · · · · · · · · · · · · · · · · · ·		BOLTS	75 / N
	***************************************	g at Time of Samp	oling: 4C		CAP & LOCK	(2) / N
	ditions Requiring		A 4 31 30	,	GROUT	20 / N
**************************************	ountered During P	urging and Sampl	ing:		WELL BOX. (Y) / N Y) / N
Comments:	ant7417110hEnlChi Ben Field C	islder(174121 OAOC victSheet)	***************************************		OLOUNED (۱۱۱ س

ETIC

Engineering, Inc.

GROUNDWATER PURGE AND SAMPLE FORM

Project Name:	Exxon 74121			Well No: Mks Z	Date:	68 +2-16
Project No:	UP4121.1.6			Personnel: AUX		
GAUGING DAT Water Level Me	A asuring Method: (WLW / IP		Measuring Point D	escription: TOC	
WELL PURGE VOLUME	Total Depth (feet)	Depth to Water (feet)	Water Column (feet)	Multiplier for Casing Diameter	Casing Volume (gal)	Total Purge Volume (gal)
CALCULATION	24-72	18-907	5-73	1 2 4 6 0.04 0.16 0.64 1.44	.91	2.75
PURGING DAT Purge Method:	A WATERRA/BA	ILER / SUB		Pur	ge Rate:	GPM
Time	1043	1046	1049			
Volume Purge (gal)	/	2	3			
Temperature (C)	18-4	/8-5	J&-3			
рН	6.89	6.97	7.06			
Spec.Cond.(umhos	1	/2/0	1199			
Turbidity/Color	STEAM / JEEN	STUTO / APPLA	CIUTO /ZHO			
Odor (Y/N)	N	N	N			
Casing Volumes	1	2	3			
Dewatered (Y/N)	N	N	N			
Comments/Obse	rvations:			<u> </u>		

SAMPLING DA	TA qua	.29				
Time Sampled:	///	O	Approximate Dept	h to Water During Sa	mpling:	(feet)
Comments:	***************************************					
Sample Number	Number of Containers	Container Type	Preservative	Volume Filled (mL or L)	Turbidity/ Color	Analysis Method
Mu 2	89	Voa	HCL	40 ml		TPH-g, BTEX, MTBE
paw Z	2	AMBERS	NONE	1L		TPH-D

Total Purge Vo	lume: 🕉	(gallons)		Disposal:	SYSTEM	
Weather Condi	40.4	7			BOLTS (R / N
	ell Box and Casing	g at Time of Samp	oling: 🕊		CAP & LOCK	7) / N
	ditions Requiring		nent		GROUT (<u> </u>
Problems Enco	untered During Po	urging and Sampli	ing: WW		WELL BOX.	2 / N
Comments:	es 74121 (Public)OM Pre-Field F				SECURED (Ŷ) / N



GROUNDWATER PURGE AND SAMPLE FORM

Date: & & 2 -/ c MUS Project Name: Exxon 74121 Well No: Project No: UP4121.1.6 Personnel: ALIX **GAUGING DATA** Water Level Measuring Method: ΙP Measuring Point Description: TOC Total Depth Depth to Water Water Column Multiplier for Casing Volume Total Purge WELL PURGE Casing Diameter Volume (gal) (feet) (feet) (feet) (gal) VOLUME CALCULATION 92 $\sqrt{2}$ 23.55 5.80 6 17-75 2.78 0.04 0.16 0.64 **PURGING DATA** WAJERRA / BAILER / SUB Purge Rate: **GPM** Purge Method: 77553 11**5%** 1159 Time 2 Volume Purge (gal) -3 18.2 Temperature (C) 18.9 17-9 7.02 7.07 рΗ 7-09 1604 1607 1632 Spec:Cond (umhos) SWOJERN SYUND/ BEN CHAM /BEAN Turbidity/Color N N Odor (Y/N) Casing Volumes 1 2 3 N Dewatered (Y/N) Comments/Observations: **SAMPLING DATA** 1210 Approximate Depth to Water During Sampling: (feet) Time Sampled: Comments: Volume Filled Number of Turbidity/ Color Analysis Method Container Type Sample Number Preservative Containers (mL or L) MUB Voa HCL 40 ml 9 TPH-g, BTEX, MTBE MUB NONE **AMBERS** 2 1L TPH-D 3 Total Purge Volume: (gallons) Disposal: SYSTEM K **BOLTS** Weather Conditions: Ν Condition of Well Box and Casing at Time of Sampling. CAP & LOCK Ν Well Head Conditions Requiring Correction: **GROUT** Ν Problems Encountered During Purging and Sampling: WELL BOX. N SECURED Ν Comments:

G.\Projects\ExxonMobit\Sites\7412\\Publie\QM\Pre-Field\Folder\\7412\\Purge\Form\x\is\Sheet1




GROUNDWATER PURGE AND SAMPLE FORM

Engineering, Inc.							
Project Name:	Exxon 74121		V	Vell No:	Neus	Date: 9	18-02-16
Project No:	UP4121.1.6		ļ-	Personnel:	ALX		
GAUGING DATA					Date: 5	aviation. TOO	
Water Level Mea	asuring Method:	MINT / IP	Name of the second of the seco	vieasuring	Point Des	scription: TOC	PARCONNE MORESTANIO
WELL PURGE VOLUME	Total Depth (feet)	Depth to Water (feet)	Water Column (feet)	Multipli Casing D		Casing Volume (gal)	Total Purge Volume (gal)
CALCULATION	25.40	17:30	3./6	1 (2) 0.04 0.16	4 6 0.64 1.44	1-29	3.28
PURGING DATA	A						
Purge Method:	WAZERBA / BAIL	ER / SUB			Purg	e Rate:	GPM
Time	1115	1118	1121				
Volume Purge (gal)	1.5	હ	45	WELLOWING THE TOTAL THE TO			
Temperature (C)	18-5	18-3	18 14				, ,
pH	6.98	7.01	7*5				
Spec Cond (umhos	18	1177	1192				
Turbidity/Color	SIMO /BIN	SIMS/BFW	STOP JEPO				
Odor (Y/N)	N	N	N				
Casing Volumes	1	2	3				
Dewatered (Y/N) »	N	N	· N				
Comments/Obse	rvations:						
SAMPLING DA	TA A	12=				8¢	
Time Sampled:		135	Approximate Depth	to Water I	During Sam	npling:	(feet)
Comments:							
Sample Number	Number of Containers	Container Type	Preservative		e Filled or L)	Turbidity/ Color	Analysis Method
MW5	89	Voa	HCL	\$ \$ 1.5% (Math. 550) \$	ml		TPH-g, BTEX, MTBE
MUS	2	AMBERS	NONE		L		TPH-D
Total Purge Vo		(gallons)		Disposal:		SYSTEM	<u> </u>
Weather Cond			- A-A	***************************************		BOLTS (Y/ N
	ell Box and Casing		ling: CL puhe			CAP & LOCK (Y) / N
	nditions Requiring C		SA & Mage			GROUT (Y/N
Problems Enco	ountered During Pu	rging and Sampli	ng:			WELL BOX. (Y D N
G:\Projects\ExxonMobil\Si	tes\74121\Public\QM Pro-Field Fol	dcr\[74121 Purge Form,xls She	ed!			the time to the state of	

Appendix C

Laboratory Analytical Reports and Chain-of-Custody Documentation





August 10, 2010

Erik Appel ETIC Engineering, Inc. 2285 Morello Avenue Pleasant Hill, CA 94523-1850

Subject: Calscience Work Order No.: 10-08-0095

> Client Reference: ExxonMobil 74121, 10605 Foothill Blvd.,

> > Oakland, CA

Dear Client:

Enclosed is an analytical report for the above-referenced project. The samples included in this report were received 8/3/2010 and analyzed in accordance with the attached chain-of-custody.

Calscience Environmental Laboratories certifies that the test results provided in this report meet all NELAC requirements for parameters for which accreditation is required or available. Any exceptions to NELAC requirements are noted in the case narrative. The original report of subcontracted analysis, if any, is provided herein, and follows the standard Calscience data package. The results in this analytical report are limited to the samples tested and any reproduction thereof must be made in its entirety.


Note that the Chain-of-Custody Record and Sample Receipt Form are integral parts of this report.

If you have any questions regarding this report, please do not hesitate to contact the undersigned.

Sincerely,

Pecill & ex Soin

Calscience Environmental Laboratories, Inc. Cecile deGuia Project Manager





ETIC Engineering, Inc. 2285 Morello Avenue Pleasant Hill. CA 94523-1850

Date Received: Work Order No:

08/03/10 10-08-0095

Preparation: Method:

EPA 3510C EPA 8015B (M)

Project: ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA

Page 1 of 2

Client Sample Number		Lab Samp Number	Lab Sample Number		Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW1	Language of the control of the contr	10-08-00	10-08-0095-1-J		Aqueous	Section of the sectio	08/05/10	08/07/10 03:19	100805B13
Comment(s): -The sample ex	xtract was subjected t	o Silica Gel treatr	nent prio	r to analysis.					
-Results were	evaluated to the MDL,	concentrations >	= to the I	MDL but < RI	_, if found, a	e qualified with	n a "J" flag.		
<u>Parameter</u>	Result	RL	MDL		DF	Qual	<u>Units</u>		
TPH as Diesel	ND ·	50	47	1		U	ug/L		
Surrogates:	<u>REC (%)</u>	Control Limits	MDL			Qual	. .		
Decachlorobiphenyl	100	68-140							
MW2	And Annual Annua	10-08-00	95-2-J	08/02/10 11:00	Aqueous	GC 27	08/05/10	08/07/10 03:37	100805B13
Comment(s): -The sample ex	xtract was subjected t	o Silica Gel treatn	nent prio	r to analysis.					The state of the s
-Results were	evaluated to the MDL,	concentrations >	= to the I	MDL but < RI	_, if found, a	e qualified with	n a "J" flag.		
<u>Parameter</u>	Result	RL	MDL		DF.	Qual	Units		

TPH as Diesel ND 50 47 ug/L Surrogates: **MDL REC (%)** Control Limits Qual

Decachlorobiphenyl 95 68-140

MW3 10-08-0095-3-J 08/02/10 Aqueous GC 27 08/05/10 08/07/10 100805B13
The state of the control of the cont

Comment(s): -The sample extract was subjected to Silica Gel treatment prior to analysis.

-Results were evaluated to the MDL, concentrations >= to the MDL but < RL, if found, are qualified with a "J" flag.

<u>Parameter</u> Result RL MDL DF <u>Qual</u> <u>Units</u> TPH as Diesel ND 50 47 ug/L

Surrogates: **REC (%)** Control Limits MDL Qual

Decachiorobiphenyl 98 68-140


MW5 (2014) (2014	10-08-0095-4-J 08/02/10 Aqueous GC 27 08/05/10 08/07/10	
	10-08-0095-4-J 08/02/10 Aqueous GC 27 08/05/10 08/07/10	100805B13
	11:35 04:14	

Comment(s): -The sample extract was subjected to Silica Gel treatment prior to analysis.

-Results were evaluated to the MDL, concentrations >= to the MDL but < RL, if found, are qualified with a "J" flag. Result RL DF


MDL Qual <u>Units</u> TPH as Diesel ND 50 47 Ü ug/L Surrogates: REC (%) Control Limits **MDL** Qual

Decachlorobiphenyl 98 68-140



Parameter

DF - Dilution Factor Qual - Qualifiers





ETIC Engineering, Inc. 2285 Morello Avenue

Pleasant Hill, CA 94523-1850

Date Received:

Work Order No:

Preparation:

Method:

08/03/10

10-08-0095

EPA 3510C

EPA 8015B (M)

Project: ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA

Page 2 of 2


Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
Method Blank	099-12-330-1,61	6 NA	Aqueous	GC 27	08/05/10	08/07/10 02:26	100805B13

Comment(s): -Results were evaluated to the MDL, concentrations >= to the MDL but < RL, if found, are qualified with a "J" flag. <u>Parameter</u> Result RLQual <u>MDL</u> DF <u>Units</u>

TPH as Diesel ND 50 47 1 U ug/L

Surrogates: REC (%) Control Limits MDL Qual

Decachlorobiphenyl 95 68-140





ETIC Engineering, Inc. 2285 Morello Avenue Pleasant Hill, CA 94523-1850 Date Received: Work Order No: Preparation: Method: 08/03/10 10-08-0095 EPA 5030B EPA 8015B (M)

Project: ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA

Page 1 of 2

Client Sample Number		Lab Samp Number		Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW1		10-08-00	95-1-E	08/02/10 10:35	Aqueous	GC 42	08/05/10	08/05/10 13:01	100805B01
-Comment(s): -Results were ev	aluated to the MDL,	concentrations >	= to the I	MDL but < RL	, if found, ar	e qualified with	ı a "J" flag.		
Parameter	Result	<u>RL</u>	MDL	j	<u>DE</u>	Qual	<u>Units</u>		
ΓPH as Gasoline	ND	50	48	1	1	J	ug/L		
urrogates:	REC (%)	Control Limits	MDL			Qual			
,4-Bromofluorobenzene	92	38-134							
MW2		10-08-00	95-2-E	08/02/10 11:00	Aqueous	GC 42	08/05/10	08/05/10 13:38	100805B01
	omatographic patter ne unknown hydroca valuated to the MDL,	arbon(s) in the sar	nple was	based upon	the specified	standard.		d.	

TPH as Gasoline 720 50 48 1 ug/L

Surrogates: REC (%) Control Limits MDL Qual

1,4-Bromofluorobenzene 98 38-134

MW3	the state of the s	Company of the Compan	95-3-E	08/02/10 Aqueo 12:10	us GC 42	08/05/10	08/05/10 100805B01 14:15
Comment(s): -Results were ev	aluated to the MDL,	concentrations >	= to the M	DL but < RL, if foun	d, are qualified v	with a "J" flag.	
<u>Parameter</u>	Result	<u>RL</u>	MDL	<u>DF</u>	Qual	<u>Units</u>	
TPH as Gasoline Surrogates:	ND <u>REC (%)</u>	50 Control Limits	48 <u>MDL</u>	1	U <u>Qual</u>	ug/L	
1,4-Bromofluorobenzene	93	38-134					
MW5	Company Company of the Company of	10-08-00	9 5-4-E	08/02/10 Aqueo 11:35	us GC 42	08/05/10	08/05/10 100805B01 14:51


Comment(s): -The sample chromatographic pattern for TPH does not match the chromatographic pattern of the specified standard.

Quantitation of the unknown hydrocarbon(s) in the sample was based upon the specified standard.

-Results were evaluated to the MDL, concentrations >= to the MDL but < RL, if found, are qualified with a "J" flag.

Parameter Result DF RL MDL Qual <u>Units</u> TPH as Gasoline 290 50 48 ug/L Surrogates: **REC (%)** Control Limits **MDL** Qual

1,4-Bromofluorobenzene 96 38-134



DF - Dilution Factor ,

Qual - Qualifiers





ETIC Engineering, Inc. 2285 Morello Avenue

Pleasant Hill, CA 94523-1850

Date Received: Work Order No: Preparation:

Method:

08/03/10 10-08-0095 EPA 5030B EPA 8015B (M)

Project: ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA

Page 2 of 2

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW5	10-08-0095-4-E	08/02/10 11:35	Aqueous	GC 42	08/05/10	08/05/10 14:51	100805B01


Comment(s): -The sample chromatographic pattern for TPH does not match the chromatographic pattern of the specified standard. Quantitation of the unknown hydrocarbon(s) in the sample was based upon the specified standard.


-Results were evaluated to the MDL, concentrations >= to the MDL but < RL, if found, are qualified with a "J" flag.

<u>Parameter</u> Result RL <u>MDL</u> Qual <u>Units</u> TPH as Gasoline 290 50 48 ug/L Surrogates: **REC (%) Control Limits** <u>MDL</u> Qual

1,4-Bromofluorobenzene 96 38-134

Method Blank	### Company of the Co	099-12-4	36-5,065		us GC 42	08/05/10	08/05/10 100805B01 06:19
Comment(s): -Results were ev	aluated to the MDL	concentrations >	= to the MC	DL but < RL, if found	d, are qualified v	vith a "J" flag.	
<u>Parameter</u>	Result	RL	<u>MDL</u>	<u>DF</u>	Qual	<u>Units</u>	
TPH as Gasoline Surrogates:	ND REC (%)	50 Control Limits	48 <u>MDL</u>	1	U <u>Qual</u>	ug/L	
1,4-Bromofluorobenzene	94	38-134		•			








ETIC Engineering, Inc. Date Received: 08/03/10 2285 Morello Avenue Work Order No: 10-08-0095 Pleasant Hill, CA 94523-1850 Preparation: EPA 5030B Method: EPA 8021B Units: ug/L

Project: EvyonMobil 74121 10605 Eastbill Plyd Oakland CA

Project: Exx	nMobil 741	21, 106	05 Foo	thill Bl	vd., (Daklar	id, CA					Page	1 of	2
Client Sample Num	ber			Lab S Nun	•		Date/Time Collected	Matrix	Instrument	Da Prepa		Date/Time Analyzed	QC Ba	tch ID
MW1 State Control Cont		And the second s		10-08	3-0095-1-D 08/02/10 Aqueous GC 8 08/04/10 10:35		/10	08/04/10 13:57	100804	IB01				
Comment(s): -	Results were ev	aluated to th	ne MDL, c	oncentral	ions >=	to the N	IDL but < RL,	if found, a	re qualified w	ith a "J" fla	ag.			
<u>Parameter</u>		Result	<u>RL</u>	MDL	DF	Qual	<u>Parameter</u>			Result	RL	MDL	DF	Qual
Benzene		ND	0.50	0.14	1	U	Ethylbenzen			ND	0.50	0.17	1	U
Toluene		ND	0.50	0.17	1	U	Xylenes (tota	al)		ND	1.0	0.26	1	U
Surrogates:		REC (%)	Control Limits	Qu	<u>al</u>									
1,4-Bromofluorober	nzene	88	70-130											
MW2		agenty A Stringerick Con- graphy A Stringerick Con- graphy A Stringerick Con-		10-08	-0095-2	2-D	08/02/10 11:00	Aqueous	GC 8	08/04	/10	08/04/10 15:30	100804	IB01
Comment(s):	Results were ev	aluated to th	e MDL c	oncentral	ions >=	to the N	MDI hut < RI	if found a	re qualified wi	tha" l" fla	201		An annual Control of Control	1 NO. 1001 NO. 10
Parameter	TOOLING WOLCOV	Result	RL	MDL	DF	Qual	Parameter	ii iodilo, a	ie quaimed wi	Result	RL	MDL	DF	Qual
Benzene		ND	0.50	0.14	1	U	Ethylbenzen	e		ND	0.50	***************************************	1	U
Toluene		ND	0.50	0.17	1	Ū	Xylenes (tota			ND	1.0	0.26	1	Ü
Surrogates:		REC (%)	Control Limits	<u>Qu</u>	<u>al</u>									
1,4-Bromofluorober	nzene	87	70-130											
MW3	1			10-08	-0095-3	3-D	08/02/10 12:10	Aqueous	GC 8	08/04	/10	08/04/10 16:02	100804	IB01
Comment(s):	Results were ev	aluated to th	ne MDL. c	oncentral	ions >=	to the N	ADL but < RL	if found a	re qualified wi	th a "J" fla	30	***************************************		
Parameter		Result	RL .	MDL	DF	Qual	Parameter			Result	<u>RL</u>	MDL	DF	Qual
Benzene		ND	0.50	0.14	1	U	Ethylbenzen	е		ND	0.50	***************************************	1	U
Toluene		ND	0.50	0.17	1	U	Xylenes (tota	al)		ND	1.0	0.26	1	U
Surrogates:		REC (%)		<u>Qu</u>	<u>al</u>									
1,4-Bromofluorober	nzene	88	<u>Limits</u> 70-130											
MW5	A control to grade to grade to grade to the control to grade to the control to grade to the control to grade to			10-08	-0095-4	4-D	08/02/10 11:35	Aqueous	GC 8	08/04	/10	08/04/10 16:32	100804	IB01
Comment(s):	Results were ev	aluated to th	ne MDL, c	oncentral	ions >=	to the N	IDL but < RL,	if found, a	re qualified wi	th a "J" fla	ag.			
<u>Parameter</u>		Result	RL	MDL	DF	Qual	<u>Parameter</u>	•	•	Result	<u>RL</u>	MDL	<u>DF</u>	Qual
Benzene		ND	0.50	0.14	1	U	Ethylbenzen	е		ND	0.50	0.17	1	Ū
Toluene		ND	0.50	0.17	1	U	Xylenes (tota			ND	1.0	0.26	1	U
Surrogates:		REC (%)	Control	Qu	<u>al</u>									



1,4-Bromofluorobenzene


DF - Dilution Factor

<u>Limits</u>

70-130

88

Qual - Qualifiers





ETIC Engineering, Inc. 2285 Morello Avenue

Pleasant Hill, CA 94523-1850

Date Received:

Units:

08/03/10


Work Order No: 10-08-0095 Preparation: EPA 5030B

Method: EPA 8021B

ug/L

Project: ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA Page 2 of 2

, , o j o o c . = , o , o , o , o , o , o , o , o , o ,					<i></i>	14, 071					raye	7 Z. UI	_
Client Sample Number			Lab Sa Num	, ,		Date/Time Collected	Matrix	Instrument	Dat Prepa		Date/Time Analyzed	QC Ba	tch ID
Method Blank	A CONTROL OF THE CONT		099-12			N/A	Aqueous	GC 8	08/04	/10	08/04/10 12:54	100804	IB01
Comment(s): -Results were ev	aluated to th	ne MDL, c	oncentrati	ons >=	to the !	MDL but < RL,	if found, are	e qualified wi	h a "J" fla	ıg.			
Parameter	Result	<u>RL</u>	MDL.	DE	Qual	<u>Parameter</u>			Result	RL	MDL	<u>DF</u>	Qual
Benzene	ND	0.50	0.14	1	U	Ethylbenzen	е		ND	0.50	0.17	1	U
Toluene	ND	0.50	0.17	1	U	Xylenes (tota	al)		ND	1.0	0.26	1	U
Surrogates:	REC (%)	Control Limits	Qua	<u>al</u>									
1,4-Bromofluorobenzene	91	70-130											






ETIC Engineering, Inc. Date Received: 08/03/10 2285 Morello Avenue Work Order No: 10-08-0095 Pleasant Hill, CA 94523-1850 Preparation: EPA 5030B Method: EPA 8260B Units: ug/L

Project: ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA


Page 1 of 2

Tioject. Exxonition 7-	7 L. 1, 1000	· · · · · ·	U 1111 LJ1	v , \	20111Q1	iu, un					rage	I OI.	<u>_</u>
Client Sample Number		***	Lab S Nun	ample nber		Date/Time Collected	Matrix	Instrument	Date Prepa		te/Time alyzed	QC Bat	ch ID
MW1	STATE OF THE PROPERTY OF THE P	AND	10-08	-0095-1	I-A	08/02/10 10:35	Aqueous	GC/MS L	08/03/		/04/10 06:32	100803	L02
Comment(s): -Results were	evaluated to the	MDL, c	oncentrat	ions >=	to the N	MDL but < RL	, if found, are	qualified wi	th a "J" flaç) .			
<u>Parameter</u>	<u>Result</u>	RL.	MDL	DF	Qual	<u>Parameter</u>			Result	RL	MDL	DF	Qual
1,2-Dibromoethane	ND	0.50	0.23	1	U	Diisopropyl	Ether (DIPE))	ND	0.50	0.12	1	U
1,2-Dichloroethane	ND	0.50	0.075	1	U		l Ether (ETB		ND	0.50	0.25	1	Ū
Methyl-t-Butyl Ether (MTBE)	0.26	0.50	0.14	1	J		lethyl Ether (,	ND	0.50	0.12	1	Ü
Tert-Butyl Alcohol (TBA)	ND	10	4.0	1	U	•	, ·						
Surrogates:		Control Limits	<u>Qu</u>	<u>al</u>		Surrogates:			REC (%)	<u>Control</u> Limits	Q	<u>ual</u>	
1,2-Dichloroethane-d4		80-128				Dibromofluo	romethane		106	80-127			
Toluene-d8		80-120					uorobenzene)	87	68-120			
MW2	Service Control of the Control of th	The second secon	10-08	0095-2	The second secon	08/02/10 11:00	Aqueous	GC/NS L	08/03/	A. State of the second second	/04/10 07:00	100803	L02
Annual Control of the	Adamin particular control of the con	200 (Annual VIII)				original designations		A hade a second respective and		21 - 1000 100 100 100 100 100 100 100 100	Service Services		
	evaluated to the					ADL but < RL	, if found, are	qualified wi	th a "J" flag] .			
<u>Parameter</u>	Result .	RL	MDL	<u>DF</u>	Qual	<u>Parameter</u>			Result	RL	MDL	DF	Qual
1,2-Dîbromoethane	ND	0.50	0.23	1	U	Diisopropyl	Ether (DIPE))	ND	0.50	0.12	1	U
1,2-Dichloroethane		0.50	0.075	1	U	Ethyl-t-Buty	l Ether (ETB	E)	ND	0.50	0.25	1	U
Methyl-t-Butyl Ether (MTBE)	ND	0.50	0.14	1	U	Tert-Amyl-N	lethyl Ether (TAME)	ND	0.50	0.12	1	U
Tert-Butyl Alcohol (TBA)	ND	10	4.0	1	U								
Surrogates:		Control Limits	Qu	<u>al</u>		Surrogates:			REC (%)	Control Limits	<u>Q</u>	ual	
1,2-Dichloroethane-d4	108	80-128				Dibromofluc	romethane		105	80-127			
Toluene-d8		80-120					uorobenzene	;	111	68-120			
MW3		and the second s	10-08	-0095-3	3-A	08/02/10 12:10	Aqueous	GC/MS L	08/03/		/04/10)7:29	100803	L02
Comment(s): -Results were	evaluated to the	MDL, co	oncentrat	ions >=	to the N	IDL but < RL	if found, are	qualified wit	th a "J" flac	i.			
Parameter		RL	MDL	DF	Quai	Parameter		,	Result	<u>,.</u> <u>RL</u>	MDL	DF	Qual
1,2-Dibromoethane		0.50	0.23	1	U		Ether (DIPE)	1	ND	0.50	0.12	1	U
1,2-Dichloroethane		0.50	0.075	1	Ŭ		l Ether (ETB		ND	0.50	0.25	1	U
Methyl-t-Butyl Ether (MTBE)		0.50	0.14	1	Ü		ethyl Ether (•	ND	0.50	0.23	1	U
Tert-Butyl Alcohol (TBA)		10	4.0	1	Ü	· Oct / tissys=ss	.ouryr Euros (··· \\=\/	1 4 LJ	0.00	V. 12.	•	J
Surrogates:		Control Limits	Qu	<u>al</u>		Surrogates:			REC (%)	Control Limits	Qı	<u>ual</u>	
1,2-Dichloroethane-d4		80-128				Dibromofluo	romethane		121	80-127			
Toluene-d8		80-120					uorobenzene	1	86	68-120			
	•,	- ·				., . 510111011		•	55				



DF - Dilution Factor

Qual - Qualifiers





ETIC Engineering, Inc. 2285 Morello Avenue

Pleasant Hill, CA 94523-1850

Date Received:

Work Order No: Preparation:

Method:

Units:

EPA 5030B EPA 8260B

08/03/10

10-08-0095

ug/L Page 2 of 2

REC (%) Control

109

88

Limits

80-127

68-120

Qual

Project: ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA

REC (%) Control

116

101

<u>Limits</u>

80-128

80-120


Qual

	,		· · · · · · · · · · · · · · · · · · ·			14, 4,		·····	raye	: Z U:	_
Client Sample Number			Lab Sample Number			Date/Time Collected Matrix Instrumer	Date nt Prepa		e/Time alyzed	QC Batch II	
MVV5 to the second seco	A CONTROL OF THE CONT	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	10-08	-0095-4	I-A	08/02/10 Aqueous GC/MS I 11:35	/MS.L 08/03/10 ⁰		08/04/10 07:57		3L02
Comment(s): -Results were	evaluated to the	ne MDL, c	concentrat	ions >=	to the N	MDL but < RL, if found, are qualified v	vith a "J" flag	g .			
<u>Parameter</u>	Result	<u>RL</u>	MDL	<u>DF</u>	<u>Qual</u>	<u>Parameter</u>	Result	<u>RL</u>	MDL	<u>DF</u>	Qua
I,2-Dibromoethane	ND	0.50	0.23	1	U	Diisopropyl Ether (DIPE)	ND	0.50	0.12	1	U
,2-Dichloroethane	ND	0.50	0.075	1	U	Ethyl-t-Butyl Ether (ETBE)	ND	0.50	0.25	1	U
Methyl-t-Butyl Ether (MTBE)	ND	0.50	0.14	1	U	Tert-Amyl-Methyl Ether (TAME)	ND	0.50	0.12	1	U
ert-Butyl Alcohol (TBA)	ND	10	4.0	1	U						
Surrogates:	REC (%)	Control	Qu	al		Surrogates:	REC (%)	Control	Q	ual	
		Limits						Limits			
,2-Dichloroethane-d4	115	80-128				Dibromofluoromethane	110	80-127			
Foluene-d8	104	80-120				1,4-Bromofluorobenzene	100	68-120			
Method Blank	man and a second a	The second secon	099-1	0-025-1	.661	N/A Aqueous GC/MS L	08/03/	10 08	/03/10	100803	1.02
	And the second s	Anny Charaching and C	- Constanting	hadrond to have a second and a		rich Arting der Germannen der	And the second s		23:55		The state of the s
Comment(s): -Results were	evaluated to th	ne MDL, c	oncentrat	ions >=	to the N	ADL but < RL, if found, are qualified v	vith a "J" flaç] .			
<u>Parameter</u>	Result	<u>RL</u>	MDL.	DF	Qual	<u>Parameter</u>	Result	RL	MDL	DF	Qua
,2-Dibromoethane	ND	0.50	0.23	1	U	Diisopropyl Ether (DIPE)	ND	0.50	0.12	1	U
,2-Dichloroethane	ND	0.50	0.075	1	U	Ethyl-t-Butyl Ether (ETBE)	ND	0.50	0.25	1	Ū
Nethyl-t-Butyl Ether (MTBE)	ND	0.50	0.14	1	U	Tert-Amyl-Methyl Ether (TAME)	ND	0.50	0.12	1	Ü

Surrogates:

Dibromofluoromethane

1,4-Bromofluorobenzene



Surrogates:

Toluene-d8

1,2-Dichloroethane-d4



Quality Control - Spike/Spike Duplicate



ETIC Engineering, Inc. 2285 Morello Avenue Pleasant Hill, CA 94523-1850 Date Received: Work Order No: Preparation: Method: 08/03/10 10-08-0095 EPA 5030B EPA 8015B (M)

Project ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA

Quality Control Sample ID	Matrix	Instrument	Date Prepared		Date Analyzed	MS/MSD Batch Number
10-08-0162-2	Aqueous	GC 42	08/05/10		08/05/10	100805S01
<u>Parameter</u>	MS %REC	MSD %REC	%REC CL	RPD	RPD CL	Qualifiers
TPH as Gasoline	86	91	68-122	6	0-18	



RPD - Relative Percent Difference , CL - Control Limit



Quality Control - Spike/Spike Duplicate




ETIC Engineering, Inc. 2285 Morello Avenue Pleasant Hill, CA 94523-1850 Date Received: Work Order No: Preparation: Method: 08/03/10 10-08-0095 EPA 5030B EPA 8021B

Project ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA

Quality Control Sample ID	Matrix	Instrument	Date Prepared	F	Date Analyzed	MS/MSD Batch Number	
AND THE RESIDENCE OF THE PROPERTY OF THE PROPE	Aqueous	GC 8	08/04/10	Control Contro	08/04/10	100804501	
<u>Parameter</u>	MS %REC	MSD %REC	%REC CL	RPD	RPD CL	Qualifiers	
Benzene	83	85	57-129	3	0-23		
Toluene	84	84	50-134	0	0-26		
Ethylbenzene	85	85	58-130	0	0-26		
p/m-Xylene	86	85	58-130	1	0-28		
o-Xylene	83	84	57-123	0	0-26		





Quality Control - Spike/Spike Duplicate




ETIC Engineering, Inc. 2285 Morello Avenue Pleasant Hill, CA 94523-1850


Date Received: Work Order No: Preparation: Method:

08/03/10 10-08-0095 EPA 5030B EPA 8260B

Project ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA

Quality Control Sample ID	Date Matrix Instrument Prepared			Date Analyzed	MS/MSD Batch Number	
10-07-2301-3	Aqueous GC/MS L		08/03/10	Application of the second of t	08/04/10	100803S02
<u>Parameter</u>	MS %REC	MSD %REC	%REC CL	RPD	RPD CL	Qualifiers
Benzene	108	100	76-124	7	0-20	
1,2-Dibromoethane	105	106	80-120	2	0-20	
1,2-Dichloroethane	113	115	80-120	2	0-20	
Ethylbenzene	75	70	78-126	7	0-20	3
Toluene	77	75	80-120	3	0-20	3
Methyl-t-Butyl Ether (MTBE)	87	104	67-121	17	0-49	
Tert-Butyl Alcohol (TBA)	102	98	36-162	3	0-30	
Diisopropyl Ether (DIPE)	93	105	60-138	12	0-45	
Ethyl-t-Butyl Ether (ETBE)	91	97	69-123	7	0-30	
Tert-Amyl-Methyl Ether (TAME)	99	93	65-120	7	0-20	
Ethanol	92	113	30-180	20	0-72	








ETIC Engineering, Inc. 2285 Morello Avenue Pleasant Hill, CA 94523-1850 Date Received: Work Order No: Preparation: Method: N/A 10-08-0095 EPA 3510C EPA 8015B (M)

Project: ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA

Quality Control Sample ID	Matrix I	nstrument	Date Prepared	Date Analyzed	LCS/LCSD Bate Number	h
099-12-330-1,616	\queous	GC 27	08/05/10	08/09/10	100805B13	and planet Wasser, and a second secon
<u>Parameter</u>	LCS %REC	LCSD %F	EC %REC	CL RPD	RPD CL	Qualifiers
TPH as Diesel	77	76	75-11	7 1	0-13	



RPD - Relative Percent Difference , CL - Control Limit





ETIC Engineering, Inc. 2285 Morello Avenue Pleasant Hill, CA 94523-1850 Date Received: Work Order No: Preparation: Method:

N/A 10-08-0095 EPA 5030B EPA 8015B (M)

Project: ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA

Quality Control Sample ID	Matrix	Instrument	Date Prepared	Date Analyzed		CSD Batch lumber	
099-12-436-5,065 A	queous	GC 42	08/05/10	08/05/10	10 State Sta	0805B01	See the second of the second o
Parameter	LCS %RE	C LCSD	<u>%REC</u> %R	EC CL	RPD R	PD CL	<u>Qualifiers</u>
TPH as Gasoline	96	96	7	8-120	0	0-10	



RPD - Relative Percent Difference , CL - Control Limit






ETIC Engineering, Inc. 2285 Morello Avenue Pleasant Hill, CA 94523-1850 Date Received: Work Order No: Preparation: Method: N/A 10-08-0095 EPA 5030B EPA 8021B

Project: ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA

Quality Control Sample ID	Matrix II	nstrument	Date Prepared	Date Analyzed	LCS/LCSD Bate Number	ch .
099-12-667-883	Aqueous	GC-8	08/04/10	08/04/10	100804B01	
<u>Parameter</u>	LCS %REC	LCSD %RE	C %REC	CL RPD	RPD CL	Qualifiers
Benzene	88	89	70-11	8 1	0-9	
Toluene	88	88	66-11	4 1	0-9	
Ethylbenzene	90	89	72-11	4 1	0-9	
p/m-Xylene	92	90	74-11	6 2	0-9	
o-Xylene	88	87	72-11	4 2	0-9	







ETIC Engineering, Inc. 2285 Morello Avenue Pleasant Hill, CA 94523-1850 Date Received: Work Order No: Preparation: Method:

N/A 10-08-0095 EPA 5030B EPA 8260B

Project: ExxonMobil 74121, 10605 Foothill Blvd., Oakland, CA


Quality Control Sample ID	Matrix	Instrument		LCS/LCSD Numbe			
099-10-025-1,661	Aqueous	GC/MS L	08/03/10	08/03	/10	100803L	OZ
<u>Parameter</u>	LCS %REC	LCSD %REC	%REC CL	ME CL	RPD	RPD CL	Qualifiers
Benzene	99	99	80-120	73-127	0	0-20	
1,2-Dibromoethane	97	98	79-121	72-128	1	0-20	
1,2-Dichloroethane	106	109	80-120)-120 73-127		0-20	
Ethylbenzene	101	102	80-120	73-127	1	0-20	
Toluene	101	100	80-120	73-127	2	0-20	
Methyl-t-Butyl Ether (MTBE)	100	99	69-123	60-132	1	0-20	
Tert-Butyl Alcohol (TBA)	90	95	63-123	53-133	5	0-20	
Diisopropyl Ether (DIPE)	104	101	59-137	46-150	3	0-37	
Ethyl-t-Butyl Ether (ETBE)	97	93	69-123	60-132	4	0-20	
Tert-Amyl-Methyl Ether (TAME)	89	90	70-120	62-128	1	0-20	
Ethanol	105	109	28-160	160 6-182 3		0-57	


Total number of LCS compounds: 11

Total number of ME compounds: 0

Total number of ME compounds allowed: 1

LCS ME CL validation result: Pass






Glossary of Terms and Qualifiers



Work Order Number: 10-08-0095

Qualifier *	Definition See applicable analysis comment.
1	Surrogate compound recovery was out of control due to a required sample dilution, therefore, the sample data was reported without further clarification.
2	Surrogate compound recovery was out of control due to matrix interference. The associated method blank surrogate spike compound was in control and, therefore, the sample data was reported without further clarification.
3	Recovery of the Matrix Spike (MS) or Matrix Spike Duplicate (MSD) compound was out of control due to matrix interference. The associated LCS and/or LCSD was in control and, therefore, the sample data was reported without further clarification.
4	The MS/MSD RPD was out of control due to matrix interference. The LCS/LCSD RPD was in control and, therefore, the sample data was reported without further clarification.
5	The PDS/PDSD or PES/PESD associated with this batch of samples was out of control due to a matrix interference effect. The associated batch LCS/LCSD was in control and, hence, the associated sample data was reported without further clarification.
В	Analyte was present in the associated method blank.
E	Concentration exceeds the calibration range.
I	Compound did not meet method-described identification guidelines. Identification was based on additional GC/MS characteristics.
J	Analyte was detected at a concentration below the reporting limit and above the laboratory method detection limit. Reported value is estimated.
ME	LCS recovery percentage is within LCS ME control limit range.
ND	Parameter not detected at the indicated reporting limit.
Q	Spike recovery and RPD control limits do not apply resulting from the parameter concentration in the sample exceeding the spike concentration by a factor of four or greater.
U	Undetected at detection limit.
X	% Recovery and/or RPD out-of-range.
Z	Analyte presence was not confirmed by second column or GC/MS analysis.
	Solid - Unless otherwise indicated, solid sample data is reported on a wet weight basis, not corrected for % moisture.



7440 LINCOLN WAY **GARDEN GROVE, CA 92841-1432**

CHAIN OF CUSTODY RECORD

	Leaboratories, inc.	TEL: (714) 895-5494 . FA)	K: (714) 894	-7501											P	AGE:			1		OF		1		
ADD	PRATORY CLIENT: onMobil c/o ETIC Engress:	gineering					7	4121	, 100	NAME / NO			uleva	ard,	CA					NO.;		2012	296		
CITY:	5 Morello Avenue Isant Hill, CA 94523						E	rik A	ppe	ot: I, ETIC NATURE)	: Eng	ginee	ring			Number 14121		}		OTE N			2000	nii neit	180181
TEL: 325-	602-4710 x21	FAX: 925-602-4720		E-MAIL SEE IT	ns <u>tructi</u>	ons	,	A		Ú		ea h	<u> </u>			-						0	<u> </u>	Z J	\Box
	SAME DAY 24 HR		X 5 E	DAYS 🗌	10 DA	YS		•	_			···	RE	QUI	STE	D A	NAI	LYS	IS		,				
ed en	lse Silica Gel Cleanu	······································		/ ticeng.co	/ m	***************************************	y EPA Method 8015B	/ EPA Method 8021B (M)	E	TBA, DIPE, TAME, ETBE, ,2-DCA by EPA Method	Andresse besselver versioner vergenter op grant grant gegenter gebruikt spiller.												de de l'étable de l'apparent de l'étable à l'étable de l'étable de l'étable de l'étable de l'étable de l'étable	en est de la constitució de la constitu	
LAB USE MLY	SAMPLE ID	LOCATION/ DESCRIPTION	SAM! DATE	PLING TIME	Malty.	*Cone	TPH-g by	втех ьу	TPH-d by	MTBE, T EDB, 1,2 8260B]	- The second	***************************************	
	MVV1	<i>o</i> &	-02-10	195	Water	11	Х	Х	Х	Х											·				
2 3	MW2			1100	Water	11	X		X	X															
ر	MVV3			/2/0	Water		X	<u> </u>	X	Х															
χ	MW5		b	//35	Water	11	X	X	Х	Х							_						-	\dashv	
															〓							-	士	寸	_
							!-									_	\dashv						_	4	
																	\exists						_	_	,
\elinq	uished by: (Signature)	In plante	Og #210	j ffw	Receive	of by:	Signate	ite)		y (00						_	Date	7	<u> </u>		Time:	12	<u></u>	h-SWHINE I
gyile)	dished by: (Signature)	<i></i>		,,	Receive	ed by: (S	Signate			J_(ت						\dashv	Date:	4	70	-	Time:	130	<u></u>	

Received by: (Signature)

SSO



〈WebShip〉>>>

800-322-5555 www.gso.com

Ship From: ALAN KEMP CAL SCIENCE- CONCORD 5063 COMMÉRCIAL CIRCLE #H CONCORD, CA 94520

Ship To: SAMPLE RECEIVING CEL 7440 LINCOLN WAY GARDEN GROVE, CA 92841

COD: \$0.00

Reference: BTS, ERI, CRA

Delivery Instructions:

Signature Type: SIGNATURE REQUIRED Tracking #: 514664795

NPS

GARDEN GROVE

D92843A



Print Date: 08/02/10 15:07 PM Package 1 of 1

Send Label To Printer

Print All

Edit Shipment

Finish

LABEL INSTRUCTIONS:

Do not copy or reprint this label for additional shipments - each package must have a unique barcode.

STEP 1 - Use the "Send Label to Printer" button on this page to print the shipping label on a laser or inkjet printer.

STEP 2 - Fold this page in half.

STEP 3 - Securely attach this label to your package, do not cover the barcode.

STEP 4 - Request an on-call pickup for your package, if you do not have scheduled daily pickup service or Drop-off your package at the nearest GSO drop box. Locate nearest GSO dropbox locations using this link.


ADDITIONAL OPTIONS:

Send Label Via Email

Create Return Label

TERMS AND CONDITIONS:

By giving us your shipment to deliver, you agree to all the service terms and conditions described in this section. Our liability for loss or damage to any package is limited to your actual damages or \$100 whichever is less, unless you pay for and declare a higher authorized value. If you declare a higher value and pay the additional charge, our liability will be the lesser of your declared value or the actual value of your loss or damage. In any event, we will not be liable for any damage, whether direct, incidental, special or consequential, in excess of the declared value of a shipment whether or not we had knowledge that such damage might be incurred including but not limited to loss of income or profit. We will not be liable for your acts or omissions, including but not limited to improper or insufficient packaging, securing, marking or addressing. Also, we will not be liable if you or the recipient violates any of the terms of our agreement. We will not be liable for loss, damage or delay caused by events we cannot control, including but not limited to acts of God, perils of the air, weather conditions, act of public enemies, war, strikes, or civil commotion. The highest declared value for our GSO Priority Letter or GSO Priority Package is \$500. For other shipments the highest declared value is \$10,000 unless your package contains items of "extraordinary value", in which case the highest declared value we allow is \$500. Items of "extraordinary value" include, but or not limited to, artwork, jewelry, furs, precious metals, tickets, negotiable instruments and other items with intrinsic value.



WORK ORDER #: 10-08- ∅ ∅ ⋬ ⋬

SAMPLE RECEIPT FORM Cooler t of 1

LIENT: ETC	DATE:	08/03/	10
TEMPERATURE: Thermometer ID: SC1 (Criteria: 0.0 °C - 6.0 °C, not frozer Temperature	Blank ay of samplinurier.	□ Sample ng. Initial: <u>\</u>	W)
CUSTODY SEALS INTACT: ☐ Cooler ☐ ☐ No (Not Intact) ☐ Not Present ☐ Sample ☐ ☐ No (Not Intact) ☐ Not Present	□ N/A	Initial: _ Initial: _	ACT.
SAMPLE CONDITION:	Yes	No i	N/A
Chain-Of-Custody (COC) document(s) received with samples	. 🗹		
COC document(s) received complete	. E		
☐ Collection date/time, matrix, and/or # of containers logged in based on sample labels.			
☐ No analysis requested. ☐ Not relinquished. ☐ No date/time relinquished.			
Sampler's name indicated on COC	₽		
Sample container label(s) consistent with COC	7		
Sample container(s) intact and good condition	2		
Proper containers and sufficient volume for analyses requested			
Analyses received within holding time	Z		
pH / Residual Chlorine / Dissolved Sulfide received within 24 hours			đ
Proper preservation noted on COC or sample container	P		
☐ Unpreserved vials received for Volatiles analysis			
Volatile analysis container(s) free of headspace	Z		
Tedlar bag(s) free of condensation CONTAINER TYPE:			
Solid: 40zCGJ 80zCGJ 160zCGJ Sleeve () EnCores	s [®] □Terra0	Cores [®] □	
Water: □VOA ∠ZVOAh □VOAna₂ □125AGB □125AGBh □125AGBp	□1AGB □]1AGBna₂ □1	AGB s
□500AGB Ø500AGJ □500AGJs □250AGB □250CGB □250CGBs			
□250PB □250PBn □125PB □125PBznna □100PJ □100PJna₂ □			
Air: Tedlar® Summa® Other: Trip Blank Lot#: Container: C: Clear A: Amber P: Plastic G: Glass J: Jar B: Bottle Z: Ziploc/Resealable Bag E: B Preservative: h: HCL n: HNO3 na2:Na2S2O3 na: NaOH p: H3PO4 s: H3SO4 znna: ZnAc2+NaOH f:	Envelope R	eviewed by:	SO DE L