

LOP - RECORD CHANGE REQUEST FORM

printed:
02/16/95

Mark Out What Needs Changing and Hand to LOP Data Entry
(Name/Address changes go to Annual Programs Data Entry)

Insp: SH

AGENCY # : 10000 SOURCE OF FUNDS: - SUBSTANCE: -0-
 StID : 5024 LOC: -0-
 SITE NAME: Allied Packing & Supply DATE REPORTED : 01/01/01
 ADDRESS : 5303 -0 Adeline St DATE CONFIRMED: -0-
 CITY/ZIP : Oakland 94608 MULTIPLE RPs : -

SITE STATUS

 CASE TYPE: - CONTRACT STATUS: - PRIOR CODE: -0- EMERGENCY RESP: -0-
 RP SEARCH: - DATE COMPLETED: -0-
 PRELIMINARY ASMNT: - DATE UNDERWAY: -0- DATE COMPLETED: -0-
 REM INVESTIGATION: - DATE UNDERWAY: -0- DATE COMPLETED: -0-
 REMEDIAL ACTION: - DATE UNDERWAY: -0- DATE COMPLETED: -0-
 POST REMED ACT MON:- DATE UNDERWAY: -0- DATE COMPLETED: -0-

ENFORCEMENT ACTION TYPE: - DATE ENFORCEMENT ACTION TAKEN: -0-
 LUFT FIELD MANUAL CONSID: -0-
 CASE CLOSED: - DATE CASE CLOSED: -0-
 DATE EXCAVATION STARTED : -0- REMEDIAL ACTIONS TAKEN: -0-

RESPONSIBLE PARTY INFORMATION

 RP#1-CONTACT NAME: -0-
 COMPANY NAME: -0-
 ADDRESS: -0-
 CITY/STATE: -0-

INSPECTOR VERIFICATION:			
NAME	SIGNATURE	DATE	
DATA ENTRY INPUT:			
Name/Address Changes Only		Case Progress Changes	
ANNPGMS	LOP	DATE	LOP DATE

2/16/95

Brian,
 (quote)
 I removed a tank at this site recently (2/10/95).
 Have you been to this place? Are they potential
 generators/H4BP candidates for our programs? Don't look
 like they are in our lists.

2/27/95 fuser

we shall see!

Bru

white -env.health
 yellow -facility
 pink -files

ALAMEDA COUNTY, DEPARTMENT OF
 ENVIRONMENTAL HEALTH
 Hazardous Materials Inspection Form

80 Swan Way, #200
 Oakland, CA 94621
 (415) 271-4320

II, III

Site ID # 5024 Site Name Allied Packing & Supply Date 8/16/95

Site Address 5303 Adeline St.

City Oakland Zip 94608 Phone _____

MAX AMT stored > 500 lbs, 55 gal., 200 cft.?

Inspection Categories:

- I. Haz. Mat/Waste GENERATOR/TRANSPORTER
- II. Business Plans, Acute Hazardous Materials
- III. Underground Tanks

Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

Comments:

On Site:
 Having concrete on the
 former tank area, including the
 dispenser island.
 Tipping left on site but permanently
 capped & covered

II.A BUSINESS PLANS (Title 19)


- 1. Immediate Reporting 2703
- 2. Bus. Plan Stds. 25503(b)
- 3. RR Cars > 30 days 25503.7
- 4. Inventory Information 25504(a)
- 5. Inventory Complete 2730
- 6. Emergency Response 25504(b)
- 7. Training 25504(c)
- 8. Deficiency 25505(a)
- 9. Modification 25505(b)

II.B ACUTELY HAZ. MATLS

- 10. Registration Form Filed 25533(a)
- 11. Form Complete 25533(b)
- 12. RMPP Contents 25534(c)
- 13. Implement Sch. Req'd? (Y/N) _____
- 14. OffSite Conseq. Assess. 25524(c)
- 15. Probable Risk Assessment 25534(d)
- 16. Persons Responsible 25534(g)
- 17. Certification 25534(f)
- 18. Exemption Request? (Y/N) _____
- 19. Trade Secret Requested? 25538

III. UNDERGROUND TANKS (Title 23)

- General**
- 1. Permit Application 25284 (H&S)
- 2. Pipeline Leak Detection 25292 (H&S)
- 3. Records Maintenance 2712
- 4. Release Report 2651
- 5. Closure Plans 2670
- 6. Method
- 1) Monthly Test
- 2) Daily Vadose
Semi-annual groundwater
One time soils
- 3) Daily Vadose
One time soils
Annual tank test
- 4) Monthly Groundwater
One time soils
- Tanks**



white - env. health
yellow - facility
pink - files

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

1131 Harbor Bay Pkwy
Alameda CA 94502
510/567-6700

Hazardous Materials Inspection Form

II, III

Site ID # _____ Site Name Allied Packing & Supply Today's Date 2/10/95
Site Address 5303 Adeline
City OAKLAND Zip 94608 Phone _____

MAX AMT stored > 500 lbs, 55 gal., 200 cft.?

Inspection Categories:

- I. Haz. Mat/Waste GENERATOR/TRANSPORTER
- II. Hazardous Materials Business Plan, Acutely Hazardous Materials
- III. Under ground Storage Tanks

* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

Comments:

One UGT Removal (1000 gal) gasoline - steel tank
Deanna LTD - tank hauler, April 95 # 428262
Manifest # 93481054 for the tank.

Oakland Fire Inspector Cody present at the site
LEL = 1%. O₂ = 19.0%

The tank was underneath the sidewalk (53rd St.)
Holes were present in the tank. Strong corrosion/
peeling observed.

No ground water was present. Two bottom soil
samples collected (1 1/2 ft bags) & Two sidewall soil
samples collected (8 ft core bags). 7 discrete soil
samples collected. The stockpiled soil (to be
compacted into 020 strength in the lab.)

Stockpiled soil allowed to be used to backfill
the excavation due to safety concern (pit in the
sidewalk). 15 quar to be placed at the bottom
before backfilling. Soil will samples to be
analyzed only if contamination is detected in the
bottom samples or the stockpiled soil.

Contact Randy McManus
Title Genco
Signature Randy McManus

Inspector SUSAN L. HUGO
Signature Susan L. Hugo

II, III

S E M C O
ENVIRONMENTAL CONTRACTORS & GENERAL ENGINEERING
1741 LESLIE STREET
SAN MATEO, CALIFORNIA 94402

February 16, 1994

ALCO
HAZMAT
95 FEB 17 PM 2:50

Susan Hugo
Alameda County
Environmental Health Department
1131 Harbor Bay Parkway, # 250
Alameda, California 94502

Re: Tank Removal Report, 5303 Adeline St., Oakland

Dear Susan:

Please find enclosed, a copy of the tank removal report for the above mentioned address.

If you have any questions, please give me a call.

Respectfully,

Rhonda Reames-Kiper
Rhonda Reames-Kiper
SEMCO-SAN MATEO

cc: Ulrik Motzfeldt, Allied Packing
File

License # 449864
A,B, C-61/D40
Hazardous Substances Certification

(800) 831-2344
(415) 572-8033
(415) 572-9734 FAX