



ENVIRONMENTAL ENGINEERING, INC.

2680 Bishop Drive, Suite 203  
San Ramon, California 94583  
TEL (925) 244-6600  
FAX (925) 244-6601

**FAX TRANSMITTAL**

DATE: 5-7-99 FAX# 510-337-9335

TO: Susan Hugo

COMPANY: ACEHS

FROM: Mansour Sefer

SUBJECT: Lab Analysis Sheet for PCBs

NUMBER OF PAGES INCLUDING COVER: 2

MESSAGE:

*Susan:*

*Per our discussion. Please call me  
if you need further assistance.*

*Mansour*

WATER • WASTE WATER • HAZARDOUS WASTE • FUEL • AIR • SOIL

# DELTA

ENVIRONMENTAL LABORATORIES

Client:  
SOMA  
2680 Bishop DR. Suite 203  
San Ramon, CA 94583

Client Project ID:  
Westinghouse 3

Ref.: R3609pcbs  
Method 8080  
Sampled: 6/23/98  
Received: 6/23/98  
Matrix: Soil  
Analyzed: 6/25-29/98  
Reported: 6/30/98  
Units: mg/kg

Attention: Dr. Sepehr

Analytical Results for PCBs					
Analyte	Detection Limit mg/kg	Results			
		Sample ID			
		N-Soil	S-Soil	Out Pit S1 Shallow	Out pit S2 Deep
<b>PCBs</b>					
PCB 1016	1.0	ND	ND	ND	ND
PCB 1221	1.0	ND	ND	ND	ND
PCB 1232	1.0	ND	ND	ND	ND
PCB 1242	1.0	ND	ND	ND	ND
PCB 1248	1.0	ND	ND	ND	ND
PCB 1254	1.0	ND	ND	ND	ND
PCB 1260	1.0	380	11.6	136	4.12

ND: Not Detected (<MDL)

The detection limits have been elevated due to high concentration of the samples.

Delta Environmental Laboratories

Hossein Khosh Khoo Ph.D. 

- ① Tank removed 1988
- ② PCBs off site (136 ppm) removed