

RECEIVED

1:34 pm, Oct 22, 2008

Alameda County
Environmental Health

October 21, 2008
DELTA Project No. SCA8999S1
SAP No. 135244

Mr. Jerry Wickham
Alameda County Health Care Services Agency
Environmental Health Services – Environmental Protection
1131 Harbor Bay Parkway, Suite 250
Alameda, California 94502-6577

**Re: THIRD QUARTER 2008 GROUNDWATER MONITORING
REPORT**
Shell-Branded Service Station
8999 San Ramon Road
Dublin, California



Dear Mr. Wickham:

On behalf of Shell Oil Products (SHELL), Delta Consultants (DELTA) has prepared this *Third Quarter 2008 Groundwater Monitoring Report* for the above referenced site. The sampling activities at the site were conducted by Blaine Tech Services, Inc. under contract to SHELL and included static water level measurements. A DELTA staff member, under the supervision of a California Registered Civil Engineer or a California Professional Geologist, performed the data evaluation.

This quarterly report represents DELTA's professional opinions based upon the currently available information and is arrived at in accordance with currently acceptable professional standards. This report is based upon a specific scope of work requested by the client. The Contract between DELTA and its client outlines the scope of work, and only those tasks specifically authorized by that contract or outlined in this report were performed. This report is intended only for the use of DELTA's Client and anyone else specifically listed on this report. DELTA will not and cannot be liable for unauthorized reliance by any other third party. Other than as contained in this paragraph, DELTA makes no express or implied warranty as to the contents of this report.

a member of:



312 PIERCY ROAD SAN JOSE, CALIFORNIA 95138 USA
PHONE +1 408.224.4724 / USA TOLL FREE 800.477.7411
FAX +1 408.225.8506 WWW.DELTAENV.COM

Mr. Jerry Wickham
Alameda County Health Care Services Agency
October 21, 2008
Page 2

If you have any questions regarding this site, please contact Ms. Elisabeth Silver (DELTA Site Manager) at (425) 498-7736 or Mr. Denis Brown (SHELL Project Manager) at (707) 865-0251.


Sincerely,
Delta Consultants



Elisabeth Silver
Project Manager



Richard A. Garlow, M.S., P.G.
Senior Project Geologist



Attachment: Third Quarter 2008 Groundwater Monitoring Report

cc: Denis Brown, Shell Oil Products US, Carson
Carl Cox, C and J Cox Corporation, Pleasanton
Colleen Winey, Zone 7 Water Agency, Livermore

SHELL QUARTERLY STATUS REPORT

Station Address:	8999 San Ramon Road, Dublin, California
DELTA Project No.:	SCA8999S1
SHELL Project Manager / Phone No.:	Denis Brown / (707) 865-0251
DELTA Site Manager / Phone No.:	Elisabeth Silver / (425) 498-7736
Primary Agency / Regulatory ID:	ACHCSA / Jerry Wickham
Other Agencies to Receive Copies:	Zone 7 Water Agency

WORK PERFORMED THIS QUARTER (THIRD - 2008):

1. Quarterly groundwater monitoring and sampling. Submitted quarterly report.

WORK PROPOSED FOR NEXT QUARTER (FOURTH - 2008):

1. Quarterly groundwater monitoring and sampling. Submit quarterly report.

Current Phase of Project:	Site Assessment, Groundwater monitoring
Frequency of Sampling:	Quarterly
Frequency of Monitoring:	Quarterly
Is Separate Phase Hydrocarbon Present On-site (Well #'s):	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Cumulative SPH Recovered to Date:	NA
SPH Recovered This Quarter:	NA
Groundwater Recovered This Quarter:	239.5 gallons were recovered during sampling on August 5, 2008.
Sensitive Receptor(s) and Respective Direction(s):	No municipal water supply wells were identified within a one-mile radius. A domestic drinking water well (25/1W-35L001) is located ~2,300 ft. southwest of the site.
Site Lithology:	Predominately clay with sand and sandy lean clays to a total depth of approximately 30 feet bg plus CPT data to 80 feet.
Current Remediation Techniques:	None
Permits for Discharge:	None
Approximate Depth to Groundwater:	26.62 feet to 37.30 feet below top of well casing
Groundwater Gradient:	Undeterminable. Insufficient data points.
Current Agency Correspondence:	NA
Date of Most Recent Work Plan Approval:	NA

SHELL QUARTERLY STATUS REPORT (CONT.)

Site History:

Case opening	August 2004
On-Site Assessment	July 2005
Off-Site Assessment	July 2006 -Present
Passive Remediation	Monitor Natural Attenuation
Active Remediation	150 cubic yards of soil removed in 2004
Monitoring Well Destruction	On May 21 and 22, 2008, monitoring wells MW-1, MW-2, MW-3, MW-4, MW-6 and MW10 were destroyed for Station Remodel and Renovation
Summary of Unusual Activity:	Wells MW-5, MW-7 and MW-11 were dry.

ATTACHMENTS:

Table:

Table 1 – Well Concentrations

Figures:

Figure 1 – Site Location Map

Figure 2 – Groundwater Elevation Map

Figure 3 – Hydrocarbon Distribution in Groundwater Map

Appendices:

Appendix A – Field Data Sheets

Appendix B – Field Procedures

Appendix C – Laboratory Report and Chain-of-Custody Documentation

TABLE

TABLE 1
WELL CONCENTRATIONS
Shell Service Station
8999 San Ramon Road
Dublin, CA

Well ID	Date	TPPH (ug/L)	TEPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8260 (ug/L)	DIPE (ug/L)	ETBE (ug/L)	TAME (ug/L)	TBA (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)
---------	------	----------------	----------------	-------------	-------------	-------------	-------------	------------------------	----------------	----------------	----------------	---------------	--------------	----------------------------	--------------------------

MW-1	5/9/2005	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	20.93	NA
MW-1	5/19/2005	<5,000	160 a	<50	<50	<50	<100	1,400	<200	<200	<200	57,000	420.06	20.70	399.36
MW-1	8/15/2005	<5,000	<50	<50	<50	<50	<100	360	<200	<200	<200	56,000	420.06	23.98	396.08
MW-1	11/8/2005	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	420.06	NA	NA
MW-1	1/30/2006	585	438	<0.500	<0.500	<0.500	<0.500	15.6	<0.500	<0.500	<0.500	115,000	420.06	26.39	393.67
MW-1	5/19/2006	2,940	279 c	<0.500	<0.500	<0.500	<0.500	150	<0.500	0.940	<0.500	49,500	420.06	23.10	396.96
MW-1	8/24/2006	812	85.6 c	<0.500	<0.500	<0.500	<0.500	33.0	<0.500	0.890	<0.500	30,700	420.06	23.94	396.12
MW-1	11/2/2006	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	420.06	NA	NA
MW-1	1/29/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	420.06	NA	NA
MW-1	6/5/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	420.06	NA	NA
MW-1	8/27/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	420.06	NA	NA
MW-1	11/30/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	420.06	NA	NA
MW-1	2/15/2008	Insufficient water		NA	NA	NA	NA	NA	NA	NA	NA	NA	420.06	26.45	393.61
MW-1	5/15/2008	Well destroyed		NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA

MW-2	5/9/2005	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	20.72	NA
MW-2	5/19/2005	<500	<50	<5.0	<5.0	<5.0	<10	11	<20	<20	<20	4,200	418.88	21.26	397.62
MW-2	8/15/2005	<1,000	<50	<10	<10	<10	<20	<10	<40	<40	<40	7,500	418.88	25.33	393.55
MW-2	11/8/2005	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	418.88	NA	NA
MW-2	1/30/2006	<50.0	401	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	1,310	418.88	25.87	393.01
MW-2	5/19/2006	398	134 c	<0.500	<0.500	<0.500	<0.500	7.65	<0.500	<0.500	<0.500	4,910	418.88	21.75	397.13
MW-2	8/24/2006	<50.0	<46.9 c	<0.500	<0.500	<0.500	<0.500	2.82	<0.500	<0.500	<0.500	4,070	418.88	24.60	394.28
MW-2	11/2/2006	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	418.88	NA	NA
MW-2	1/29/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	418.88	NA	NA
MW-2	6/5/2007	Insufficient water		NA	NA	NA	NA	NA	NA	NA	NA	NA	418.88	26.54	392.34
MW-2	8/27/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	418.88	NA	NA
MW-2	11/30/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	418.88	NA	NA
MW-2	2/15/2008	Insufficient water		NA	NA	NA	NA	NA	NA	NA	NA	NA	418.88	26.15	392.73

TABLE 1
WELL CONCENTRATIONS
Shell Service Station
8999 San Ramon Road
Dublin, CA

Well ID	Date	TPPH (ug/L)	TEPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8260 (ug/L)	DIPE (ug/L)	ETBE (ug/L)	TAME (ug/L)	TBA (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)
MW-2	5/15/2008	Well destroyed		NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
MW-3	5/9/2005	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	19.08	NA
MW-3	5/19/2005	<50	120 a	<0.50	<0.50	<0.50	<1.0	40	<2.0	<2.0	<2.0	6.5	417.24	19.08	398.16
MW-3	8/15/2005	<50	73	<0.50	<0.50	<0.50	<1.0	34	<2.0	<2.0	<2.0	<5.0	417.24	22.20	395.04
MW-3	11/8/2005	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	417.24	NA	NA
MW-3	1/30/2006	<50.0	412	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	<10.0	417.24	23.64	393.60
MW-3	5/19/2006	<50.0	183 c	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	<10.0	417.24	19.00	398.24
MW-3	8/24/2006	<50.0	214 c	<0.500	<0.500	<0.500	<0.500	3.11	<0.500	<0.500	<0.500	661	417.24	21.84	395.40
MW-3	11/2/2006	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	417.24	NA	NA
MW-3	1/29/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	417.24	NA	NA
MW-3	6/5/2007	<50 f	230 c	<0.50	<1.0	<1.0	<1.0	0.38 g	<2.0	<2.0	<2.0	<10	417.24	23.80	393.44
MW-3	8/27/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	417.24	NA	NA
MW-3	11/30/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	417.24	NA	NA
MW-3	2/15/2008	Insufficient water		NA	NA	NA	NA	NA	NA	NA	NA	NA	417.24	23.60	393.64
MW-3	5/15/2008	Well destroyed		NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
MW-4	5/9/2005	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	19.77	NA
MW-4	5/19/2005	97	59 a	0.66	<0.50	<0.50	<1.0	4.8	<2.0	<2.0	<2.0	8.2	420.52	19.85	400.67
MW-4	8/15/2005	67	<50	<0.50	<0.50	<0.50	<1.0	0.86	<2.0	<2.0	<2.0	<5.0	420.52	23.34	397.18
MW-4	11/8/2005	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	420.52	NA	NA
MW-4	1/30/2006	<50.0	112	<0.500	<0.500	<0.500	<0.500	1.63	<0.500	<0.500	<0.500	<10.0	420.52	24.13	396.39
MW-4	5/19/2006	<50.0	<46.9 c	<0.500	<0.500	<0.500	<0.500	1.08	<0.500	<0.500	<0.500	<10.0	420.52	19.79	400.73
MW-4	8/24/2006	<50.0	<47.2 c	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	78.3	420.52	22.50	398.02
MW-4	11/2/2006	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	420.52	NA	NA
MW-4	1/29/2007	<50	<50 c	<0.50	<0.50	<0.50	<1.0	<0.50	<2.0	<2.0	<2.0	<5.0	420.52	25.82	394.70
MW-4	6/5/2007	62 f	120 c	<0.50	<1.0	<1.0	<1.0	1.4	<2.0	<2.0	<2.0	<10	420.52	24.32	396.20
MW-4	8/27/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	420.52	NA	NA

**TABLE 1
WELL CONCENTRATIONS
Shell Service Station
8999 San Ramon Road
Dublin, CA**

Well ID	Date	TPPH (ug/L)	TEPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8260 (ug/L)	DIPE (ug/L)	ETBE (ug/L)	TAME (ug/L)	TBA (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)
MW-4	11/30/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	420.52	NA	NA
MW-4	2/15/2008	56 f	<50 c	<0.50	<1.0	<1.0	<1.0	2.9	<2.0	<2.0	<2.0	<10	420.52	24.34	396.18
MW-4	5/15/2008	Well destroyed		NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
MW-5	8/21/2006	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	416.88	25.25	391.63
MW-5	8/24/2006	<50.0	108 c	<0.500	<0.500	<0.500	<0.500	3.33	<0.500	<0.500	<0.500	21.0	416.88	25.70	391.18
MW-5	11/2/2006	<50	NA	<0.50	<0.50	<0.50	<1.0	<0.50	<2.0	<2.0	<2.0	<5.0	416.88	28.00	388.88
MW-5	1/29/2007	<50	66 c	<0.50	<0.50	<0.50	<1.0	<0.50	<2.0	<2.0	<2.0	<5.0	416.88	27.80	389.08
MW-5	6/5/2007	<50 f	2,200 c,e	<0.50	<1.0	<1.0	<1.0	0.56 g	<2.0	<2.0	<2.0	<10	416.88	27.72	389.16
MW-5	8/27/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	416.88	NA	NA
MW-5	11/30/2007	Insufficient water		NA	NA	NA	NA	NA	NA	NA	NA	NA	416.88	28.39	388.49
MW-5	2/15/2008	Insufficient water		NA	NA	NA	NA	NA	NA	NA	NA	NA	416.88	27.55	389.33
MW-5	5/27/2008	<50	83 c	<0.50	<1.0	<1.0	<1.0	4.3	<2.0	<2.0	<2.0	<10	416.88	26.68	390.20
MW-5	8/5/2008	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	416.88	NA	NA
MW-5B	2/7/2008	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	417.66	29.74	387.92
MW-5B	2/15/2008	110 e,f	<50 c	<0.50	<1.0	<1.0	<1.0	1,700	<2.0	<2.0	<2.0	250	417.66	28.85	388.81
MW-5B	5/27/2008	620	<50 c	<2.5	<5.0	<5.0	<5.0	590	<10	<10	<10	<50	417.66	27.89	389.77
MW-5B	8/5/2008	470	140 c,h	<2.5	<5.0	<5.0	<5.0	430	<10	<10	<10	<50	417.66	32.21	385.45
MW-5C	2/7/2008	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	417.10	33.97	383.13
MW-5C	2/15/2008	<50 f	<50 c	<0.50	<1.0	<1.0	<1.0	360	<2.0	<2.0	<2.0	97	417.10	34.25	382.85
MW-5C	5/27/2008	350	<50 c	<2.5	<5.0	<5.0	<5.0	290	<10	<10	<10	<50	417.10	33.97	383.13
MW-5C	8/5/2008	210	<50 c,h	<1.0	<2.0	<2.0	<2.0	180	<4.0	<4.0	<4.0	<20	417.10	37.30	379.80
MW-6	2/28/2006	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	422.50	23.55	398.95
MW-6	3/3/2006	<50.0	104	<0.500	<0.500	<0.500	<0.500	4.93	<0.500	<0.500	<0.500	<10.0	422.50	23.30	399.20
MW-6	5/19/2006	<50.0	<46.9	<0.500	<0.500	<0.500	<0.500	5.76	<0.500	<0.500	<0.500	<10.0	422.50	20.31	402.19

TABLE 1
WELL CONCENTRATIONS
Shell Service Station
8999 San Ramon Road
Dublin, CA

Well ID	Date	TPPH (ug/L)	TEPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8260 (ug/L)	DIPE (ug/L)	ETBE (ug/L)	TAME (ug/L)	TBA (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)
MW-6	8/24/2006	<50.0	<47.2 c	<0.500	<0.500	<0.500	<0.500	0.870	<0.500	<0.500	<0.500	<10.0	422.50	23.69	398.81
MW-6	11/2/2006	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	422.50	28.51	393.99
MW-6	1/29/2007	<50	<50 c	<0.50	<0.50	<0.50	<1.0	1.7	<2.0	<2.0	<2.0	<5.0	422.50	27.08	395.42
MW-6	6/5/2007	<50 f	97 c	<0.50	<1.0	<1.0	<1.0	1.1	<2.0	<2.0	<2.0	<10	422.50	25.77	396.73
MW-6	8/27/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	422.50	NA	NA
MW-6	11/30/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	422.50	NA	NA
MW-6	2/15/2008	<50 f	<50 c	<0.50	<1.0	<1.0	<1.0	9.0	<2.0	<2.0	<2.0	<10	422.50	25.56	396.94
MW-6	5/15/2008	Well destroyed		NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
MW-7	8/21/2006	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	414.35	25.84	388.51
MW-7	8/24/2006	<50.0	<47.2 c	<0.500	<0.500	<0.500	<0.500	2.63	<0.500	<0.500	<0.500	751	414.35	26.21	388.14
MW-7	11/2/2006	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	414.35	NA	NA
MW-7	1/29/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	414.35	NA	NA
MW-7	6/5/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	414.35	NA	NA
MW-7	8/27/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	414.35	NA	NA
MW-7	11/30/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	414.35	NA	NA
MW-7	2/15/2008	Insufficient water		NA	NA	NA	NA	NA	NA	NA	NA	NA	414.35	27.95	386.40
MW-7	5/27/2008	<50	<50 c	<0.50	<1.0	<1.0	<1.0	2.0	<2.0	<2.0	<2.0	<10	414.35	26.93	387.42
MW-7	8/5/2008	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	414.35	NA	NA
MW-8	8/21/2006	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	414.54	23.02	391.52
MW-8	8/24/2006	110	74.5 c	<0.500	<0.500	<0.500	<0.500	4.62	<0.500	<0.500	<0.500	6,610	414.54	23.17	391.37
MW-8	11/2/2006	92	96 c	<0.50	<0.50	<0.50	<1.0	1.4	<2.0	<2.0	<2.0	2,300	414.54	27.69	386.85
MW-8	1/29/2007	<50	<50 c	<0.50	<0.50	<0.50	<1.0	0.51	<2.0	<2.0	<2.0	350	414.54	26.40	388.14
MW-8	6/5/2007	<50 f	120 c	<0.50	<1.0	<1.0	<1.0	0.48 g	<2.0	<2.0	<2.0	290	414.54	25.17	389.37
MW-8	8/27/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	414.54	NA	NA
MW-8	11/30/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	414.54	NA	NA
MW-8	2/15/2008	<50 f	<50 c	<0.50	<1.0	<1.0	<1.0	<1.0	<2.0	<2.0	<2.0	<10	414.54	24.66	389.88

TABLE 1
WELL CONCENTRATIONS
Shell Service Station
8999 San Ramon Road
Dublin, CA

Well ID	Date	TPPH (ug/L)	TEPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8260 (ug/L)	DIPE (ug/L)	ETBE (ug/L)	TAME (ug/L)	TBA (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)
MW-8	5/27/2008	58	<50 c	<0.50	<1.0	<1.0	<1.0	1.4	<2.0	<2.0	<2.0	520	414.54	25.98	388.56
MW-8	8/5/2008	<50	<50 c,h	<0.50	<1.0	<1.0	<1.0	<1.0	<2.0	<2.0	<2.0	34	414.54	26.62	387.92
MW-8B	2/7/2008	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	414.81	26.81	388.00
MW-8B	2/15/2008	<50 f	<50 c	<0.50	<1.0	<1.0	<1.0	17	<2.0	<2.0	<2.0	65	414.81	26.23	388.58
MW-8B	5/27/2008	<50	<50 c	<0.50	<1.0	<1.0	<1.0	23	<2.0	<2.0	<2.0	33	414.81	25.51	389.30
MW-8B	8/5/2008	<50	<50 c,h	<0.50	<1.0	<1.0	<1.0	11	<2.0	<2.0	<2.0	<10	414.81	28.72	386.09
MW-9	8/21/2006	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	412.69	27.75	384.94
MW-9	8/24/2006	<50.0	69.9 c,d	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	<0.500	86.8	412.69	28.35	384.34
MW-9	11/2/2006	<50	NA	<0.50	<0.50	<0.50	<1.0	<0.50	<2.0	<2.0	<2.0	<5.0	412.69	28.43	384.26
MW-9	1/29/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	412.69	NA	NA
MW-9	6/5/2007	Insufficient water		NA	NA	NA	NA	NA	NA	NA	NA	NA	412.69	28.72	383.97
MW-9	8/27/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	412.69	NA	NA
MW-9	11/30/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	412.69	NA	NA
MW-9	2/15/2008	Insufficient water		NA	NA	NA	NA	NA	NA	NA	NA	NA	412.69	28.00	384.69
MW-9	5/27/2008	<50	NA	<0.50	<1.0	<1.0	<1.0	<1.0	<2.0	<2.0	<2.0	<10	412.69	27.93	384.76
MW-9	8/5/2008	Insufficient water		NA	NA	NA	NA	NA	NA	NA	NA	NA	412.69	28.40	384.29
MW-10	8/21/2006	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	419.48	23.90	395.58
MW-10	8/24/2006	626	100 c	1.04	<0.500	1.22	<0.500	12.4	<0.500	<0.500	<0.500	5,740	419.48	24.02	395.46
MW-10	11/2/2006	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	419.48	28.50	390.98
MW-10	1/29/2007	91	<50 c	<0.50	<0.50	<0.50	<1.0	4.9	<2.0	<2.0	<2.0	1,900	419.48	27.30	392.18
MW-10	6/5/2007	82 f	150 c	<0.50	<1.0	<1.0	<1.0	1.3	<2.0	<2.0	<2.0	540	419.48	26.09	393.39
MW-10	8/27/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	419.48	NA	NA
MW-10	11/30/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	419.48	NA	NA
MW-10	2/15/2008	<50 f	<50 c	<0.50	<1.0	<1.0	<1.0	1.6	<2.0	<2.0	<2.0	500	419.48	25.58	393.90
MW-10	5/15/2008	Well destroyed		NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA

TABLE 1
WELL CONCENTRATIONS
Shell Service Station
8999 San Ramon Road
Dublin, CA

Well ID	Date	TPPH (ug/L)	TEPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8260 (ug/L)	DIPE (ug/L)	ETBE (ug/L)	TAME (ug/L)	TBA (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)
MW-11	8/21/2006	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	409.69	NA	NA
MW-11	8/24/2006	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	409.69	NA	NA
MW-11	11/2/2006	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	409.69	NA	NA
MW-11	1/29/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	409.69	NA	NA
MW-11	6/5/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	409.69	NA	NA
MW-11	8/27/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	409.69	NA	NA
MW-11	11/30/2007	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	409.69	NA	NA
MW-11	2/15/2008	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	409.69	NA	NA
MW-11	5/27/2008	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	409.69	NA	NA
MW-11	8/5/2008	Well dry	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	409.69	NA	NA
MW-11B	2/7/2008	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	409.03	31.47	377.56
MW-11B	2/15/2008	<50 f	<50 c	<0.50	<1.0	<1.0	<1.0	<1.0	<2.0	<2.0	<2.0	<10	409.03	31.53	377.50
MW-11B	5/27/2008	<50	<50 c	<0.50	<1.0	<1.0	<1.0	<1.0	<2.0	<2.0	<2.0	<10	409.03	30.83	378.20
MW-11B	8/5/2008	<50	<50 c,h	<0.50	<1.0	<1.0	<1.0	<1.0	<2.0	<2.0	<2.0	<10	409.03	33.51	375.52
MW-12	2/7/2008	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	411.18	31.10	380.08
MW-12	2/15/2008	<50 f	<50 c	<0.50	<1.0	<1.0	<1.0	<1.0	<2.0	<2.0	<2.0	<10	411.18	31.22	379.96
MW-12	5/27/2008	<50	<50 c	<0.50	<1.0	<1.0	<1.0	<1.0	<2.0	<2.0	<2.0	<10	411.18	30.53	380.65
MW-12	8/5/2008	<50	<50 c,h	<0.50	<1.0	<1.0	<1.0	<1.0	<2.0	<2.0	<2.0	<10	411.18	33.29	377.89

**TABLE 1
WELL CONCENTRATIONS
Shell Service Station
8999 San Ramon Road
Dublin, CA**

Well ID	Date	TPPH (ug/L)	TEPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8260 (ug/L)	DIPE (ug/L)	ETBE (ug/L)	TAME (ug/L)	TBA (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)
---------	------	----------------	----------------	-------------	-------------	-------------	-------------	------------------------	----------------	----------------	----------------	---------------	--------------	----------------------------	--------------------------

Abbreviations:

TPPH = Total petroleum hydrocarbons as gasoline by modified EPA Method 8260B.

TEPH = Total petroleum hydrocarbons as diesel by modified EPA Method 8015.

BTEX = Benzene, toluene, ethylbenzene, xylenes by EPA Method 8260B.

MTBE = Methyl tertiary butyl ether

DIPE = Di-isopropyl ether, analyzed by EPA Method 8260B

ETBE = Ethyl tertiary butyl ether, analyzed by EPA Method 8260B

TAME = Tertiary amyl methyl ether, analyzed by EPA Method 8260B

TBA = Tertiary butyl alcohol or tertiary butanol, analyzed by EPA Method 8260B

TOC = Top of Casing Elevation

GW = Groundwater

ug/L = Parts per billion

MSL = Mean sea level

ft. = Feet

<n = Below detection limit

NA = Not applicable

**TABLE 1
WELL CONCENTRATIONS
Shell Service Station
8999 San Ramon Road
Dublin, CA**

Well ID	Date	TPPH (ug/L)	TEPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8260 (ug/L)	DIPE (ug/L)	ETBE (ug/L)	TAME (ug/L)	TBA (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)
---------	------	----------------	----------------	-------------	-------------	-------------	-------------	------------------------	----------------	----------------	----------------	---------------	--------------	----------------------------	--------------------------

Notes:

a = Hydrocarbon reported does not match the pattern of the laboratory's Diesel standard.

b = Quantity of unknown hydrocarbon(s) in sample based on gasoline.

c = Diesel with silica gel clean-up.

d = Insufficient sample available for reanalysis.

e = The sample chromatographic pattern for TPH does not match the chromatographic pattern of the specified standard. Quantitation of the unknown hydrocarbon(s) in the sample was based upon the specified standard.

f = Analyzed by EPA Method 8015B (M).


g = Analyte was detected at a concentration below the reporting limit and above the laboratory method detection limit. Reported value is estimated.

h = TPH as Diesel is quantified in the carbon range C10-C28

Site surveyed May 10, 2005 by Mid Coast Engineers.

Well MW-6 surveyed March 3, 2006 by Mid Coast Engineers.

FIGURES



GENERAL NOTES:

Base Map from: 3-D TopoQuads DeLorme
 Yarmouth, ME 04096 Source Data: USGS



QUADRANGLE LOCATION





FIGURE 1
SITE LOCATION MAP

SHELL-BRANDED SERVICE STATION
 8999 San Ramon Road
 Dublin, California

PROJECT NO. SCA899S1	DRAWN BY V. F. 12/9/04
FILE NO.	PREPARED BY VF
REVISION NO.	REVIEWED BY



PROJECT NUMBER SC8899S1
 APPROVED BY
 CHECKED BY
 DRAWN BY J.F.F. 9/4/2008




LEGEND

- MW-5 GROUNDWATER MONITORING WELL LOCATION AND DESIGNATION
- MW-1 DESTROYED GROUNDWATER MONITORING WELL LOCATION AND DESIGNATION
- MW-8B GROUNDWATER MONITORING WELL LOCATION AND DESIGNATION
- MW-5C GROUNDWATER MONITORING WELL LOCATION AND DESIGNATION
- MW-2B PROPOSED GROUNDWATER MONITORING WELL LOCATION
- (396.94) GROUNDWATER ELEVATION IN FEET ABOVE MEAN SEA LEVEL (FT/MSL)
- ** B AND C LEVEL WELLS NOT USED IN CONTOURING
- * INSUFFICIENT WATER FOR SAMPLING DATA NOT USED IN CONTOURING
- DRY WELL DRY, NOT SAMPLED

NOTE

GROUNDWATER FLOW AND DIRECTION UNDETERMINABLE. INSUFFICIENT DATA POINTS.

0 20 40
 SCALE IN FEET



SHELL OIL PRODUCTS U.S.
 SHELL-BRANDED SERVICE STATION
 DUBLIN, CALIFORNIA

FIGURE 2
 GROUNDWATER ELEVATION
 MAP
 8/5/2008
 8999 SAN RAMON ROAD
 DUBLIN, CALIFORNIA

PROJECT NUMBER SCA8999S1
 APPROVED BY
 CHECKED BY
 DRAWN BY J.F.F. 9/4/2008

SCALE IN FEET
 0 20 40

DISPENSER ISLAND (TYP)

ALCOSTA BOULEVARD

SAN RAMON ROAD

LANDSCAPING

I-680 ON-RAMP


RESTAURANT AND STORES

SHELL SERVICE STATION

CAR WASH

KIOSK

UST's



LEGEND

- MW-5 GROUNDWATER MONITORING WELL LOCATION AND DESIGNATION
- MW-1 DESTROYED GROUNDWATER MONITORING WELL LOCATION AND DESIGNATION
- MW-8B GROUNDWATER MONITORING WELL LOCATION AND DESIGNATION
- MW-5C GROUNDWATER MONITORING WELL LOCATION AND DESIGNATION
- MW-2B PROPOSED GROUNDWATER MONITORING WELL LOCATION
- TPH-g TOTAL PETROLEUM HYDROCARBONS AS GASOLINE
- MTBE METHYL TERT-BUTYL ETHER
- TBA TERT-BUTYL ALCOHOL
- ND< NOT DETECTED ABOVE LIMIT NOTED
- µg/L MICROGRAMS PER LITER
- NA NOT ANALYZED
- DRY WELL DRY, NOT SAMPLED

MW-8			
TPH-g (µg/L)	BENZENE (µg/L)	MTBE (µg/L)	TBA (µg/L)
ND<50	ND<0.50	ND<1.0	34

MW-8B			
TPH-g (µg/L)	BENZENE (µg/L)	MTBE (µg/L)	TBA (µg/L)
ND<50	ND<0.50	11	ND<10

MW-12			
TPH-g (µg/L)	BENZENE (µg/L)	MTBE (µg/L)	TBA (µg/L)
ND<50	ND<0.50	ND<1.0	ND<10

MW-11B			
TPH-g (µg/L)	BENZENE (µg/L)	MTBE (µg/L)	TBA (µg/L)
ND<50	ND<0.50	ND<1.0	ND<10

MW-5C			
TPH-g (µg/L)	BENZENE (µg/L)	MTBE (µg/L)	TBA (µg/L)
210	ND<1.0	180	ND<20

MW-5B			
TPH-g (µg/L)	BENZENE (µg/L)	MTBE (µg/L)	TBA (µg/L)
470	ND<2.5	430	ND<50

MW-9			
TPH-g (µg/L)	BENZENE (µg/L)	MTBE (µg/L)	TBA (µg/L)
NA	NA	NA	NA



SHELL OIL PRODUCTS U.S.
 SHELL-BRANDED SERVICE STATION
 DUBLIN, CALIFORNIA

FIGURE 3
 HYDROCARBON DISTRIBUTION IN
 GROUNDWATER MAP
 8/5/2008
 8999 SAN RAMON ROAD
 DUBLIN, CALIFORNIA

APPENDIX A

FIELD DATA SHEETS

SHELL WELLHEAD INSPECTION FORM

(FOR SAMPLE TECHNICIAN)

Site Address 8999 San Ramon Rd. Date 8/5/08
 Job Number 080805-WL1 Technician W. Lampe Page 1 of 1

Well ID	Well Inspected - No Corrective Action Required	Well Box Meets Compliance Requirements - See Below	Water Bailed From Wellbox	Cap Replaced	Lock Replaced	Well Not Inspected (explain in notes)	New Deficiency Identified	Previously Identified Deficiency Persists	Notes
MW-5	X	X							
MW-5B	X	X							
MW-5C	X	X							
MW-7	X	X							
MW-8	X	X							
MW-8B	X	X							
MW-9	X	X							
MW-11	X							X	Cristy Box
MW-11B	X	X							
MW-12	X	X							

*Well box must meet all three criteria to be compliant: 1) WELL IS SECURABLE BY DESIGN (12" or less) 2) WELL IS MARKED WITH THE WORDS "MONITORING WELL" (12" or less) 3) WELL TAG IS PRESENT, SECURE, AND CORRECT

Notes: _____

WELL GAUGING DATA

Project # 080905-WL1 Date 8/5/08 Client Shell

Site 8999 San Ramon Rd.

Well ID	Time	Well Size (in.)	Sheen / Odor	Depth to Immiscible Liquid (ft.)	Thickness of Immiscible Liquid (ft.)	Volume of Immiscibles Removed (ml)	Depth to water (ft.)	Depth to well bottom (ft.)	Survey Point: TOB or TOC	Notes	
MW-5	0845	4					Dry	28.51	↓		
MW-5B	0851	4					32.21	66.93			
MW-5C	0840	4					37.30	99.93			
MW-7	0834	4					Dry	28.54			
MW-8	0819	4					26.62	28.83			
MW-8B	0824	4					28.72	68.13			
MW-9	0830	4					28.40	29.01			
MW-11	0808	2					Dry	28.51			
MW-11B	0803	4					33.51	38.83			
MW-12	0815	4					33.29	38.81			

.61

SHELL WELL MONITORING DATA SHEET

BTS #: 080805-WL1	Site: 8999 San Ramon Rd.
Sampler: WL	Date: 8/15/08
Well I.D.: MW-5	Well Diameter: 2 3 4 6 8
Total Well Depth (TD): 28.51	Depth to Water (DTW): DRY
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: PVC Grade	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]:	

Purge Method: Bailer Water Sampling Method: Bailer
 Disposable Bailer Peristaltic Disposable Bailer
 Positive Air Displacement Extraction Pump Extraction Port
 Electric Submersible Other _____ Dedicated Tubing
 Other: _____

$\frac{\text{(Gals.) X}}{\text{1 Case Volume}} = \frac{\text{Specified Volumes}}{\text{Calculated Volume}}$	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th>Well Diameter</th> <th>Multiplier</th> <th>Well Diameter</th> <th>Multiplier</th> </tr> <tr> <td>1"</td> <td>0.04</td> <td>4"</td> <td>0.65</td> </tr> <tr> <td>2"</td> <td>0.16</td> <td>6"</td> <td>1.47</td> </tr> <tr> <td>3"</td> <td>0.37</td> <td>Other</td> <td>radius² * 0.163</td> </tr> </table>	Well Diameter	Multiplier	Well Diameter	Multiplier	1"	0.04	4"	0.65	2"	0.16	6"	1.47	3"	0.37	Other	radius ² * 0.163
Well Diameter	Multiplier	Well Diameter	Multiplier														
1"	0.04	4"	0.65														
2"	0.16	6"	1.47														
3"	0.37	Other	radius ² * 0.163														

Time	Temp (°F)	pH	Cond. (mS or µS)	Turbidity (NTUs)	Gals. Removed	Observations
Dry # unable to purge + sample						

Did well dewater? Yes No Gallons actually evacuated: _____

Sampling Date: **8/15/08** Sampling Time: _____ Depth to Water: _____

Sample I.D.: _____ Laboratory: STL Other: **Cal science**

Analyzed for: TPH-G BTEX MTBE TPH-D Other: **see COC**

EB I.D. (if applicable): _____ @ _____ Time Duplicate I.D. (if applicable): _____

Analyzed for: TPH-G BTEX MTBE TPH-D Other: _____

D.O. (if req'd):	Pre-purge:	mg/L	Post-purge:	mg/L
O.R.P. (if req'd):	Pre-purge:	mV	Post-purge:	mV

SHELL WELL MONITORING DATA SHEET

BTS #: 080805-WL1	Site: 8999 San Ramon Rd.
Sampler: WL	Date: 8/15/08
Well I.D.: MW-5B	Well Diameter: 2 3 ④ 6 8
Total Well Depth (TD): 66.93	Depth to Water (DTW): 32.21
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: PVC Grade	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]: 39.15	

Purge Method: Bailer Waterra Sampling Method: ~~Bailer~~
 Disposable Bailer Peristaltic Disposable Bailer
 Positive Air Displacement Extraction Pump Extraction Port
~~X~~ Electric Submersible Other _____ Dedicated Tubing

Other: _____

22.5 (Gals.) X 3 = 67.5 Gals.
 1 Case Volume Specified Volumes Calculated Volume

Well Diameter	Multiplier	Well Diameter	Multiplier
1"	0.04	4"	0.65
2"	0.16	6"	1.47
3"	0.37	Other	radius ² * 0.163

Time	Temp (°F)	pH	Cond. (mS or μ S)	Turbidity (NTUs)	Gals. Removed	Observations
1016	66.5	7.0	1148	127	22.5	
1020	67.1	7.0	1164	78	45	
1024	67.3	7.0	1166	43	67.5	

Did well dewater? Yes No Gallons actually evacuated: 67.5

Sampling Date: 8/15/08 Sampling Time: 1310 Depth to Water: 34.87

Sample I.D.: MW-5B Laboratory: STL Other: Cal science

Analyzed for: TPH-G BTEX MTBE TPH-D Other: see COC

EB I.D. (if applicable): @ Time Duplicate I.D. (if applicable):

Analyzed for: TPH-G BTEX MTBE TPH-D Other:

D.O. (if req'd):	Pre-purge:	mg/L	Post-purge:	mg/L
O.R.P. (if req'd):	Pre-purge:	mV	Post-purge:	mV

Blaine Tech Services, Inc. 1680 Rogers Ave., San Jose, CA 95112 (800) 545-7558

SHELL WELL MONITORING DATA SHEET

BTS #: 080805-WL1	Site: 8999 San Ramon Rd.
Sampler: WL	Date: 8/15/08
Well I.D.: MW-5C	Well Diameter: 2 3 4 6 8
Total Well Depth (TD): 99.93	Depth to Water (DTW): 37.30
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: PVC Grade	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]: 49.82	

Purge Method: Bailer Waterra Sampling Method: Bailer
 Disposable Bailer Peristaltic Disposable Bailer
 Positive Air Displacement Extraction Pump Extraction Port
 Electric Submersible Other _____ Dedicated Tubing

40 (Gals.) X 3 = 120 Gals. Case Volume Specified Volumes Calculated Volume	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Well Diameter</th> <th>Multiplier</th> <th>Well Diameter</th> <th>Multiplier</th> </tr> </thead> <tbody> <tr> <td>1"</td> <td>0.04</td> <td>4"</td> <td>0.65</td> </tr> <tr> <td>2"</td> <td>0.16</td> <td>6"</td> <td>1.47</td> </tr> <tr> <td>3"</td> <td>0.37</td> <td>Other</td> <td>radius² * 0.163</td> </tr> </tbody> </table>	Well Diameter	Multiplier	Well Diameter	Multiplier	1"	0.04	4"	0.65	2"	0.16	6"	1.47	3"	0.37	Other	radius ² * 0.163
Well Diameter	Multiplier	Well Diameter	Multiplier														
1"	0.04	4"	0.65														
2"	0.16	6"	1.47														
3"	0.37	Other	radius ² * 0.163														

Time	Temp (°F)	pH	Cond. (mS or µS)	Turbidity (NTUs)	Gals. Removed	Observations
1045	67.5	7.3	1229	663	40	cloudy
1053 ⁽⁴⁾	Well dewatered @ 75 gallons					
1101 ⁽⁴⁾						
1330	68.8	7.1	1192	105		

Did well dewater? Yes No Gallons actually evacuated: **75**

Sampling Date: **8/15/08** Sampling Time: **1330** Depth to Water: **40.17**

Sample I.D.: **MW-5C** Laboratory: STL Other: **Cal science**

Analyzed for: TPH-G BTEX MTBE TPH-D Other: **see COC**

EB I.D. (if applicable): _____ @ _____ Time Duplicate I.D. (if applicable): _____

Analyzed for: TPH-G BTEX MTBE TPH-D Other: _____

D.O. (if req'd):	Pre-purge:	mg/L	Post-purge:	mg/L
O.R.P. (if req'd):	Pre-purge:	mV	Post-purge:	mV

SHELL WELL MONITORING DATA SHEET

BTS #: 080805-WL1	Site: 8999 San Ramon Rd.
Sampler: WL	Date: 8/15/08
Well I.D.: MW-7	Well Diameter: 2 3 4 6 8
Total Well Depth (TD): 28.54	Depth to Water (DTW): Dry
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: PVC Grade	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]:	

Purge Method: Bailer Water Sampling Method: Bailer
 Disposable Bailer Peristaltic Disposable Bailer
 Positive Air Displacement Extraction Pump Extraction Port
 Electric Submersible Other _____ Dedicated Tubing

Other: _____

$$\frac{\text{I Case Volume (Gals.)} \times \text{Specified Volumes}}{\text{Calculated Volume}} = \text{Gals.}$$

Well Diameter	Multiplier	Well Diameter	Multiplier
1"	0.04	4"	0.65
2"	0.16	6"	1.47
3"	0.37	Other	radius ² * 0.163

Time	Temp (°F)	pH	Cond. (mS or µS)	Turbidity (NTUs)	Gals. Removed	Observations
Dry & unable to purge + sample						

Did well dewater? Yes No Gallons actually evacuated:

Sampling Date: **8/15/08** Sampling Time: Depth to Water:

Sample I.D.: Laboratory: STL Other **Cal science**

Analyzed for: TPH-G BTEX MTBE TPH-D Other: **see COC**

EB I.D. (if applicable): @ Duplicate I.D. (if applicable):

Analyzed for: TPH-G BTEX MTBE TPH-D Other:

D.O. (if req'd):	Pre-purge:	mg/L	Post-purge:	mg/L
O.R.P. (if req'd):	Pre-purge:	mV	Post-purge:	mV

SHELL WELL MONITORING DATA SHEET

BTS #: 080805-WL1	Site: 8999 San Ramon Rd.
Sampler: WL	Date: 8/15/08
Well I.D.: MW-8	Well Diameter: 2 3 (4) 6 8
Total Well Depth (TD): 28.83	Depth to Water (DTW): 26.62
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: (PVC) Grade	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]: 27.06	

Purge Method: Bailer Waterra Sampling Method: Bailer
 Disposable Bailer Peristaltic Disposable Bailer
 Positive Air Displacement Extraction Pump Extraction Port
 Electric Submersible Other _____ Dedicated Tubing
 Other: _____

1.4 (Gals.) X **3** = **4.2** Gals.
 Case Volume Specified Volumes Calculated Volume

Well Diameter	Multiplier	Well Diameter	Multiplier
1"	0.04	4"	0.65
2"	0.16	6"	1.47
3"	0.37	Other	radius ² * 0.163

Time	Temp (°F)	pH	Cond. (mS or (µS))	Turbidity (NTUs)	Gals. Removed	Observations
1002	Well dewatered @			1 gallon		
1255	68.8	7.1	947	198	—	

Did well dewater? Yes No Gallons actually evacuated: **1**

Sampling Date: **8/15/08** Sampling Time: **1255** Depth to Water: **26.71**

Sample I.D.: **MW-8** Laboratory: STL Other: **Cal science**

Analyzed for: TPH-G BTEX MTBE TPH-D Other: **see COC**

EB I.D. (if applicable): @ Time Duplicate I.D. (if applicable):

Analyzed for: TPH-G BTEX MTBE TPH-D Other:

D.O. (if req'd):	Pre-purge:	mg/L	Post-purge:	mg/L
O.R.P. (if req'd):	Pre-purge:	mV	Post-purge:	mV

SHELL WELL MONITORING DATA SHEET

BTS #: 080805-WL1	Site: 8999 San Ramon Rd.
Sampler: WL	Date: 8/5/08
Well I.D.: MW-88	Well Diameter: 2 3 4 6 8 _____
Total Well Depth (TD): 68.13	Depth to Water (DTW): 28.72
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: PVC Grade	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]: 36.60	

Purge Method: Bailer Waterra Sampling Method: Bailer
 Disposable Bailer Peristaltic Disposable Bailer
 Positive Air Displacement Extraction Pump Extraction Port
 Electric Submersible Other _____ Dedicated Tubing

25 (Gals.) X 3 = 75 Gals. 1 Case Volume Specified Volumes Calculated Volume	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th>Well Diameter</th> <th>Multiplier</th> <th>Well Diameter</th> <th>Multiplier</th> </tr> <tr> <td>1"</td> <td>0.04</td> <td>4"</td> <td>0.65</td> </tr> <tr> <td>2"</td> <td>0.16</td> <td>6"</td> <td>1.47</td> </tr> <tr> <td>3"</td> <td>0.37</td> <td>Other</td> <td>radius² * 0.163</td> </tr> </table>	Well Diameter	Multiplier	Well Diameter	Multiplier	1"	0.04	4"	0.65	2"	0.16	6"	1.47	3"	0.37	Other	radius ² * 0.163
Well Diameter	Multiplier	Well Diameter	Multiplier														
1"	0.04	4"	0.65														
2"	0.16	6"	1.47														
3"	0.37	Other	radius ² * 0.163														

Time	Temp (°F)	pH	Cond. (mS or μ S)	Turbidity (NTUs)	Gals. Removed	Observations
0944	66.1	7.1	952	110	25	cloudy
0949	65.9	6.9	974	178	50	↓
0954	67.2	6.7	973	162	75	

Did well dewater? Yes **No** Gallons actually evacuated: **75**

Sampling Date: **8/5/08** Sampling Time: **1240** Depth to Water: **29.05**

Sample I.D.: **MW-88** Laboratory: STL Other **cal science**

Analyzed for: TPH-G BTEX MTBE TPH-D Other: **see loc**

EB I.D. (if applicable): @ _____ Time Duplicate I.D. (if applicable): _____

Analyzed for: TPH-G BTEX MTBE TPH-D Other: _____

D.O. (if req'd): Pre-purge:	mg/L	Post-purge:	mg/L
O.R.P. (if req'd): Pre-purge:	mV	Post-purge:	mV

SHELL WELL MONITORING DATA SHEET

BTS #: 080805-WL1	Site: 8999 San Ramon Rd.
Sampler: WL	Date: 8/5/08
Well I.D.: MW-9	Well Diameter: 2 3 4 6 8
Total Well Depth (TD): 29.01	Depth to Water (DTW): 28.40
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: PVC Grade	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]:	

Purge Method: Bailer Disposable Bailer Positive Air Displacement Electric Submersible	Waterra Peristaltic Extraction Pump Other:	Sampling Method: Bailer Disposable Bailer Extraction Port Dedicated Tubing Other:
--	---	---

$(\text{Gals.}) \times \text{Specified Volumes} = \text{Calculated Volume}$ 1 Case Volume	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th>Well Diameter</th> <th>Multiplier</th> <th>Well Diameter</th> <th>Multiplier</th> </tr> <tr> <td>1"</td> <td>0.04</td> <td>4"</td> <td>0.65</td> </tr> <tr> <td>2"</td> <td>0.16</td> <td>6"</td> <td>1.47</td> </tr> <tr> <td>3"</td> <td>0.37</td> <td>Other</td> <td>radius² * 0.163</td> </tr> </table>	Well Diameter	Multiplier	Well Diameter	Multiplier	1"	0.04	4"	0.65	2"	0.16	6"	1.47	3"	0.37	Other	radius ² * 0.163
Well Diameter	Multiplier	Well Diameter	Multiplier														
1"	0.04	4"	0.65														
2"	0.16	6"	1.47														
3"	0.37	Other	radius ² * 0.163														

Time	Temp (°F)	pH	Cond. (mS or µS)	Turbidity (NTUs)	Gals. Removed	Observations
Insufficient water available to purge and sample						

Did well dewater? Yes No	Gallons actually evacuated:
Sampling Date: 8/5/08	Sampling Time: _____ Depth to Water: _____
Sample I.D.:	Laboratory: STL Other Cal science
Analyzed for: TPH-G BTEX MTBE TPH-D	Other: see loc
EB I.D. (if applicable): _____ @ _____ Time	Duplicate I.D. (if applicable): _____
Analyzed for: TPH-G BTEX MTBE TPH-D	Other: _____
D.O. (if req'd): Pre-purge: _____ mg/L	Post-purge: _____ mg/L
O.R.P. (if req'd): Pre-purge: _____ mV	Post-purge: _____ mV

SHELL WELL MONITORING DATA SHEET

BTS #: 080805-WL1	Site: 8999 San Ramon Rd.
Sampler: WL	Date: 8/5/08
Well I.D.: MW-11	Well Diameter: (2) 3 4 6 8
Total Well Depth (TD): 28.51	Depth to Water (DTW): Dry
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: PVC Grade	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]:	

Purge Method: Bailer Water: Peristaltic Sampling Method: Bailer
 Disposable Bailer Extraction Pump Disposable Bailer
 Positive Air Displacement Other: Extraction Port
 Electric Submersible Other: Dedicated Tubing

_____ (Gals.) X _____ = _____ Gals.
 1 Case Volume Specified Volumes Calculated Volume

Well Diameter	Multiplier	Well Diameter	Multiplier
1"	0.04	4"	0.65
2"	0.16	6"	1.47
3"	0.37	Other	radius ² * 0.163

Time	Temp (°F)	pH	Cond. (mS or µS)	Turbidity (NTUs)	Gals. Removed	Observations
Dry & unable to purge + sample						

Did well dewater? Yes No Gallons actually evacuated: _____

Sampling Date: **8/5/08** Sampling Time: _____ Depth to Water: _____

Sample I.D.: _____ Laboratory: STL Other: **Cal science**

Analyzed for: TPH-G BTEX MTBE TPH-D Other: **see loc**

EB I.D. (if applicable): _____ @ _____ Time Duplicate I.D. (if applicable): _____

Analyzed for: TPH-G BTEX MTBE TPH-D Other: _____

D.O. (if req'd):	Pre-purge:	_____ mg/L	Post-purge:	_____ mg/L
O.R.P. (if req'd):	Pre-purge:	_____ mV	Post-purge:	_____ mV

SHELL WELL MONITORING DATA SHEET

BTS #: 080805-WL1	Site: 8999 San Ramon Rd.
Sampler: WL	Date: 8/15/08
Well I.D.: MW-11B	Well Diameter: 2 3 4 6 8
Total Well Depth (TD): 38.83	Depth to Water (DTW): 33.51
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: PVC Grade	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]: 34.57	

Purge Method: Bailer Disposable Bailer Positive Air Displacement Electric Submersible

Watterra Peristaltic Extraction Pump Other _____

Sampling Method: Bailer Disposable Bailer Extraction Port Dedicated Tubing

Other: _____

3.4 (Gals.) X	3 Specified Volumes	= 10.2 Gals. Calculated Volume	
1 Case Volume			Well Diameter Multiplier Well Diameter Multiplier
			1" 0.04 4" 0.65
			2" 0.16 6" 1.47
			3" 0.37 Other radius ² * 0.163

Time	Temp (°F)	pH	Cond. (mS or µS)	Turbidity (NTUs)	Gals. Removed	Observations
0914	64.9	7.1	849	107	3.4	cloudy
0915	65.1	6.9	801	222	6.8	↓
0916	66.8	6.9	725	438	10.2	

Did well dewater? Yes No Gallons actually evacuated: **10.2**

Sampling Date: **8/15/08** Sampling Time: **1210** Depth to Water: **33.88**

Sample I.D.: **MW-11B** Laboratory: STL Other: **cal science**

Analyzed for: TPH-G BTEX MTBE TPH-D Other: **see COC**

EB I.D. (if applicable): @ Time Duplicate I.D. (if applicable):

Analyzed for: TPH-G BTEX MTBE TPH-D Other:

D.O. (if req'd):	Pre-purge:	mg/L	Post-purge:	mg/L
O.R.P. (if req'd):	Pre-purge:	mV	Post-purge:	mV

SHELL WELL MONITORING DATA SHEET

BTS #: 080805-WL1	Site: 8999 San Ramon Rd.
Sampler: WL	Date: 8/5/08
Well I.D.: MW-12	Well Diameter: 2 3 4 6 8 _____
Total Well Depth (TD): 38.81	Depth to Water (DTW): 33.29
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: PVC Grade	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]: 34.39	

Purge Method: Bailer	Waters: _____	Sampling Method: <input checked="" type="checkbox"/> Bailer
Disposible Bailer	Peristaltic	Disposible Bailer
Positive Air Displacement	Extraction Pump	Extraction Port
<input checked="" type="checkbox"/> Electric Submersible	Other: _____	Dedicated Tubing

3.6 (Gals.) X 3 = 10.8 Gals. 1 Case Volume Specified Volumes Calculated Volume	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Well Diameter</th> <th>Multiplier</th> <th>Well Diameter</th> <th>Multiplier</th> </tr> <tr> <td>1"</td> <td>0.04</td> <td>4"</td> <td>0.65</td> </tr> <tr> <td>2"</td> <td>0.16</td> <td>6"</td> <td>1.47</td> </tr> <tr> <td>3"</td> <td>0.37</td> <td>Other</td> <td>radius² * 0.163</td> </tr> </table>	Well Diameter	Multiplier	Well Diameter	Multiplier	1"	0.04	4"	0.65	2"	0.16	6"	1.47	3"	0.37	Other	radius ² * 0.163
Well Diameter	Multiplier	Well Diameter	Multiplier														
1"	0.04	4"	0.65														
2"	0.16	6"	1.47														
3"	0.37	Other	radius ² * 0.163														

Time	Temp (°F)	pH	Cond. (mS or μ S)	Turbidity (NTUs)	Gals. Removed	Observations
0924	65.8	6.9	704	737	3.6	cloudy
0924	65.9	6.7	699	71000	7.2	↓
0925	66.4	6.6	692	71000	10.8	

Did well dewater? Yes <input checked="" type="checkbox"/> No	Gallons actually evacuated: 10.8	
Sampling Date: 8/5/08	Sampling Time: 1225	Depth to Water: 33.73
Sample I.D.: MW-12	Laboratory: STL Other cal science	
Analyzed for: TPH-G BTEX MTBE TPH-D Other: see coc		
EB I.D. (if applicable): @ _____ Time	Duplicate I.D. (if applicable):	
Analyzed for: TPH-G BTEX MTBE TPH-D Other:		
D.O. (if req'd): Pre-purge: _____ mg/L	Post-purge: _____ mg/L	
O.R.P. (if req'd): Pre-purge: _____ mV	Post-purge: _____ mV	

APPENDIX B

FIELD PROCEDURES

BLAINE
TECH SERVICES INC.

GROUNDWATER SAMPLING SPECIALISTS
SINCE 1985

August 26, 2008

Denis Brown
Shell Oil Products US
20945 South Wilmington Avenue
Carson, CA 90810

Third Quarter 2008 Groundwater Monitoring at
Shell-branded Service Station
8999 San Ramon Road
Dublin, CA

Monitoring performed on August 5, 2008

Groundwater Monitoring Report **080805-WL-1**

This report covers the routine monitoring of groundwater wells at this Shell-branded facility. In accordance with standard procedures that conform to Regional Water Quality Control Board requirements, routine field data collection includes depth to water, total well depth, thickness of any separate immiscible layer, water column volume, calculated purge volume (if applicable), elapsed evacuation time (if applicable), total volume of water removed (if applicable), and standard water parameter instrument readings. Sample material is collected, contained, stored, and transported to the laboratory in conformance with EPA standards. Purgewater (if applicable) is, likewise, collected and transported to the Martinez Refining Company.

Basic field information is presented alongside analytical values excerpted from the laboratory report in the cumulative table of **WELL CONCENTRATIONS**. The full analytical report for the most recent samples and the field data sheets are attached to this report.

At a minimum, Blaine Tech Services, Inc. field personnel are certified on completion of a forty-hour Hazardous Materials and Emergency Response training course per 29 CFR 1910.120. Field personnel are also enrolled in annual eight-hour refresher courses.

Blaine Tech Services, Inc. conducts sampling and documentation assignments of this type as an independent third party. Our activities at this site consisted of objective data and sample collection only. No interpretation of analytical results, defining of hydrological conditions or formulation of recommendations was performed.

Please call if you have any questions.

Yours truly,

Mike Ninokata
Project Manager

MN/tm

attachments: Cumulative Table of WELL CONCENTRATIONS
Certified Analytical Report
Field Data Sheets

cc: Rich Garlow
Delta Environmental
175 Bernal Road, Suite 200
San Jose, CA 95119

BLAINE TECH SERVICES, INC. METHODS AND PROCEDURES FOR THE ROUTINE MONITORING OF GROUNDWATER WELLS AT SHELL SITES

Blaine Tech Services, Inc. performs environmental sampling and documentation as an independent third party. We specialize in groundwater monitoring assignments and intentionally limit the scope of our services to those centered on the generation of objective information.

To avoid conflicts of interest, Blaine Tech Services, Inc. personnel do not evaluate or interpret the information we collect. As a state licensed contractor (C-57 well drilling -water - 746684) performing strictly technical services, we do not make any professional recommendations and perform no consulting of any kind.

SAMPLING PROCEDURES OVERVIEW

SAFETY

All groundwater monitoring assignments performed for Shell comply with Shell's safety guidelines, 29 CFR 1910.120 and SB-198 Injury and Illness Prevention Program (IIPP). All Field Technicians receive the full 40-hour 29CFR 1910.120 OSHA SARA HAZWOPER course, medical clearance and on-the-job training prior to commencing any work on any Shell site.

INSPECTION AND GAUGING

Wells are inspected prior to evacuation and sampling. The condition of the wellhead is checked and noted according to a wellhead inspection checklist.

Standard measurements include the depth to water (DTW) and the total well depth (TD) obtained with industry standard electronic water level indicators that are graduated in increments of hundredths of a foot.

The water in each well is inspected for the presence of immiscibles. When free product is suspected, its presence is confirmed using an electronic interface probe (e.g. MMC). No samples are collected from a well containing over two-hundredths of a foot (0.02') of product.

EVACUATION

Depth to water measurements are collected by our personnel prior to purging and minimum purge volumes are calculated anew for each well based on the height of the water column and the diameter of the well. Expected purge volumes are never less than three case volumes and are set at no less than four case volumes in some jurisdictions.

Well purging devices are selected on the basis of the well diameter and the total volume to be evacuated. In most cases the well will be purged using an electric submersible pump (i.e. Grundfos) suspended near (but not touching) the bottom of the well.

PARAMETER STABILIZATION

Well purging completion standards include minimum purge volumes, but additionally require stabilization of specific groundwater parameters prior to sample collection. Typical groundwater parameters used to measure stability are electrical conductivity, pH, and temperature. Instrument readings are obtained at regular intervals during the evacuation process (no less than once per case volume).

Stabilization standards for routine quarterly monitoring of fuel sites include the following: Temperature is considered to have stabilized when successive readings do not fluctuate more than +/- 1 degree Celsius. Electrical conductivity is considered stable when successive readings are within 10%. pH is considered to be stable when successive readings remain constant or vary no more than 0.2 of a pH unit.

DEWATERED WELLS

Normal evacuation removes no less than three case volumes of water from the well. However, less water may be removed in cases where the well dewateres and does not immediately recharge.

MEASURING RECHARGE

Upon completion of well purging, a depth to water measurement is collected and notated to ensure that the well has recharged to within 80% of its static, pre-purge level prior to sampling.

Wells that do not immediately show 80% recharge or dewatered wells will be allowed a minimum of 2 hours to recharge prior to sampling. The water level at time of sampling will be noted.

PURGEWATER CONTAINMENT

All non-hazardous purgewater evacuated from each groundwater monitoring well is captured and contained in on-board storage tanks on the Sampling Vehicle and/or special water hauling trailers. Effluent from the decontamination of reusable apparatus (sounders, electric pumps and hoses etc.), consisting of groundwater combined with deionized water and non-phosphate soap, is also captured and pumped into effluent tanks.

Non-hazardous purgewater is transported under standard Bill of Lading documentation to a Blaine Tech Services, Inc. facility before being transported to a Shell approved disposal facility.

SAMPLE COLLECTION DEVICES

All samples are collected using a stainless steel, Teflon or disposable ballers.

SAMPLE CONTAINERS

Sample material is decanted directly from the sampling baller into sample containers provided by the laboratory that will analyze the samples. The transfer of sample material from the baller to the sample container conforms to specifications contained in the USEPA T.E.G.D. The type of sample container, material of construction, method of closure and filling requirements are specific to the intended analysis. Chemicals needed to preserve the sample material are commonly placed inside the sample containers by the laboratory or glassware vendor prior to delivery of the bottle to our personnel. The laboratory sets the number of replicate containers.

TRIP BLANKS

Trip Blanks, if requested, are taken to the site and kept inside the sample cooler for the duration of the event. They are turned over to the laboratory for analysis with the samples from that site.

DUPLICATES

Duplicates, if requested, may be collected at a site. The Field Technician uses their discretion in choosing the well at which the Duplicate is collected, typically one suspected of containing measurable contaminants. The Duplicate sample is labeled "DUP" and the time of collection is omitted from the COC, thus rendering the sample blind.

SAMPLE STORAGE

All sample containers are promptly placed in food grade ice chests for storage in the field and transport (direct or via our facility) to the designated analytical laboratory. These ice chests contain quantities of restaurant grade ice as a refrigerant material. The samples are maintained in either an ice chest or a refrigerator until relinquished into the custody of the laboratory or laboratory courier.

DOCUMENTATION CONVENTIONS

A label must be affixed to all sample containers. In most cases these labels are generated by our office personnel and are partially preprinted. Labels can also be hand written by our field personnel. The site is identified with the store number and site address, as is the particular groundwater well from which the sample is drawn (e.g. MW-1, MW-2, S-1 etc.). The time and date of sample collection along with the initials of the person who collects the sample are handwritten onto the label.

Chain of Custody records are created using client specific preprinted forms following USEPA specifications.

Bill of Lading records are contemporaneous records created in the field at the site where the non-hazardous purgewater is generated. Field Technicians use preprinted Bill of Lading forms.

DECONTAMINATION

All equipment is brought to the site in clean and serviceable condition and is cleaned after use in each well and before subsequent use in any other well. Equipment is decontaminated before leaving the site.

The primary decontamination device is a commercial steam cleaner. The steam cleaner is detuned to function as a hot pressure washer that is then operated with high quality deionized water that is produced at our facility and stored onboard our sampling vehicle. Cleaning is facilitated by the use of proprietary fixtures and devices included in the patented workstation (U.S. Patent 5,535,775) that is incorporated in each sampling vehicle. The steam cleaner is used to decon reels, pumps and bailers.

Any sensitive equipment or parts (i.e. Dissolved Oxygen sensor membrane, water level indicator, etc.) that cannot be washed using the high pressure water, will be sprayed with a non-phosphate soap and deionized water solution and rinsed with deionized water.

DISSOLVED OXYGEN READINGS

Dissolved Oxygen readings are taken pre- and/or post-purge using YSI meters (e.g. YSI Model 54, 58 or 95) or HACH field test kits.

The YSI meters are equipped with a stirring device that enables them to collect accurate in-situ readings. The probe/stirring devices are modified to allow downhole measurements to be taken from wells with diameters as small as two inches. The probe and reel is decontaminated between wells as described above. The meter is calibrated between wells as per the instructions in the operating manual. The probe and stirrer is lowered into the water column. The reading is allowed to stabilize prior to collection.

OXYIDATON REDUCTION POTENTIAL READINGS


All readings are obtained with either Corning or Myron-L meters (e.g. Corning ORP-65 or a Myron-L Ultrameter GP). The meter is cleaned between wells as described above. The meter is calibrated at the start of each day according to the instruction manual.

FERROUS IRON MEASUREMENTS

All field measurements are collected at time of sampling with a HACH test kit.

APPENDIX C

LABORATORY REPORT AND CHAIN-OF-CUSTODY DOCUMENTATION



August 20, 2008

Michael Ninokata
Blaine Tech Services, Inc.
1680 Rogers Avenue
San Jose, CA 95112-1105

Subject: **Calscience Work Order No.:** 08-08-0535
Client Reference: 8999 San Ramon Road, Dublin, CA

Dear Client:

Enclosed is an analytical report for the above-referenced project. The samples included in this report were received 8/7/2008 and analyzed in accordance with the attached chain-of-custody.


Unless otherwise noted, all analytical testing was accomplished in accordance with the guidelines established in our Quality Systems Manual, applicable standard operating procedures, and other related documentation. The original report of subcontracted analysis, if any, is provided herein, and follows the standard Calscience data package. The results in this analytical report are limited to the samples tested and any reproduction thereof must be made in its entirety.

If you have any questions regarding this report, please do not hesitate to contact the undersigned.

Sincerely,

A handwritten signature in black ink, appearing to read "Jessie Kim".

Calscience Environmental
Laboratories, Inc.
Jessie Kim
Project Manager



Analytical Report



Blaine Tech Services, Inc.
1680 Rogers Avenue
San Jose, CA 95112-1105

Date Received: 08/07/08
Work Order No: 08-08-0535
Preparation: EPA 3510C
Method: EPA 8015B

Project: 8999 San Ramon Road, Dublin, CA

Page 1 of 3

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW-5B	08-08-0535-1-D	08/05/08 13:10	Aqueous	GC 15	08/12/08	08/14/08 00:31	080812B18

Comment(s):
-The sample extract was subjected to Silica Gel treatment prior to analysis.
-TPH as Diesel is quantified in the carbon range C10-C28.

Parameter	Result	RL	DF	Qual	Units
Diesel Range Organics	140	50	1		ug/L
<u>Surrogates:</u>	<u>REC (%)</u>	<u>Control Limits</u>		<u>Qual</u>	
Decachlorobiphenyl	119	68-140			

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW-5C	08-08-0535-2-D	08/05/08 13:30	Aqueous	GC 15	08/12/08	08/14/08 01:08	080812B18

Comment(s):
-The sample extract was subjected to Silica Gel treatment prior to analysis.
-TPH as Diesel is quantified in the carbon range C10-C28.


Parameter	Result	RL	DF	Qual	Units
Diesel Range Organics	ND	50	1		ug/L
<u>Surrogates:</u>	<u>REC (%)</u>	<u>Control Limits</u>		<u>Qual</u>	
Decachlorobiphenyl	103	68-140			

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW-8	08-08-0535-3-D	08/05/08 12:55	Aqueous	GC 15	08/12/08	08/14/08 13:46	080812B18

Comment(s):
-The sample extract was subjected to Silica Gel treatment prior to analysis.
-TPH as Diesel is quantified in the carbon range C10-C28.

Parameter	Result	RL	DF	Qual	Units
Diesel Range Organics	ND	50	1		ug/L
<u>Surrogates:</u>	<u>REC (%)</u>	<u>Control Limits</u>		<u>Qual</u>	
Decachlorobiphenyl	115	68-140			

RL - Reporting Limit , DF - Dilution Factor , Qual - Qualifiers



Analytical Report



Blaine Tech Services, Inc.
1680 Rogers Avenue
San Jose, CA 95112-1105

Date Received: 08/07/08
Work Order No: 08-08-0535
Preparation: EPA 3510C
Method: EPA 8015B

Project: 8999 San Ramon Road, Dublin, CA

Page 2 of 3

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW-8B	08-08-0535-4-D	08/05/08 12:40	Aqueous	GC 15	08/12/08	08/14/08 02:19	080812B18

Comment(s): -The sample extract was subjected to Silica Gel treatment prior to analysis.
-TPH as Diesel is quantified in the carbon range C10-C28.

Parameter	Result	RL	DF	Qual	Units
Diesel Range Organics	ND	50	1		ug/L
Surrogates:	REC (%)	Control Limits		Qual	
Decachlorobiphenyl	120	68-140			

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW-11B	08-08-0535-5-D	08/05/08 12:10	Aqueous	GC 15	08/12/08	08/14/08 02:55	080812B18

Comment(s): -The sample extract was subjected to Silica Gel treatment prior to analysis.
-TPH as Diesel is quantified in the carbon range C10-C28.


Parameter	Result	RL	DF	Qual	Units
Diesel Range Organics	ND	50	1		ug/L
Surrogates:	REC (%)	Control Limits		Qual	
Decachlorobiphenyl	112	68-140			

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW-12	08-08-0535-6-D	08/05/08 12:25	Aqueous	GC 15	08/12/08	08/14/08 03:30	080812B18

Comment(s): -The sample extract was subjected to Silica Gel treatment prior to analysis.
-TPH as Diesel is quantified in the carbon range C10-C28.

Parameter	Result	RL	DF	Qual	Units
Diesel Range Organics	ND	50	1		ug/L
Surrogates:	REC (%)	Control Limits		Qual	
Decachlorobiphenyl	112	68-140			

RL - Reporting Limit , DF - Dilution Factor , Qual - Qualifiers



Analytical Report



Blaine Tech Services, Inc.
1680 Rogers Avenue
San Jose, CA 95112-1105

Date Received: 08/07/08
Work Order No: 08-08-0535
Preparation: EPA 3510C
Method: EPA 8015B

Project: 8999 San Ramon Road, Dublin, CA

Page 3 of 3

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
Method Blank	099-12-211-581	N/A	Aqueous	GC 15	08/12/08	08/13/08 16:44	080812B18

Parameter	Result	RL	DF	Qual	Units
Diesel Range Organics	ND	50	1		ug/L
<u>Surrogates:</u>	<u>REC (%)</u>	<u>Control Limits</u>		<u>Qual</u>	
Decachlorobiphenyl	106	68-140			

RL - Reporting Limit , DF - Dilution Factor , Qual - Qualifiers

Analytical Report



Blaine Tech Services, Inc.
 1680 Rogers Avenue
 San Jose, CA 95112-1105

Date Received: 08/07/08
 Work Order No: 08-08-0535
 Preparation: EPA 5030B
 Method: LUFT GC/MS / EPA 8260B
 Units: ug/L

Project: 8999 San Ramon Road, Dublin, CA

Page 1 of 3

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW-5B	08-08-0535-1-A	08/05/08 13:10	Aqueous	GC/MS LL	08/08/08	08/09/08 06:33	080808L02

Parameter	Result	RL	DF	Qual	Parameter	Result	RL	DF	Qual
TPPH	470	250	5		Methyl-t-Butyl Ether (MTBE)	430	5.0	5	
Benzene	ND	2.5	5		Tert-Butyl Alcohol (TBA)	ND	50	5	
Ethylbenzene	ND	5.0	5		Diisopropyl Ether (DIPE)	ND	10	5	
Toluene	ND	5.0	5		Ethyl-t-Butyl Ether (ETBE)	ND	10	5	
p/m-Xylene	ND	5.0	5		Tert-Amyl-Methyl Ether (TAME)	ND	10	5	
o-Xylene	ND	5.0	5						
Surrogates:	REC (%)	Control Limits		Qual	Surrogates:	REC (%)	Control Limits		Qual
1,4-Bromofluorobenzene	91	70-130			1,4-Bromofluorobenzene-TPPH	91	70-130		

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW-5C	08-08-0535-2-A	08/05/08 13:30	Aqueous	GC/MS LL	08/08/08	08/09/08 06:57	080808L02

Parameter	Result	RL	DF	Qual	Parameter	Result	RL	DF	Qual
TPPH	210	100	2		Methyl-t-Butyl Ether (MTBE)	180	2.0	2	
Benzene	ND	1.0	2		Tert-Butyl Alcohol (TBA)	ND	20	2	
Ethylbenzene	ND	2.0	2		Diisopropyl Ether (DIPE)	ND	4.0	2	
Toluene	ND	2.0	2		Ethyl-t-Butyl Ether (ETBE)	ND	4.0	2	
p/m-Xylene	ND	2.0	2		Tert-Amyl-Methyl Ether (TAME)	ND	4.0	2	
o-Xylene	ND	2.0	2						
Surrogates:	REC (%)	Control Limits		Qual	Surrogates:	REC (%)	Control Limits		Qual
1,4-Bromofluorobenzene	89	70-130			1,4-Bromofluorobenzene-TPPH	89	70-130		

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW-8	08-08-0535-3-A	08/05/08 12:55	Aqueous	GC/MS LL	08/08/08	08/09/08 07:22	080808L02

Parameter	Result	RL	DF	Qual	Parameter	Result	RL	DF	Qual
TPPH	ND	50	1		Methyl-t-Butyl Ether (MTBE)	ND	1.0	1	
Benzene	ND	0.50	1		Tert-Butyl Alcohol (TBA)	34	10	1	
Ethylbenzene	ND	1.0	1		Diisopropyl Ether (DIPE)	ND	2.0	1	
Toluene	ND	1.0	1		Ethyl-t-Butyl Ether (ETBE)	ND	2.0	1	
p/m-Xylene	ND	1.0	1		Tert-Amyl-Methyl Ether (TAME)	ND	2.0	1	
o-Xylene	ND	1.0	1						
Surrogates:	REC (%)	Control Limits		Qual	Surrogates:	REC (%)	Control Limits		Qual
1,4-Bromofluorobenzene	92	70-130			1,4-Bromofluorobenzene-TPPH	92	70-130		

RL - Reporting Limit , DF - Dilution Factor , Qual - Qualifiers

Analytical Report



Blaine Tech Services, Inc.
 1680 Rogers Avenue
 San Jose, CA 95112-1105

Date Received: 08/07/08
 Work Order No: 08-08-0535
 Preparation: EPA 5030B
 Method: LUFT GC/MS / EPA 8260B
 Units: ug/L

Project: 8999 San Ramon Road, Dublin, CA

Page 2 of 3

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW-8B	08-08-0535-4-A	08/05/08 12:40	Aqueous	GC/MS LL	08/08/08	08/09/08 07:46	080808L02

Parameter	Result	RL	DF	Qual	Parameter	Result	RL	DF	Qual
TPPH	ND	50	1		Methyl-t-Butyl Ether (MTBE)	11	1.0	1	
Benzene	ND	0.50	1		Tert-Butyl Alcohol (TBA)	ND	10	1	
Ethylbenzene	ND	1.0	1		Diisopropyl Ether (DIPE)	ND	2.0	1	
Toluene	ND	1.0	1		Ethyl-t-Butyl Ether (ETBE)	ND	2.0	1	
p/m-Xylene	ND	1.0	1		Tert-Amyl-Methyl Ether (TAME)	ND	2.0	1	
o-Xylene	ND	1.0	1						
Surrogates:	REC (%)	Control Limits		Qual	Surrogates:	REC (%)	Control Limits		Qual
1,4-Bromofluorobenzene	91	70-130			1,4-Bromofluorobenzene-TPPH	91	70-130		


Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW-11B	08-08-0535-5-A	08/05/08 12:10	Aqueous	GC/MS LL	08/08/08	08/09/08 08:10	080808L02

Parameter	Result	RL	DF	Qual	Parameter	Result	RL	DF	Qual
TPPH	ND	50	1		Methyl-t-Butyl Ether (MTBE)	ND	1.0	1	
Benzene	ND	0.50	1		Tert-Butyl Alcohol (TBA)	ND	10	1	
Ethylbenzene	ND	1.0	1		Diisopropyl Ether (DIPE)	ND	2.0	1	
Toluene	ND	1.0	1		Ethyl-t-Butyl Ether (ETBE)	ND	2.0	1	
p/m-Xylene	ND	1.0	1		Tert-Amyl-Methyl Ether (TAME)	ND	2.0	1	
o-Xylene	ND	1.0	1						
Surrogates:	REC (%)	Control Limits		Qual	Surrogates:	REC (%)	Control Limits		Qual
1,4-Bromofluorobenzene	92	70-130			1,4-Bromofluorobenzene-TPPH	91	70-130		

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
MW-12	08-08-0535-6-A	08/05/08 12:25	Aqueous	GC/MS LL	08/08/08	08/09/08 08:34	080808L02

Parameter	Result	RL	DF	Qual	Parameter	Result	RL	DF	Qual
TPPH	ND	50	1		Methyl-t-Butyl Ether (MTBE)	ND	1.0	1	
Benzene	ND	0.50	1		Tert-Butyl Alcohol (TBA)	ND	10	1	
Ethylbenzene	ND	1.0	1		Diisopropyl Ether (DIPE)	ND	2.0	1	
Toluene	ND	1.0	1		Ethyl-t-Butyl Ether (ETBE)	ND	2.0	1	
p/m-Xylene	ND	1.0	1		Tert-Amyl-Methyl Ether (TAME)	ND	2.0	1	
o-Xylene	ND	1.0	1						
Surrogates:	REC (%)	Control Limits		Qual	Surrogates:	REC (%)	Control Limits		Qual
1,4-Bromofluorobenzene	92	70-130			1,4-Bromofluorobenzene-TPPH	92	70-130		

RL - Reporting Limit , DF - Dilution Factor , Qual - Qualifiers



Analytical Report



Blaine Tech Services, Inc.
1680 Rogers Avenue
San Jose, CA 95112-1105

Date Received: 08/07/08
Work Order No: 08-08-0535
Preparation: EPA 5030B
Method: LUFT GC/MS / EPA 8260B
Units: ug/L


Project: 8999 San Ramon Road, Dublin, CA

Page 3 of 3

Client Sample Number	Lab Sample Number	Date/Time Collected	Matrix	Instrument	Date Prepared	Date/Time Analyzed	QC Batch ID
Method Blank	099-12-715-740	N/A	Aqueous	GC/MS LL	08/08/08	08/09/08 00:56	080808L02

Parameter	Result	RL	DF	Qual	Parameter	Result	RL	DF	Qual
TPPH	ND	50	1		Methyl-t-Butyl Ether (MTBE)	ND	1.0	1	
Benzene	ND	0.50	1		Tert-Butyl Alcohol (TBA)	ND	10	1	
Ethylbenzene	ND	1.0	1		Diisopropyl Ether (DIPE)	ND	2.0	1	
Toluene	ND	1.0	1		Ethyl-t-Butyl Ether (ETBE)	ND	2.0	1	
p/m-Xylene	ND	1.0	1		Tert-Amyl-Methyl Ether (TAME)	ND	2.0	1	
o-Xylene	ND	1.0	1						
<u>Surrogates:</u>	<u>REC (%)</u>	<u>Control Limits</u>		<u>Qual</u>	<u>Surrogates:</u>	<u>REC (%)</u>	<u>Control Limits</u>		<u>Qual</u>
1,4-Bromofluorobenzene	94	70-130			1,4-Bromofluorobenzene-TPPH	94	70-130		

RL - Reporting Limit , DF - Dilution Factor , Qual - Qualifiers



Quality Control - Spike/Spike Duplicate



Blaine Tech Services, Inc.
1680 Rogers Avenue
San Jose, CA 95112-1105


Date Received: 08/07/08
Work Order No: 08-08-0535
Preparation: EPA 5030B
Method: LUFT GC/MS / EPA
8260B

Project 8999 San Ramon Road, Dublin, CA

Quality Control Sample ID	Matrix	Instrument	Date Prepared	Date Analyzed	MS/MSD Batch Number
08-08-0531-1	Aqueous	GC/MS LL	08/08/08	08/09/08	080808S02

Parameter	MS %REC	MSD %REC	%REC CL	RPD	RPD CL	Qualifiers
Benzene	118	116	70-130	2	0-30	
Ethylbenzene	126	123	70-130	2	0-30	
Toluene	122	121	70-130	1	0-30	
p/m-Xylene	130	129	70-130	1	0-30	
o-Xylene	129	127	70-130	1	0-30	
Methyl-t-Butyl Ether (MTBE)	114	110	70-130	1	0-30	
Tert-Butyl Alcohol (TBA)	116	115	70-130	0	0-30	
Diisopropyl Ether (DIPE)	111	110	70-130	1	0-30	
Ethyl-t-Butyl Ether (ETBE)	104	105	70-130	1	0-30	
Tert-Amyl-Methyl Ether (TAME)	101	103	70-130	1	0-30	
Ethanol	137	134	70-130	2	0-30	3

RPD - Relative Percent Difference, CL - Control Limit



Quality Control - LCS/LCS Duplicate



Blaine Tech Services, Inc.
 1680 Rogers Avenue
 San Jose, CA 95112-1105


Date Received: N/A
 Work Order No: 08-08-0535
 Preparation: EPA 3510C
 Method: EPA 8015B

Project: 8999 San Ramon Road, Dublin, CA

Quality Control Sample ID	Matrix	Instrument	Date Prepared	Date Analyzed	LCS/LCSD Batch Number
099-12-211-581	Aqueous	GC 15	08/12/08	08/13/08	080812B18

Parameter	LCS %REC	LCSD %REC	%REC CL	RPD	RPD CL	Qualifiers
Diesel Range Organics	110	117	75-117	7	0-13	

RPD - Relative Percent Difference , CL - Control Limit



Quality Control - LCS/LCS Duplicate



Blaine Tech Services, Inc.
1680 Rogers Avenue
San Jose, CA 95112-1105


Date Received: N/A
Work Order No: 08-08-0535
Preparation: EPA 5030B
Method: LUFT GC/MS / EPA 8260B

Project: 8999 San Ramon Road, Dublin, CA

Quality Control Sample ID	Matrix	Instrument	Date Prepared	Date Analyzed	LCS/LCSD Batch Number
099-12-715-740	Aqueous	GC/MS LL	08/08/08	08/08/08	080808L02

Parameter	LCS %REC	LCSD %REC	%REC CL	RPD	RPD CL	Qualifiers
TPPH	111	111	65-135	0	0-30	
Benzene	111	111	70-130	1	0-30	
Ethylbenzene	120	121	70-130	1	0-30	
Toluene	116	118	70-130	2	0-30	
p/m-Xylene	124	125	70-130	0	0-30	
o-Xylene	123	125	70-130	2	0-30	
Methyl-t-Butyl Ether (MTBE)	106	108	70-130	1	0-30	
Tert-Butyl Alcohol (TBA)	120	118	70-130	2	0-30	
Diisopropyl Ether (DIPE)	107	108	70-130	0	0-30	
Ethyl-t-Butyl Ether (ETBE)	102	104	70-130	2	0-30	
Tert-Amyl-Methyl Ether (TAME)	101	103	70-130	2	0-30	
Ethanol	125	120	70-130	4	0-30	

RPD - Relative Percent Difference, CL - Control Limit



Work Order Number: 08-08-0535

<u>Qualifier</u>	<u>Definition</u>
*	See applicable analysis comment.
1	Surrogate compound recovery was out of control due to a required sample dilution, therefore, the sample data was reported without further clarification.
2	Surrogate compound recovery was out of control due to matrix interference. The associated method blank surrogate spike compound was in control and, therefore, the sample data was reported without further clarification.
3	Recovery of the Matrix Spike (MS) or Matrix Spike Duplicate (MSD) compound was out of control due to matrix interference. The associated LCS and/or LCSD was in control and, therefore, the sample data was reported without further clarification.
4	The MS/MSD RPD was out of control due to matrix interference. The LCS/LCSD RPD was in control and, therefore, the sample data was reported without further clarification.
5	The PDS/PDSD associated with this batch of samples was out of control due to a matrix interference effect. The associated batch LCS/LCSD was in control and, hence, the associated sample data was reported with no further corrective action required.
A	Result is the average of all dilutions, as defined by the method.
B	Analyte was present in the associated method blank.
C	Analyte presence was not confirmed on primary column.
E	Concentration exceeds the calibration range.
H	Sample received and/or analyzed past the recommended holding time.
J	Analyte was detected at a concentration below the reporting limit and above the laboratory method detection limit. Reported value is estimated.
ME	A Marginal Exceedance (ME) is defined as a LCS percent recovery beyond the normal 3 standard deviation Control Limits but still within the marginal exceedance limits (set at 4 standard deviations from the mean)
N	Nontarget Analyte.
ND	Parameter not detected at the indicated reporting limit.
Q	Spike recovery and RPD control limits do not apply resulting from the parameter concentration in the sample exceeding the spike concentration by a factor of four or greater.
U	Undetected at the laboratory method detection limit.
X	% Recovery and/or RPD out-of-range.
Z	Analyte presence was not confirmed by second column or GC/MS analysis.

A handwritten signature in black ink, appearing to be a stylized name.

LAB (LOCATION)

- CALSCIENCE ()
- SPL ()
- XENCO ()
- TEST AMERICA ()
- OTHER ()



Shell Oil Products Chain Of Custody Record

Please Check Appropriate Box:

<input checked="" type="checkbox"/> ENV. SERVICES	<input type="checkbox"/> MOTIVA RETAIL	<input type="checkbox"/> SHELL RETAIL
<input type="checkbox"/> MOTIVA SD&GH	<input type="checkbox"/> CONSULTANT	<input type="checkbox"/> LUBES
<input type="checkbox"/> SHELL PIPELINE	<input type="checkbox"/> OTHER	

Print Bill To Contact Name: **Denis Brown**

INCIDENT # (ENV SERVICES): **9 7 5 6 5 9 9 5**

PO #: _____ SAP #: _____

CHECK IF NO INCIDENT # APPLIES

DATE: **8/5/08**

PAGE: **1** of **1**

SAMPLING COMPANY: **Blaine Tech Services**

LOG CODE: **BTSS**

ADDRESS: **1680 Rogers Ave, San Jose, CA 95112**

SITE ADDRESS: Street and City: **8999 San Ramon Road, Dublin**

State: **CA** GLOBAL ID NO.: **T0600159797**

BDP DELIVERABLE TO (Name, Company, Office Location): **Jon Suling, Delta, Monrovia Office**

PHONE NO.: **626.256.6662** EMAIL: **jsuling@deltanv.com**

CONSULTANT PROJECT NO: **BTS # 080805-WL1**

PROJECT CONTACT (Hardcopy or PDF Report): **Michael Ninokata**

TELEPHONE: **(408)573-8555** FAX: **(408)573-7771** EMAIL: **mninokata@blainetech.com**

SAMPLER NAME(S) (PRINT): **Will Lampe**

LAB USE ONLY: **08-0535**

TURNAROUND TIME (CALENDAR DAYS):

STANDARD (14 DAY) 5 DAYS 3 DAYS 2 DAYS 24 HOURS

RESULTS NEEDED ON WEEKEND

LA - RWQCB REPORT FORMAT UST AGENCY:

REQUESTED ANALYSIS

SPECIAL INSTRUCTIONS OR NOTES :

Run TPH-d w/Silica Gel Clean Up

SHELL CONTRACT RATE APPLIES

STATE REIMBURSEMENT RATE APPLIES

EDD NOT NEEDED


RECEIPT VERIFICATION REQUESTED

LAB USE ONLY	Field Sample Identification	SAMPLING		MATRIX	PRESERVATIVE					NO. OF CONT.	TPH - Purgeable (8260B)	TPH - Extractable (8015M)	BTEX (8260B)	5 Oxygenates (8260B)	MTBE (8260B)	TBA (8260B)	DIPE (8260B)	TAME (8260B)	ETBE (8260B)	1,2 DCA (8260B)	EDB (8260B)	Ethanol (8260B)	Methanol (8015M)	TEMPERATURE ON RECEIPT °C	Container PID Readings or Laboratory Notes
		DATE	TIME		HCL	HNO3	H2SO4	NONE	OTHER																
	MW-5B	8/5	1310	W	3			2	5	X	X	X	X												
	MW-5C		1330	W	3			2	5	X	X	X	X												
	MW-8		1255	W	3			2	5	X	X	X	X												
	MW-8B		1240	W	3			2	5	X	X	X	X												
	MW-11B		1210	W	3			2	5	X	X	X	X												
	MW-12		1225	W	3			2	5	X	X	X	X												

Relinquished by: (Signature) <i>[Signature]</i>	Received by: (Signature) <i>[Signature]</i> (sample custodian)	Date: 8/5/08	Time: 1525
Relinquished by: (Signature) <i>[Signature]</i> (Sample Custodian)	Received by: (Signature) <i>[Signature]</i> CEL	Date: 8-6-08	Time: 1305
Relinquished by: (Signature) <i>[Signature]</i> CO 8608	Received by: (Signature) <i>[Signature]</i> CEL	Date: 8-7-08	Time: 1630

510130761

05/2/08 Revision



WORK ORDER #: 08 - 08 - 0535

Cooler 1 of 1

SAMPLE RECEIPT FORM

CLIENT: Blaine Beck

DATE: 8/7/08

TEMPERATURE - SAMPLES RECEIVED BY:

CALSCIENCE COURIER:

- Chilled, cooler with temperature blank provided.
Chilled, cooler without temperature blank.
Chilled and placed in cooler with wet ice.
Ambient and placed in cooler with wet ice.
Ambient temperature (For Air & Filter Only).
°C Temperature blank.

LABORATORY (Other than CalScience Courier):

- 3.4 °C Temperature blank.
°C IR Thermometer.
Ambient temperature (For Air & Filter Only).

Initial: JB

CUSTODY SEAL INTACT:

Sample(s): Cooler: No (Not Intact): Not Present: [checked]

Initial: JB

SAMPLE CONDITION:

Table with 4 columns: Item, Yes, No, N/A. Rows include Chain-Of-Custody document(s), Sampler's name, Sample container label(s), Sample container(s) intact, Correct containers and volume, Proper preservation, VOA vial(s) free of headspace, Tedlar bag(s) free of condensation.

Initial: JB

COMMENTS:

Multiple horizontal lines for handwritten comments.