



FAX TRANSMISSION

DECON Environmental Services, Inc.
23490 Connecticut Street
Hayward, CA 94545
Phone: (510) 732-6444
Fax: (510) 782-8584

TO: SCOTT SEERY FAX: (510) 337-9335
COMPANY: ALA. CTY PHONE: (11) 567-6783
FROM: RAY MAIDEN DATE: 8-21 TIME: 1145
REFERENCE: _____

TOTAL NUMBER OF PAGES SENT (Including Cover Sheet): 2

Original to follow by:

____ U.S. Mail
____ Courier

____ Express Overnight Mail
____ No Hard Copy to Follow

COMMENTS:


Analyte	5' Soil	10' Soil	Water
TPH-O	ND	ND	ND
TPH-D	ND	ND	1400
TPH-G	ND	ND	ND
Benzene	ND	ND	ND
Toluene	ND	ND	ND
Ethylbenzene	ND	ND	ND
Xylenes	ND	ND	ND
MTBE	ND	ND	7
VOCs	--	--	ND

Analyte	5' Soil	10' Soil	Water
TPH-O	ND	ND	ND
TPH-D	ND	ND	ND
TPH-G	ND	ND	ND
Benzene	ND	ND	ND
Toluene	ND	ND	ND
Ethylbenzene	ND	ND	ND
Xylenes	ND	ND	ND
MTBE	ND	ND	ND
VOCs	--	--	ND

Analyte	6' Soil	10' Soil	Water
TPH-O	ND	ND	280
TPH-D	ND	ND	1400
TPH-G	ND	ND	53
Benzene	ND	ND	ND
Toluene	ND	ND	ND
Ethylbenzene	ND	ND	ND
Xylenes	ND	ND	ND
MTBE	ND	ND	31
VOCs	--	--	ND

Analyte	5' Soil	10' Soil	Water
TPH-O	ND	ND	ND
TPH-D	ND	ND	110**
TPH-G	ND	ND	ND
Benzene	ND	ND	ND
Toluene	0.006	0.006	ND
Ethylbenzene	ND	ND	ND
Xylenes	ND	ND	ND
MTBE	ND	ND	ND
VOCs	--	--	ND


Analyte	5' Soil	11' Soil	Water
TPH-O	ND	ND	ND
TPH-D	ND	ND	ND
TPH-G	ND	ND	<200*
Benzene	ND	ND	<2*
Toluene	ND	ND	<2*
Ethylbenzene	ND	ND	<2*
Xylenes	ND	ND	<2*
MTBE	0.17	0.34	9700
VOCs	--	--	ND



Legend

- B5 ⊕ Soil boring location
- * Method reporting limit was elevated due to high analyte concentrations
- ** Sample contains components in the diesel range, but the chromatogram does not match the diesel fingerprint
- ND Not detected at or above the method reporting limit
- Not analyzed

- TPH-O Total Petroleum Hydrocarbons as Oil
- TPH-D Total Petroleum Hydrocarbons as Diesel
- TPH-G Total Petroleum Hydrocarbons as Gasoline
- MTBE Methyl Tert-Butyl Ether
- VOCs Volatile Organic Compounds



<table border="1"> <tr> <th>No.</th> <th>Date</th> <th>Revised</th> <th>Approved</th> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> </tr> </table>	No.	Date	Revised	Approved					<p>Henshaw Associates, Inc. Environmental Engineering Services 11875 Dublin Blvd., Suite A-200 • Dublin, California 94568</p>	<table border="1"> <tr> <td>Date:</td> <td>07/27/98</td> </tr> <tr> <td>Designed:</td> <td>OS</td> </tr> <tr> <td>Drawn:</td> <td>OS</td> </tr> <tr> <td>Checked:</td> <td>DB</td> </tr> <tr> <td>DWG file:</td> <td>3307.98</td> </tr> </table>	Date:	07/27/98	Designed:	OS	Drawn:	OS	Checked:	DB	DWG file:	3307.98	<p>STORAGE AREA TEST RESULTS Oliver Property 18905 Hesperian Blvd. Hayward, California</p>	<table border="1"> <tr> <td>Figure</td> <td>5</td> </tr> <tr> <td>Project</td> <td>160.A.01</td> </tr> </table>	Figure	5	Project	160.A.01
No.	Date	Revised	Approved																							
Date:	07/27/98																									
Designed:	OS																									
Drawn:	OS																									
Checked:	DB																									
DWG file:	3307.98																									
Figure	5																									
Project	160.A.01																									