RECEIVED

1:27 pm, Apr 09, 2012

Alameda County Environmental Health

April 3, 2012

Ms. Donna Drogos Alameda County Environmental Health 1131 Harbor Parkway, Suite 250 Oakland, CA 94502-6577

Subject:

Letter Report - Offsite Findings

Shore Acres Gas

403 East 12th Street, Oakland, Alameda County, California

RO #0002931 ECG # GHA.19009

Dear Ms. Drogos:

Enclosed please find a copy of the April 3, 2012 Letter Report – Offsite Findings for the above referenced site prepared by our consultant Environmental Compliance Group, LLC.

I declare, under penalty and perjury, that the information and/or recommendations contained in this report are true and correct to the best of my knowledge.

Respectfully,

Rashid Ghafoor



270 Vintage Drive Turlock, CA 95382 P: 209.664.1035

F: 209.664.1040

April 3, 2012

Ms. Barbara Jakub Alameda County Environmental Health 1131 Harbor Parkway, Suite 250 Oakland, CA 94502-6577

Subject:

Letter Report – Offsite Findings

Shore Acres Gas

403 East 12th Street, Oakland, Alameda County, California

RO #0002931 ECG # GHA.19009

Dear Ms. Jakub:

In Environmental Compliance Group's (ECG) January 26, 2012 Report entitled *Off Site Investigation and Dual Phase Pilot Test Results with Fourth Quarter 2011 Groundwater Monitoring Report*, ECG stated in our conclusions section that it "appears that a second source is present near the intersection of Fourth Avenue and East Eleventh Street. In addition, the absence of MTBE in the second source area borings provides further evidence that contamination found in this area is not associated with the Shore Acres Gas site." Since the submittal of the above referenced report, ECG has found documentation that a petroleum contaminated soil source is located at the Downtown Educational Complex (DEC) located at 314 East 10th Street in Oakland California. The evidence for this offsite source is contained in a report prepared by Ninyo and Moore dated July 14, 2011 and entitled *Removal Action Complete Report*.

In Ninyo and Moore's report, they discuss in detail on pages 17 through 19 activities relating to removal of petroleum contaminated soil in the northwest section of the DEC facility. Figure 6 illustrates the pervasive presence of TPHg in soil in many areas of the site and shows the area that was excavated and over excavated to remove petroleum contaminated soil. Figure 7 shows the presence of benzene in soil gas samples collected in many areas of the site. The link to Ninyo and Moore's report is shown below:

http://www.envirostor.dtsc.ca.gov/regulators/deliverable_documents/2731961905/401501 008%20R%20-%20RACR%20-%20pt.1.pdf Based on the information in Ninyo and Moore report and the findings during the offsite investigation for the Shore Acres site, it appears the Shore Acres groundwater plume is defined. ECG recommends completing a Corrective Action Plan and upon Alameda County approval, beginning remediation at the site.

Respectfully,

Michael S. Sgourakis Principal Geologist

Mul S Syll

cc Rashid Ghafoor