


RECEIVED

1:50 pm, Apr 29, 2008

Alameda County
Environmental Health



Source: Figure modified from drawing provided by Delta Environmental Consultants, Inc.

GETTLER - RYAN, INC.
 6747 Sierra Court, Suite J
 Dublin, CA 94568 (925) 551-7555

GROUNDWATER ELEVATION MAP
 Chevron Service Station #9-1924
 4904 Southfront Road
 Livermore, California

STATION 261128
 4707 1st STREET
 LIVERMORE, CA

FIGURE 1

PROJECT NUMBER 386448
 REVIEWED BY
 FILE NAME: P:\Enviro\Chevron\9-1924\Q05-9-1924.dwg | Layout Tab: Plot4

DATE December 5, 2005

REVISED DATE

261128 MBL Detections at B-1d30.0, B-1(GW), B-4(GW), B-4d21.0, B-6(GW), B-6d19.0, B-2(GW), B-2d31.0, B-3d20.0, B-3(GW)