

ACTIVITY RECORD



RO #: 0002977
DATE: Thursday, June 19, 2008
TIME: 8:30 AM

<input type="checkbox"/>	Meeting	HAZ MAT SPECIALIST:	Paresh C. Khatri
<input checked="" type="checkbox"/>	Site Visit/Inspection	Work Location:	1131 Harbor Bay Pkwy, Alameda
<input type="checkbox"/>	Telephone Conversation	Conferee(s):	M. Goldstein
<input type="checkbox"/>	Document Review		N. Ceteras, SCOTT WILLIAMS
<input type="checkbox"/>	Peer Review	Phone #	TONY, McEUGLINT

SITE NAME & ADDRESS: FCI-Dublin, 5701 8th Street, Dublin

TOPIC: NEXT STEP FOR SITE ASSESSMENT.

SUMMARY:

MET AT THE SITE WITH MIKE GOLDSTEIN (SAFETY MANAGER) AND REMEDIATION CONTRACTORS NOAH, SCOTT & TONY.

I EXPLAINED THE WE NEED TO ASSESS SITE CONDITIONS BY DELINEATING THE VERTICAL & LATERAL EXTENT OF SOIL CONTAMINATION AND VERIFY WHETHER GW IS ~~IMPACTED~~ IMPACTED. TONY WILL BE PREPARING A WORK PLAN. I ALSO INFORMED THEM THAT THE SITE IS LOCATED WITHIN A DRINKING WATER BASIN.

WE TOURED THE LOCATION WHERE THE DIESEL SPILL OCCURRED AND SAW THE EXCAVATION & NOTED VISIBLE STAINING SOIL.