

SHATTUCK IMPORTS (T0600101219) - [MAP THIS SITE](#)

OPEN - SITE ASSESSMENT

6562 SHATTUCK AVE
OAKLAND , CA 94609
ALAMEDA COUNTY[ACTIVITIES REPORT](#)[PUBLIC WEBPAGE](#)[VIEW PRINTABLE CASE SUMMARY FOR THIS SITE](#)**CLEANUP OVERSIGHT AGENCIES**ALAMEDA COUNTY LOP (*LEAD*) - CASE #: 01-1324

SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-1324

THIS PROJECT WAS LAST MODIFIED BY **PARESH KHATRI** ON 4/22/2010 3:54:31 PM - [HISTORY](#)**ACTIVITIES REPORT** ACTIVITY TYPE FILTER: Show All Activities

* INDICATES A REVISED DUE DATE

[SCHEDULE NEW REGULATORY ACTION](#)[SCHEDULE NEW COMPLIANCE RESPONSE](#) / [SCHEDULE RECURRING](#)

ACTION TYPE	ACTION	ACTION DATE	RECEIVED / ISSUE DATE	ACTION DESCRIPTION
LEAK ACTION	Leak Discovery	6/2/1985		
LEAK ACTION	Leak Reported	6/2/1985		
LEAK ACTION	Leak Stopped	6/2/1985		

LOGGED IN AS TEENALEKHAN

[CONTACT GEOTRACKER HELP](#)

6562 SHATTUCK AVE
 OAKLAND , CA 94609
 ALAMEDA COUNTY
[VIEW PRINTABLE CASE SUMMARY FOR THIS SITE](#)

[ACTIVITIES REPORT](#)
[PUBLIC WEBPAGE](#)

CLEANUP OVERSIGHT AGENCIES
 ALAMEDA COUNTY LOP (*LEAD*) - CASE #: 01-1324
 SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-1324

THIS PROJECT WAS LAST MODIFIED BY *PARESH KHATRI* ON 4/22/2010 3:54:31 PM - [HISTORY](#)

CLOSURE REVIEW [CLOSURE REVIEW HISTORY](#)

THIS VERSION IS IN PROGRESS AS OF 4/22/2010

IS THIS CASE READY FOR CLOSURE? YES NO - [VIEW MAXIMUM CONCENTRATIONS REPORT](#)

IMPEDIMENTS TO CLOSURE

Site Assessment Incomplete

- Incomplete Conceptual Site Model (CSM)
- Pollutant Sources Have Not Been Adequately Identified or Evaluated

- Extent of Contamination Has Not Been Determined
- Potential Risks, Threats, And Other Environmental Concerns Have Not Been Adequately Identified And Assessed

- Sensitive Receptor Survey Has Not Been Completed
- Other

Inadequate Source Control

- Feasible Source Control Not Performed
- Remaining Source Poses Threat to Groundwater
- Other

Plume Instability

- Groundwater Contamination Plume Not Stable or Decreasing
- Significant Rebound In Concentrations After Remediation
- Verification Monitoring Not Complete
- Other

Groundwater Impacts

- Groundwater Impacted Above Background
- Groundwater Impacted Above Other Cleanup Goal
- Groundwater Will Not Meet Relevant WQOs Before the Beneficial Use of the Groundwater is Needed
- Other

Well Impacts

- Municipal Wells Impacted
- Municipal Wells Potentially Impacted
- Domestic Wells Impacted
- Domestic Wells Potentially Impacted
- Irrigation / Industrial Wells Impacted
- Irrigation / Industrial Wells Potentially Impacted
- De-Watering Well / Sump Impacted
- De-Watering Well / Sump Potentially Impacted
- Other

Unacceptable Risk

- Unacceptable Risks to Human Health from Soil
- Unacceptable Risks to Human Health from Vapor Intrusion
- Unacceptable Risk from Soil Contaminants Entering Surface Runoff
- Unacceptable Risk from Contaminated Groundwater Day Lighting to Surface Water
- Other

Land Use Impediments

- Proposed Change In Land Use (Need Additional RI and/or Cleanup)
- Risk Management Measures Need Agency Oversight (eg. Cap Maintenance)
- Other

Procedural Impediments

- Non-Responsive and / or Recalcitrant Responsible Party
- RP Says They Do Not Have Adequate Funds to Initiate or Continue Work at the Site
- Site Data And Reports Not Uploaded to Geotracker
- Monitoring Wells Not Yet Abandoned
- Landowner Objects to Case Closure
- Regional Water Board Objects to Closure
- Local Agency Objects to Case Closure
- Community Objects to Case Closure
- LOC Suspended
- Reimbursements Delayed
- Other

Other Impediments

BENEFITS OF ADDITIONAL WORK

- Fill-in RI Data Gaps
- Complete CSM and Our Understanding of Hydrogeologic Regime and Fate and Transport of Contaminants
- Verify Remedial Action Effectiveness
- Remove / Reduce Source Mass
- Protect Designated Beneficial Uses
- Restore Beneficial Uses
- Protect Existing Water Supply Wells
- Protect Human Health
- Protect Ecological Receptors
- Restore Blighted Property to Productive Use
- Other

SENSITIVE RECEPTORS LIKELY TO BE IMPACTED AND TIME FRAME FOR IMPACT

- Municipal Well
- Domestic Wells
- Groundwater
- Surface Water (Bay, Estuary, Stream, Lake)
- Storm drain (Runoff of contaminated soil)
- Indoor Air (Residential or Commercial)
- Irrigation / Industrial Well
- Other

NOTES / COMMENTS

[SPELL CHECK](#)

LOGGED IN AS TEENALEKHAN

[CONTACT GEOTRACKER HELP](#)

Facility / Site Address

[GEOTRACKER HOME](#) | [MANAGE PROJECTS](#) | [REPORTS](#) | [SEARCH](#) | [LOGOUT](#)SHATTUCK IMPORTS (T0600101219) - [MAP THIS SITE](#)[OPEN - SITE ASSESSMENT](#)6562 SHATTUCK AVE
OAKLAND , CA 94609
ALAMEDA COUNTY[ACTIVITIES REPORT](#)[PUBLIC WEBPAGE](#)[VIEW PRINTABLE CASE SUMMARY FOR THIS SITE](#)**CLEANUP OVERSIGHT AGENCIES**ALAMEDA COUNTY LOP (**LEAD**) - CASE #: 01-1324

SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-1324

THIS PROJECT WAS LAST MODIFIED BY **PARESH KHATRI** ON 4/22/2010 3:54:31 PM - [HISTORY](#)

FACILITY / SITE ADDRESS

 Save ChangesTHIS IS A "TEST PROJECT" (WILL BE EXCLUDED FROM PUBLIC SEARCH / REPORTS AND REGULATOR REPORTS)**PROJECT NAME**

THIS PROJECT IS A RESIDENCE

STREET # **STREET NAME / LOCATION** **BUILDING #****CITY** **STATE** **ZIP** **COUNTY**
Alameda**CROSS STREET NAME****FIELDS CALCULATED BASED ON LATITUDE / LONGITUDE**

GW BASIN NAME	WATERSHED NAME	COUNTY
Santa Clara Valley - East Bay Plain (2-9.04)	Bay Bridges - Berkeley (20330)	Alameda

[SPELL CHECK](#)

LOGGED IN AS TEENALEKHAN

[CONTACT GEOTRACKER HELP](#)

SHATTUCK IMPORTS (T0600101219) - [MAP THIS SITE](#)

OPEN - SITE ASSESSMENT

6562 SHATTUCK AVE
OAKLAND , CA 94609
ALAMEDA COUNTY[ACTIVITIES REPORT](#)[PUBLIC WEBPAGE](#)**CLEANUP OVERSIGHT AGENCIES**ALAMEDA COUNTY LOP (*LEAD*) - CASE #: 01-1324
SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-1324[VIEW PRINTABLE CASE SUMMARY FOR THIS SITE](#)THIS PROJECT WAS LAST MODIFIED BY *PARESH KHATRI* ON 4/22/2010 3:54:31 PM - [HISTORY](#)

PROJECT INFORMATION

[PROJECT STATUS HISTORY](#) Save Changes

SITE TYPE	STATUS	STATUS DATE
LUST Cleanup Site	Open - Site Assessment	

FUNDING FOR CLEANUP	FILE LOCATION	RP IDENTIFICATION	RP ID DATE

HUMAN HEALTH EXPOSURE - [INFO](#)**GROUNDWATER MIGRATION - [INFO](#)****FINAL REMEDY FOR CLEANUP**

CONTROLLED?	DATE	CONTROLLED?	DATE	SELECTED?	DATE	IMPLEMENTED?	DATE

STAFF NOTES (INTERNAL)**SITE HISTORY (PUBLIC)****CLEANUP OVERSIGHT AGENCIES**

CASE NUMBER	CLEANUP OVERSIGHT AGENCY	LEAD	LEAD DATE	END DATE
	ALAMEDA COUNTY LOP			
	SAN FRANCISCO BAY RWQCB (REGION 2)			

LATITUDE/LONGITUDE INFORMATION MUST BE IN THE GEOGRAPHIC NAD83 COORDINATE SYSTEM:

LATITUDE	LONGITUDE	BUFFER (IN FEET)	LAT / LONG SOURCE
			* Historical Geocode - Street Match

[CLICK HERE TO RE-POSITION THIS PROJECT ON THE MAP](#)[SPELL CHECK](#)

SHATTUCK IMPORTS (T0600101219) - [MAP THIS SITE](#)

OPEN - SITE ASSESSMENT

6562 SHATTUCK AVE
OAKLAND , CA 94609
ALAMEDA COUNTY

[ACTIVITIES REPORT](#)[PUBLIC WEBPAGE](#)[VIEW PRINTABLE CASE SUMMARY FOR THIS SITE](#)**CLEANUP OVERSIGHT AGENCIES**ALAMEDA COUNTY LOP (*LEAD*) - CASE #: 01-1324

SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-1324

THIS PROJECT WAS LAST MODIFIED BY **PARESH KHATRI** ON 4/22/2010 3:54:31 PM - [HISTORY](#)**PROJECT STATUS HISTORY**

PROJECT STATUS	STATUS DATE	DATE UPDATED
Open - Case Begin Date	6/2/1985	6/2/1985
Open - Site Assessment	6/2/1985	6/2/1985

LOGGED IN AS TEENALEKHAN

[CONTACT GEOTRACKER HELP](#)

Project Summary

[GEOTRACKER HOME](#) | [MANAGE PROJECTS](#) | [REPORTS](#) | [SEARCH](#) | [LOGOUT](#)
SHATTUCK IMPORTS (T0600101219) - [MAP THIS SITE](#)

OPEN - SITE ASSESSMENT

6562 SHATTUCK AVE
OAKLAND , CA 94609
ALAMEDA COUNTY

[ACTIVITIES REPORT](#)[PUBLIC WEBPAGE](#)[VIEW PRINTABLE CASE SUMMARY FOR THIS SITE](#)**CLEANUP OVERSIGHT AGENCIES**ALAMEDA COUNTY LOP (*LEAD*) - CASE #: 01-1324

SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-1324

THIS PROJECT WAS LAST MODIFIED BY **PARESH KHATRI** ON 4/22/2010 3:54:31 PM - [HISTORY](#)[PROJECT INFO](#)

SITE TYPE	STATUS	STATUS DATE
LUST CLEANUP SITE	OPEN - SITE ASSESSMENT	6/2/1985

[CONTACTS](#)

THERE ARE CURRENTLY NO CONTACTS ASSOCIATED WITH THIS PROJECT

LOGGED IN AS TEENALEKHAN

[CONTACT GEOTRACKER HELP](#)

SHATTUCK IMPORTS (T0600101219) - [MAP THIS SITE](#)

OPEN - SITE ASSESSMENT

6562 SHATTUCK AVE
OAKLAND , CA 94609
ALAMEDA COUNTY[ACTIVITIES REPORT](#)[PUBLIC WEBPAGE](#)**CLEANUP OVERSIGHT AGENCIES**ALAMEDA COUNTY LOP (*LEAD*) - CASE #: 01-1324

SAN FRANCISCO BAY RWQCB (REGION 2) - CASE #: 01-1324

[VIEW PRINTABLE CASE SUMMARY FOR THIS SITE](#)THIS PROJECT WAS LAST MODIFIED BY *PARESH KHATRI* ON 4/22/2010 3:54:31 PM - [HISTORY](#)

RISK INFORMATION

 Save ChangesRELEASE TYPECONTAMINANT(S) OF CONCERNINTERNAL PRIORITY

GASOLINE

(OPTIONAL)REDEVELOPMENT PLANNED - INFO

YES NO

CURRENT LAND USE

NONE SPECIFIED

BENEFICIAL USE

NONE SPECIFIED

MEDIA OF CONCERN

NONE SPECIFIED

VULNERABILITY BASISADDITIONAL RISK DESCRIPTION (IF NEEDED)# IMPACTED DRINKING WATER WELLSDRINKING WATER SUPPLY SHUT DOWN

YES NO

THERE ARE 0 DHS SUPPLY WELLS WITHIN 1/2 MILE OF THIS SITE
(INCLUDING SITE BUFFER)WELL IMPACT DESCRIPTIONREPORT DATERELEASE DESCRIPTIONSTOP DATESTOP METHODSTOP DESCRIPTIONDISCHARGE DATEDISCHARGE CAUSEDISCHARGE SOURCEDISCHARGE DESCRIPTION

STRUCTURAL FAILURE

TANK

DISCOVERED DATEHOW DISCOVEREDHOW DISCOVERED DESCRIPTION

TANK CLOSURE

QUANTITY (GALLONS)HAZMAT INCIDENT FILED WITH OES?LEAK CONFIRMED AS A VAPOR RELEASE?[SPELL CHECK](#)

GEOTRACKER

LAYERS

- Leaking Underground Tank (LUST) Cleanup Sites
- Other Cleanup Sites
- Land Disposal Sites
- Military Sites
- Permitted Underground Storage Tank (UST) Facilities
- Monitoring Wells
- DTSC Cleanup Sites
- DTSC Haz Waste Permit

CLEANUP STATUS FILTER

All Cleanup Statuses

MAP SIZE

640x480

OPTIONS

Site List - [EXPORT TO EXCEL](#)



Imagery ©2010 GeoEye, U.S. Geological Survey, DigitalGlobe, USDA Farm Service Agency, Map data ©2010 Google - [Terms of Use](#)

SITE LIST

SITE NAME	GLOBAL ID	CLEANUP STATUS	ADDRESS	CITY
<input checked="" type="checkbox"/> SHATTUCK IMPORTS	T0600101219	OPEN - SITE ASSESSMENT	6562 SHATTUCK AVE	OAKLAND

MAP AN ADDRESS: