

Photo Log

Facility #: R00003066

Name: Gas Station / East Bay Smog Center

Address: 6501 Shattuck Avenue, Oakland, CA



ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION

1131 Harbor Bay Parkway, Suite 250

Alameda, CA 94502-6577

(510) 567-6700

FAX (510) 337-9335



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: Northern Sidewall of Northern Excavation



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: Western Sidewall of Northern Excavation

Photo Log

Facility #: R00003066

Name: Gas Station / East Bay Smog Center

Address: 6501 Shattuck Avenue, Oakland, CA



ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION

1131 Harbor Bay Parkway, Suite 250

Alameda, CA 94502-6577

(510) 567-6700

FAX (510) 337-9335



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: Southern Excavation



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: South wall of Southern Excavation

Photo Log

Facility #: R00003066

Name: Gas Station / East Bay Smog Center

Address: 6501 Shattuck Avenue, Oakland, CA



ENVIRONMENTAL HEALTH SERVICES
ENVIRONMENTAL PROTECTION
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577
(510) 567-6700
FAX (510) 337-9335



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: Eastern Sidewall of Southern Excavation



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: Close-up of Northern excavation Sidewall

Photo Log

Facility #: R00003066

Name: Gas Station / East Bay Smog Center

Address: 6501 Shattuck Avenue, Oakland, CA



ENVIRONMENTAL HEALTH SERVICES
ENVIRONMENTAL PROTECTION
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577
(510) 567-6700
FAX (510) 337-9335



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: Hydrocarbon staining on Northern Sidewall of Northern Excavation



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: Northwestern corner of excavation.

Photo Log

Facility #: R00003066

Name: Gas Station / East Bay Smog Center

Address: 6501 Shattuck Avenue, Oakland, CA



ENVIRONMENTAL HEALTH SERVICES
ENVIRONMENTAL PROTECTION
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577
(510) 567-6700
FAX (510) 337-9335



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: Over-excitation of Southern pit



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: Standing GW in Southern Excavation Pit

Photo Log

Facility #: R00003066

Name: Gas Station / East Bay Smog Center

Address: 6501 Shattuck Avenue, Oakland, CA



ENVIRONMENTAL HEALTH SERVICES
ENVIRONMENTAL PROTECTION
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577
(510) 567-6700
FAX (510) 337-9335



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: Hydrocarbon stained soil from Southern Excavation



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: View of Site from Shattuck Avenue

Photo Log

Facility #: R00003066

Name: Gas Station / East Bay Smog Center

Address: 6501 Shattuck Avenue, Oakland, CA



ENVIRONMENTAL HEALTH SERVICES
ENVIRONMENTAL PROTECTION
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577
(510) 567-6700
FAX (510) 337-9335



Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: View of 6525 Shattuck Avenue, located north of 6501 Shattuck Avenue.

Photo Taken by: Paresh Khatri

Date: 10/13/2011

Description: