UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT			
EMER	ENCY HAS STATE OFFICE OF EMERGENCY SERVICES	FOR LOCAL AGENCY USE ONLY	ANNACHT EMPLOYEE AND THAT I HAVE
	S No REPORT BEEN FILED? LI YES XI NO RET DATE CASE #	REPORTED THIS INFORMATION TO LOCAL OFFICIALS THE HEALTHAND SAPETY CODE.	S PURSUANT TO SECTION 25180 / UF
	7/1/2001 203077	Children .	07/29/11
	NAME OF INDIVIDUAL FILING REPORT PHONE	SIGNED	
REPORTED BY		891-1395 May (C	Right -
	REPRESENTING  LOCAL AGENCY  REGIONAL BOARD	COMPANY OR AGENCY NAME	
	OWNER/OPERATOR ☐ OTHER		
	ADDRESS 1829 9 <sup>th</sup> Avenue	Oakland	CA 94606
	STREET	CITY CONTACT PERSON	STATE ZIP PHONE
RESPONSIBLE PARTY	Wright, Mary L. Heirs of Estate ☐ Unknow	3 - TY TY 7 1 1 .	(510) 891-1395
	ADDRESS		
ZESP P,	1829 9 <sup>th</sup> Avenue	Oakland	CA 94606 STATE ZIP
	STREET FACILITY NAME (IF APPLICABLE)	OPERATOR	PHONE
SITE LOCATION	Former F&M Auto Service Site		
	ADDRESS 1839 Foothill Boulevard	Oakland Alameda	94606
	STREET CROSS STREET	CITY COUNTY	ZiP
	19 <sup>th</sup> Avenue		
IMPLEMENTING AGENCIES	LOCAL AGENCY AGENCY NAME		PHONE
	Alameda County Local Oversight Program		(510) 567-6702
	REGIONAL BOARD		PHONE
			( )
SUBSTANCES	(1) NAME	QUANT	TTY LOST (GALLONS)
	Petroleum Hydrocarbons (Gasoline)		
BSTA	(2)		<b></b>
DS.			Unknown
Y/ABATEMENT	, —	Test Tank Removal	Nuisance Conditions Other
	4/6/2011 Invei	ntory Control Subsurface Monitoring METHOD USED TO STOP DISCHARGE (CHEC	K ALL THAT APPLY)
Y/AB	Remove Contents Close Tank		
OVER	UNKNOWN Repair Tank Change Procedure  HAS DISCHARGE BEEN STOPPED? Replace Tank Other		
DISCOVER	YES NO IF YES, DATE Repair Piping		
-	SOURCE OF DISCHARGE CAUSE(		•
SOURCE	☐ Tank Leak ☐ Piping Leak ☐ Unknown ☐ Other ☐ Ove	rfiil ⊠ Corrosion 🔲 Rupture/Failure 🔲 Unl	known Spill Other
	CHECK ONE ONLY		
CASE	☑ Undetermined ☐ Soil Only ☐ Groundwater ☐ Drinking Water – (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)		
CURRENT STATUS	CHECK ONE ONLY	Case Closed (Cleanup Completed or Unneces	esarv)
	☐ Leak Being Confirmed ☐ Pollution Characterization		
	☐ Remediation Plan ☐ Preliminary Site Assessment Workplan Submitted ☐	Post Cleanup Monitoring in Progress Cleanup Underway	
	Preliminary Site Assessment Underway		
REMEDIAL ACTION	CHECK APPROPRIATE ACTION(S)  ☐ Cap Site (CD) ☐ Excavate & Treat (ET)	Treatment At Hookup (HU)	☐ Other
	☐ Contamination Barrier (CB) ☐ No Action Required (NA) ☐ Vacuum Extract (VE) ☐ Remove Free Product (FP)	<ul><li>☐ Enhanced Bio Degradation (IT)</li><li>☐ Replace Supply (RS)</li></ul>	
₹`	Excavate & Dispose (ED) Pump & Treat Groundwater (GT) Vent Soil (VS)		
Mary K. Wright inherited the property from the estate of Frank Wright and Mary L. Wright			
MENI	COMMENTS		
COM			5
1			