Facility #: SR0019828

Name: GSA

Address: 16335 E 14TH ST, SAN LORENZO



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL FIZALTT SERVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335




Photo Taken by: Steven Plunkett Insp. Rtp #: 11-UNKNOWN FORMER UST Description:

12/1/2011 Date:




Photo #2

	y: Steven Plunkett	Insp. Rtp #: 11-	Date:	12/1/2011
Description:	UNKNOWN FORMER UST			

Facility #: SR0019828

Name: GSA

Address: 16335 E 14TH ST, SAN LORENZO



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335




Photo #3

Photo Taken by: Steven Plunkett Insp. Rtp #: 12/1/2011 11-Date: Description: REMOVAL OF UNKNOWN UST



Photo #4

Photo Taken by: Steven Plunkett	Insp. Rtp #: I1-	Date: 12/1/2011
Description: EXCAVATION OF IMPACTED SOIL		

Facility #: SR0019828

Name: GSA

Address: 16335 E 14TH ST, SAN LORENZO



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



Photo Taken by: Steven Plunkett Insp. Rtp #: I1- Date: 12/1/2011

Description: REMOVAL OF UNKNOW MATERIAL FROM UST 1




Photo Taken by: Steven Plunkett Insp. Rtp #: 11- Date: 12/1/2011
Description: UST 1 WITH MATERIAL REMOVED

Facility #: SR0019828

Name: GSA

Address: 16335 E 14TH ST, SAN LORENZO



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335




Photo #7

Photo Taken by: Steven Plunkett Insp. Rtp #: I1- Date: 12/1/2011

Description: STOCKPILED SOIL FOR DISPOSAL UST 1




Photo Taken by: Steven Plunkett	Insp. Rtp #: 11-	Date: 12/1/2011
Description: UNKNOWN MATERIAL IN UST 1		

Facility #: SR0019828

Name: GSA

Address: 16335 E 14TH ST, SAN LORENZO



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335




Photo Taken by: Steven Plunkett Insp. Rtp #: 11- Date: 12/1/2011

Description: OVEREXCAVATION OF IMPACTED SOIL UST 1




Photo Taken by: Steven Plunkett Insp. Rtp #: 11- Date: 12/1/2011

Description: REMOVAL OF MATERIAL FROM UST 2

Facility #: SR0019828

Name: GSA

Address: 16335 E 14TH ST, SAN LORENZO



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



Photo #11

Photo Taken by: Steven Plunkett Insp. Rtp #: 11- Date: 12/1/2011

Description: STOCKPILE OF UNKNOWN MATERIAL FROM UST 2




Photo #12

Photo Taken by: Steven Plunkett
Description: REMOVAL OF UST 2

Insp. Rtp #:

11-

Date:

12/1/2011

Facility #: SR0019828

Name: GSA

Address: 16335 E 14TH ST, SAN LORENZO



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



Photo #13

Photo Taken by: Steven Plunkett Insp. Rtp #: I1- Date: 12/1/2011

Description: VCP PIPE LEADING INTO UST 2




Photo #14

Photo Taken by:	Steven Plunkett	Insp. Rtp #:	1-	Date: 12/1/2011
Description:	REMOVAL OF VCP FROM UST 2 AREA			

Facility #: SR0019828

Name: GSA

Address: 16335 E 14TH ST, SAN LORENZO



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



Photo Taken by: Steven Plunkett Insp. Rtp #: I1- Date: 12/1/2011

Description: OVEREXCAVATION OF UST 1




Photo #16

Photo Taken by: Steven Plunkett Insp. Rtp #: 11- Date: 12/1/2011

Description: OVEREXCAVATION OF UST 1 (NOTE SOIL STAINING)


Facility #: SR0019828

Name: GSA

Address: 16335 E 14TH ST, SAN LORENZO



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335



Description:	SAMPLING IMPACTED SOIL FROM UST 1
<u></u>	

- Secretarian de la company de	
Average and a second	

Photo Taken by:	Insp. Rtp #:	11-	Date:
Description:			