

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK)/ CONTAMINATION SITE REPORT

EMERGENCY <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED? <input type="checkbox"/> Yes <input type="checkbox"/> No		FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.	
REPORT DATE 4/14/10		CASE #		 DATE: 4/18/10	
REPORTED BY	NAME OF INDIVIDUAL FILING REPORT Annette Chen		PHONE (415) 512-1555		SIGNATURE
	REPRESENTING <input type="checkbox"/> LOCAL AGENCY <input checked="" type="checkbox"/> OWNER/OPERATOR		REGIONAL BOARD <input checked="" type="checkbox"/> OTHER... contractor		COMPANY OR AGENCY NAME Golden Gate Tank Removal, Inc.
	ADDRESS 3730 Mission Street		CITY San Francisco		STATE CA
RESPONSIBLE PARTY	NAME Spencer & Roberta Kaitz		<input type="checkbox"/> Unknown		PHONE 510-681-6976
	ADDRESS 40 Crocker Avenue		CITY Piedmont		STATE CA
SITE LOCATION	FACILITY NAME (IF APPLICABLE)		OPERATOR		PHONE
	ADDRESS 40 Crocker Avenue		CITY Piedmont		STATE Alameda
	CROSS STREET Wildwood Ave.		CITY Alameda		ZIP 94611
IMPLEMENTING AGENCIES	LOCAL AGENCY Alameda County Department of Environmental Health		AGENCY NAME -Robert Weston		PHONE (510)567-6781
	REGIONAL BOARD				PHONE
SUBSTANCES INVOLVED	(1) Diesel		NAME		QUANTITY LOST (GALLONS) <input checked="" type="checkbox"/> Unknown
	(2)				<input type="checkbox"/> Unknown
DISCOVERY/STATEMENT	DATE DISCOVERED 4/13/10		HOW DISCOVERED <input type="checkbox"/> Tank Test <input checked="" type="checkbox"/> Tank Removal <input type="checkbox"/> Nuisance Conditions <input type="checkbox"/> Inventory Control <input type="checkbox"/> Subsurface Monitoring <input type="checkbox"/> Other...		
	DATE DISCHARGE BEGAN		<input checked="" type="checkbox"/> Unknown		METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) <input checked="" type="checkbox"/> Remove Contents <input checked="" type="checkbox"/> Close Tank & Remove <input type="checkbox"/> Repair Tank <input type="checkbox"/> Change Procedure <input type="checkbox"/> Replace Tank <input type="checkbox"/> Other... <input type="checkbox"/> Repair Piping
	HAS DISCHARGE BEEN STOPPED? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		IF YES, DATE 4/13/10		
SOURCE/CAUSE	SOURCE OF DISCHARGE <input type="checkbox"/> Tank Leak <input type="checkbox"/> Piping Leak <input checked="" type="checkbox"/> Unknown <input type="checkbox"/> Other...		CAUSE(S) <input type="checkbox"/> Overfill <input type="checkbox"/> Corrosion <input type="checkbox"/> Rupture/Failure <input checked="" type="checkbox"/> Unknown <input type="checkbox"/> Spill <input type="checkbox"/> Other...		
	CASE TYPE <input checked="" type="checkbox"/> Undetermined <input type="checkbox"/> Soil Only <input type="checkbox"/> Groundwater <input type="checkbox"/> Drinking Water - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)				
CURRENT STATUS	CHECK ONE ONLY <input checked="" type="checkbox"/> No Action Taken		<input type="checkbox"/> Case Closed (Cleanup Completed or Unnecessary)		
	<input type="checkbox"/> Leak Being Confirmed		<input type="checkbox"/> Pollution Characterization		
REMEDIAL ACTION	<input type="checkbox"/> Remediation Plan		<input type="checkbox"/> Post Cleanup Monitoring in Progress		
	<input type="checkbox"/> Preliminary Site Assessment Workplan Submitted		<input type="checkbox"/> Cleanup Underway		
	<input type="checkbox"/> Preliminary Site Assessment Underway				
	CHECK APPROPRIATE ACTION(S) <input type="checkbox"/> Cap Site (CD) <input type="checkbox"/> Excavate & Treat (FT) <input type="checkbox"/> Treatment at Hookup (HU) <input type="checkbox"/> Other... <input type="checkbox"/> Contamination Barrier (CB) <input type="checkbox"/> No Action Required (NA) <input type="checkbox"/> Enhanced Bio Degradation (IT) <input type="checkbox"/> Vacuum Extract (VE) <input type="checkbox"/> Remove Free Product (FP) <input type="checkbox"/> Replace Supply (RS) <input type="checkbox"/> Excavate & Dispose (ED) <input type="checkbox"/> Pump & Treat Groundwater (GT) <input type="checkbox"/> Vent Soil (VS)				
COMMENTS	Holes found in the tank.				

Alameda County
 APR 14 2010
 Environmental Health