## Alameda County CUPA Program

# Contaminated Site Case Transfer Form

#### Referral To:

Date	September 6, 2012
Agency	Alameda County Environmental Health, 1131 Harbor Bay Parkway, Alameda, CA 94502
Attention	Donna L. Drogos, LOP/SLIC Program Manager

### Site Information:

Site Responsible Party(s)	CHRISTOPHER GIESE
Site Name residence	
Site Address	4845 PROCTOR RD., CASTRO VALLEY CA 94546
Site Phone	(912) 313-4366 Texas phone number
Site Contact	CHRISTOPHER GIESE
Site DBA	

#### Site Conditions

Site Conditions:								
Date of incident April 19, 2012 UST Removal	Yes	$\boxtimes$	No					
Contents (circle): gasoline diese waste oil heating oil solvents kerosene stoddard solvent other (specify)	Yes		No					
Observations of system (holes, leaks)? Tank contains numerous holes	Yes	$\boxtimes$	No					
Observed contamination (odor) odor of old gasoline	Yes	$\boxtimes$	No					
Detectable concentrations of soil and/or groundwater contamination?  ☐ Highest Concentration Detected in Soil under dispenser—3.2 ppm TPH Contaminant (specify) ☐ Highest Concentration Detected in Water in pit − 23.4 ppb xylene	Yes		No					
Unauthorized Release Form filed?	Yes	$\boxtimes$	No					
Future intended use if known? RESIDENTIAL	Yes		No					
NON-UST		1	e de la segui					
Former industrial use?	Yes		No					
Detectable concentrations of soil and/or groundwater contamination?  O Highest Concentration Detected in Soil Contaminant (specify) Concentration ppm  O Highest Concentration Detected in Water Contaminant (specify) Concentration ppb	Yes		No					
Future intended use if known? Specifyunknown	Yes		No					
If available, attach pertinent reports: photos previously su	bmitted							
Transferred as: LOP SLIC   Level of Update requested: distribution list all meetings all site visits closur  Transfer requested by Inspector: Robert Weston Date:	9-6-2012			9				
Transfer accepted by (ACEH): Date: 09/25/12								