UNDERGROUND STORAGE TANK UNAUTH **MERGENCY** HAS STATE OFFICE OF EMERGENCY S REPORT BEEN FILED? Yes ☑ Yes ☑ Yes ☑	SERVICES	FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DE REPORTED THIS INFORMATION TO THE HEALTH AND SAFETY CODE	SIGNATED GOVERNMENT EM	PLOYEE AND THAT I HAVE	
4/20/12 CASE #		SIGNED	ig 1	2/10/12 DATE	
NAME OF INDIVIDUAL FILING REPORT Annette Chen	(415	5) 512-1555 SIGNATURE		Annette Chen District square by Office Chen, Old District Chen, Old Di	
REPRESENTING LOCAL AGENCY REGIONAL BOARD OWNER/OPERATOR OTHER Contractor		Golden Gate Tank Removal, Inc.			
1455 Yosemite Avenue		San Francisco	TX	94124 ZIP	
Christopher Giese ADDRESS 4301 W William Cannon Dr #B150 Ste 240				912-313-4366	
4301 W William Cannon Dr., #B150 Ste 240		Austin	TX	78749	
FACILITY NAME (IF APPLICABLE)		OPERATOR		PHONE	
4043 FTOCIOT ROAU STREET CITY				AMEDA 94546	
ADDRESS 4845 Proctor Road CROSS STREET Dorson Ln					
ALAMEDA COUNTY ENVIRONMENTAL HEALTH -ROBERT WESTON				(510)567-6781	
ALAMEDA COUNTY ENVIRONMENTAL HEALTH -ROBERT WESTON REGIONAL BOARD				PHONE	
Gasoline NAME				QUANTITY LOST (GALLONS) M Unknown	
Gasoline	T THE			☐ Unknown	
DATE DISCOVERED HOW DISCOVERED Tank Test Subsurface Monitoring Other				litions	
DATE DISCOVERED 4/19/12 DATE DISCOVERED HOW DISCOVERED HOW DISCOVERED A/19/12 DATE DISCHARGE BEGAN	□ Unknown □ Remove Contents □ Close Tank & Removed				
HAS DISCHARGE BEEN STOPPED? Yes No 4/19/12 IF YES, DATE	Repair Tank				
SOURCE OF DISCHARGE Tank Leak Piping Leak Unknown Other CHECK ONE ONLY Undetermined Soil Only Groundwater Drinkin	ng Water - (CHECK ONLY IF WATER WI	ELLS HAVE ACTUALLY	BEEN AFFECTED)	
CHECK ONE ONLY No Action Taken Leak Being Confirmed	ase Closed (Cle ollution Characte ost Cleanup Mo	anup Completed or Unnecess erization nitoring in Progress			
CHECK APPROPRIATE ACTION(S) Cap Site (CD) Contamination Barrier (CB) Vacuum Extract (VE) Excavate & Treat (ET) No Action Required (NA) Remove Free Product (F) Excavate & Dispose (ED) Pump & Treat Groundwa)	eatment at Hookup (HU) hanced Bio Degradation (IT) eplace Supply (RS) ent Soil (VS)	Other		
Holes found in the tank.					