

Detterman, Mark, Env. Health

From: Tougeron, Christopher, Env. Health
Sent: Tuesday, September 18, 2012 1:31 PM
To: 'Peter Cusack'
Cc: Detterman, Mark, Env. Health
Subject: RE: UST Results
Attachments: unauthorized release form instructions.pdf; Unauthorized Release From 2006.pdf; Unauthorized Release Form 2006.doc

Mr. Cusack,

Thank you for submitting the test results. Please complete the attached URF document and submit to ACDEH.

Once I receive all the repots/documents I will transfer the case to the ACDEH LOP division, they will assign a case worker to provide you with cleanup/remediation oversight. Currently Mark Detterman will be your point of contact for any future work. Mark's contact information: 510-567-6876 mark.detterman@acgov.org

Please contact me if you have any questions

Thank you

Sincerely,

Chris Tougeron
Hazardous Materials Specialist
Alameda County Health Agency
1131 Harbor Bay Parkway
Alameda, CA 94502
Ph: 510-567-6804
Fax: 510-337-9335
Email: christopher.tougeron@acgov.org
www.acgov.org/aceh

From: Peter Cusack [<mailto:pcusack@Langan.com>]
Sent: Tuesday, September 18, 2012 9:19 AM
To: Tougeron, Christopher, Env. Health; mark.detterman@acgov.com
Subject: FW: UST Results

Hello Chris and Mark,

Below is a summary of the analytical results of results from the tank pull. Diesel and motor oil were detected in most of the samples and I also provided the chromium and lead results. No VOCs, SVOCs or gasoline were detected above their reporting limits.

Sample ID	Diesel	Motor Oil	Chromium	Lead
Tank 1 – E	200 mg/kg	300 mg/kg	58 mg/kg	ND
Comments				
Beneath UST East End				
Tank 1- W	34 mg/k	67 mg/kg	72 mg/kg	9.4 mg/kg
Comments				
Beneath UST West End				
Tank 1- NW	2.7 mg/kg	22 mg/kg	64 mg/kg	44 mg/kg
Comments				
North Sidewall				

Tank 1- SW	ND	ND	76 mg/kg	10 mg/kg
South Sidewall				
Tank 1- EW	8.3 mg/kg	36 mg/kg	73 mg/kg	19
mg/kg	East Sidewall			
Tank 1- WW	ND	ND	90 mg/kg	10 mg/kg
West Sidewall				
SP 1-4	18 mg/kg	64 mg/kg	53 mg/kg	74 mg/kg
Stockpile				

Could you give an initial opinion on any additional work that would be required. We will prepare the require Tank Removal report and submit once we received all the required documentation.

Thanks for your assistance.

Thanks
Peter

**Peter J. Cusack, REA
Associate**

Treadwell & Rollo | A Langan Company
Direct: 415.955.5244

Treadwell & Rollo | A Langan Company

Phone: 415.955.5200 Fax: 415.955.5201
555 Montgomery Street, Suite 1300
San Francisco, California 94111
www.treadwellrollo.com

CALIFORNIA NEW JERSEY NEW YORK PENNSYLVANIA CONNECTICUT FLORIDA VIRGINIA
ABU DHABI DUBAI ATHENS DOHA ISTANBUL

Langan's goal is to be SAFE! - (Stay Accident-Free Every day!)

Please consider the environment before printing this e-mail

This electronic transmission may contain confidential, proprietary or privileged information. No confidentiality or privilege is intended to be waived or lost by erroneous transmission of this message. If you receive this message in error, please notify the sender immediately by return email and delete this message from your system. Disclosure, use, distribution or copying of this message, any attachments thereto or their contents is strictly prohibited.