



---

1172 Kansas Avenue, Suite A  
Modesto, CA 95351  
209.522.4119 - PH  
209.522.4227 - FAX  
groundzeroanalysis.com

October 2, 2014

Mr. Jerry Wickham  
Alameda County Health Care Services Agency,  
Environmental Health Services  
1131 Harbor Bay Parkway, Suite 250  
Alameda, CA 94502-6577

Subject:       **Results of Onsite Well Search**  
                  The Green, 5411 Martinelli Way, Dublin, CA  
                  SLIC Case No. RO0003131

Dear Mr. Wickham:

We are writing to provide you with the results of our investigation into the status of suspected wells on the subject property. As you discovered, EDR reports included with various Phase I Site Assessment Reports for the property indicated that there may have been as many as three wells onsite. These were identified in the most recent EDR report as USGS monitoring wells with the following designations:


<u>EDR Map ID</u>	<u>USGS Well ID</u>	<u>DWR Well ID</u>
1	374209121532501	3S/1E 5F2
2	374210121533001	3S/1E 6G5
3	374207121531501	3S/1E 5F1

We contacted USGS who informed us that the wells in question were monitored by USGS but not installed or owned by USGS. We contacted the Zone 7 Water Agency, identified as the owner of Wells No. 1 and 3, and who provided us with documentation that they had been destroyed in 1990. We also contacted DWR who provided us with Drillers Reports/Well Completion reports for the property and surrounding area. These reports verified the destruction of Wells No. 1 and No. 3. The DWR report for Well No. 2 verified that it is located in Section 6, not Section 5, and that the USGS latitude/longitude based designation for the well is incorrect.

In addition, a suspected well was identified by ENGEO in their August 2013 Phase I ESA report. A field check on October 1 determined that this feature is not a well but is a water valve.

We conclude that there are no existing wells on the property. We can provide you with the DWR reports if you would like them. Please contact us if you need any additional information.

Respectfully,  
Ground Zero Analysis



Gregory P. Stahl, PG 5023  
CA Certified Hydrogeologist No. 264

cc: Mr. David Clock, Lennar Commercial