UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK)/ CONTAMINATION SITE REPORT								
1 _	* REPORT BEEN	FICE OF EMERGENCY SERVICE	FOR LOCAL AGENCY USE DINLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE					
☐ Yes ☐ No ☐ Yes ☐ No				REPORTED THIS INFORMATION TO LOCAL OFF 11410 DEPOSITION TO SECTION 25180.7 OF				
	719/14 CASE	E#	THE HET APP AND SAFETY CODE.					
- 1 1				SIGNED		en er gal retagli Heliginere de solo	DATE	
REPORTED BY	l		PHONE	512-1555	SIGNATURE			
	REPRESENTING			) 512-1555 Annette Chen COMPANY OR AGENCY NAME				
	☐ LOCAL AGENCY ☐ REGIONAL BOARD ☐ OWNER/OPERATOR ☑ OTHER contractor			Golden Gate Tank Removal, Inc.				
	1455 Yosemite Avenue			San Francisco	CA s	STATE ZIP		
RESPONSIBLE	1607 2nd Ave. LLC					510-928-1026		
	ADDRESS 64096 Piedmont Ave., #150			Oakland	CA	94611 TATE ZIP		
	FACILITY NAME (IF APPLICABLE)			OPERATOR		PHONE	24	
SITE LOCATION		된						
	ADDRESS 1607 2nd Ave.			Oakland	Alam		94606	
	CROSS STREET CITY COUNTY ZF							
	E 16th Street							
IMPLEMENTING AGENCIES	LOCAL AGENCY A	killern (510) 238-7253			7052			
	City of Oakland Fire Prevention Bureau Sheryl Skillern					<u> </u>		
	REGIONAL BOARD PHONE							
SUBSTANCES	NAME . QUANTITY LOST (GALLONS)							
	Heating Oil   Unknown							
	□ Unknown							
DISCOVERY/ABATEMENT	DATE DISCOVERED HOW DISCOVERED Tank Test			☑ Tank Removal ☐ Nuisance Conditions				
	DATE DISCHARGE BEGAN . ET Unknown			METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)  ☑ Remove Contents ☑ Close Tank & Removed				
	HAS DISCHARGE BEEN STOPPED?			☐ Repair Tank ☐ Change Procedure ☐ Replace Tank ☐ Other ☐ Repair Piping				
	Yes □ No 11/18/14     IF YES, DATE							
SOURCE/ CAUSE	SOURCE OF DISCHARGE							
Sol	☐ Tank Leak ☐ Piping Leak ☒ Unknown ☐ Other ☐ Overfill ☐ Corrosion ☐ Rupture/Failure ☒ Unknown ☐ Spill ☐ Other							
CASE								
CURRENT	CHECK ONE ONLY							
	<ul> <li>☑ No Action Taken</li> <li>☐ Case Closed (Cleanup Completed or Unnecessary)</li> <li>☐ Leak Being Confirmed</li> <li>☐ Pollution Characterization</li> </ul>							
	☐ Remediation Plan ☐ Post Cleanup Monitoring in Progress ☐ Preliminary Site Assessment Workplan Submitted ☐ Cleanup Underway							
	□ Preliminary Site Assessment Underway							
REMER	CHECK APPROPRIATE ACTION(S)							
	☐ Cap Site (CD) ☐ Excavate & Treat (ET) ☐ Treatment at Hookup (HU) ☐ Other ☐ Contamination Barrier (CB) ☐ No Action Required (NA) ☐ Enhanced Bio Degradation (IT)							
	□ Vacuum Extract (VE) □ Remove Free Product (FP) □ Replace Supply (RS) □ Excavate & Dispose (ED) □ Pump & Treat Groundwater (GT) □ Vent Soil (VS)							
COMMENTS	Holes found in the tank.							
ō								